



Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: ARCH/ASS/GHT/013

SECTION I : IDENTIFICATION

1. Name ()

Present

Tank of Negheriting Siva doul

Past

Other Name (if any)

2. Location ()

Address

LONGITUDE E94°00'146' LATITUDE N26°44'003'

State

Assam.

Negheriting, Dergam

Village (village code)

Post Negheriting

District

PIN

Golaghat

Approach

Take right turn from Negheriting
Tinali while moving from Sonbat
towards west through NH37.

3. Property Type ()

Buildings

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

Engineering structure

- Bridge
- Tunnel
- Other engineering

Religious structures

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

Open space and related structures

- Public square
- Park or garden
- Graveyard
- Baolis, Well

Other Structures

- Wall
- Gateway
- Pillar
- Others (specify)

structure

Tank
 Cave

4. Property Use ()

ABANDONED / IN USE

Present

Tank

Past

Tank

5. Age (Source) ()

PERIOD ()

YEARS ()

Precise date of

Construction

Completion

Subsequent changes

Destruction / Demolition

During King Rajeswar Singh (1751-1769 AD).

6. Ownership / Level of Protection ()

SINGLE / MULTIPLE

Public

Archaeological Survey of India / State Archaeology Department /

Any Other (Please specify) Local people.

Private

Any other (Please specify)

Name

Address

Phone

7. Association ()

• WITH EVENTS

In History

In Rituals

In Building Construction

Any other (specify) With Negheriting Siva dowl rituals in the past

• WITH PERSONS

Patron King Rajeswar Singh

Architect / Engineer

Any other (specify)

8. Statement of Significance (□ □ □ □ □ □ □ □ □ □ □ □)

- Architectural
- Archaeological
- Historical
- Religious
- Any other (specify) _____

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

● Context

* Drawings (Attach extra sheet if necessary)

Urban / Rural Setting
Surroundings

Stand in Isolation
Integral part of a Landscape / Street / Complex

● Quantification

Area Dimension (L x B x H)

5 Bighas or present.
_____ (m / cm / feet / inch)

Number of Blocks

One.

Number of Storeys

● Spatial Organization

Orientation

Plan

Almost Rectangular

Allocation of Spaces

ARCHITECTURAL STYLE

● Ornamentation

Exteriors

NA

Interiors

NA

Movable Collections

NA

* Any Other (specify)

10. Construction Technology

Structural System

Jack digging involves elaborate technique during stone period.

Building Techniques

Material of Construction

11. Condition Assessment

In General

Good / Fair

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

In Brief (Attach extra sheet if necessary)

The engrossment problem and vegetation are the main threats in front of this historic tank

12. Threats to the Property

- Natural
- Negligence
- Vandalism
- Urban Pressures