



Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: ARCH/ASS/KBA/001

SECTION I: IDENTIFICATION

1. Name ()

Present

Bura Gotain than

Past

Other Name (if any)

2. Location ()

Address

LONGITUDE E 93°02'68 LATITUDE N 26°13'725Dokmoka

Village (village code)

Post

District

Karbianglong

State

Assam

PIN

782441

Approach

About 16 km from Howrahpat;
North west to Dokmoka.

3. Property Type ()

Buildings

- Palace
 Fort
 Citadel
 Govt. building
 Railway station
 Defence building
 Industrial building
 Other public buildings
 Residential building

Engineering structure

- Bridge
 Tunnel
 Other engineering

Religious structures

- Temple
 Mosque
 Minar
 Church
 Monastery
 Stupa
 Tomb, Mausoleum

Open space and related structures

- Public square
 Park or garden
 Graveyard
 Baolis, Well

Other Structures

- Wall
 Gateway
 Pillar
 Others (specify)

structure

- Tank
 Cave

4. Property Use ()

ABANDONED / IN USE

Present

Temple remains

Past

Temple

5. Age (Source) ()

PERIOD ()

YEARS ()

Precise date of

Construction

Completion

Subsequent changes

Destruction / Demolition

Not known.

6. Ownership / Level of Protection ()

SINGLE / MULTIPLE

Public

Archaeological Survey of India / State Archaeology Department /
Any Other (Please specify)

Private

Any other (Please specify)

Name

Address

Phone

7. Association ()

• WITH EVENTS

In History

In Rituals

In Building Construction

Any other (specify)

• WITH PERSONS

Patron

Architect / Engineer

Any other (specify)

8. Statement of Significance ()

- Architectural
- Archaeological
- Historical
- Religious
- Any other (specify) _____

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

• Context

* Drawings (Attach extra sheet if necessary)

Urban / Rural Setting
Surroundings

Stand in Isolation ✓
Integral part of a Landscape / Street / Complex

• Quantification

Area Dimension (L x B x H)

Could not be found out.
(m / cm / feet / inch)

Number of Blocks
Number of Storeys

Not known

• Spatial Organization

Orientation

Plan

Allocation of Spaces

Not known.

ARCHITECTURAL STYLE

• Ornamentation

Exteriors

Interiors

Movable Collections

Siva image standing with a trishul (known as burchai or Burchagohain), door frame parts, Kalasha, amalaka, some mythical figure in stone are lying on the site.

* Any Other (specify)

10. Construction Technology

Structural System

Building Techniques

Not known - Need Study

Masonry.

Material of Construction Stone.

11. Condition Assessment

In General

Good / Fair

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

In Brief (Attach extra sheet if necessary)

The historical facts should be studied systema-
-tically and it needs preservation of the
existing remains first.

12. Threats to the Property

- Natural
- Negligence
- Vandalism
- Urban Pressures