



Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: ARCH/ASS/KBA/005

SECTION I: IDENTIFICATION

1. Name ()

Present

Sarthi Rangphor Village.

Past

Other Name (if any)

2. Location ()

Address

LONGITUDE E93°07'613" LATITUDE N26°09'543"

Phulani

Village (village code) Sarthi RangphorPost Phulani District Karbianglong

State

Assam

Approach

1 km west from NH36 after crossing a distance of 2 km from Phulani bazar.

3. Property Type ()

Buildings

- Palace
 Fort
 Citadel
 Govt. building
 Railway station
 Defence building
 Industrial building
 Other public buildings
 Residential building

Engineering structure

- Bridge
 Tunnel
 Other engineering

Religious structures

- Temple
 Mosque
 Minar
 Church
 Monastery
 Stupa
 Tomb, Mausoleum

Open space and related structures

- Public square
 Park or garden
 Graveyard
 Baolis, Well

Other Structures

- Wall
 Gateway
 Pillar
 Others (specify)

structure

- Tank
 Cave

4. Property Use ()

ABANDONED / IN USE

Present

Remains of a temple

Past

Temple.

5. Age (Source) ()

PERIOD ()

YEARS ()

Precise date of
Construction
Completion
Subsequent changes
Destruction / Demolition

Not known - Need study for conclusive view.

6. Ownership / Level of Protection ()

SINGLE / MULTIPLE

Public Archaeological Survey of India / State Archaeology Department /
Any Other (Please specify)

Private

Any other (Please specify)

Name

Address

Phone

7. Association ()

• WITH EVENTS

- In History
In Rituals
In Building Construction
Any other (specify)

• WITH PERSONS

- Patron
Architect / Engineer
Any other (specify)

8. Statement of Significance ()

- Architectural
- Archaeological
- Historical
- Religious
- Any other (specify) _____

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

• Context

* Drawings (Attach extra sheet if necessary)

Urban / Rural Setting
Surroundings

Stand in Isolation
Integral part of a Landscape / Street Complex

• Quantification

Area Dimension (L x B x H)

_____ (m / cm / feet / inch)

Number of Blocks

Number of Storeys

• Spatial Organization

Orientation

Not known.

Plan

Not known

Allocation of Spaces

ARCHITECTURAL STYLE

• Ornamentation

Exteriors

Interiors

Movable Collections

The structural remains tend to prove a huge temple of stone and brick works. Broken image of Vishnu, parts of door frame with carvings, stone block and remnants of boundary wall are noticed on the site. Two tanks are also present here.

* Any Other (specify)

Excavation was started by state archaeology department but it is not completed yet.

10. Construction Technology

Structural System

Could not be inferred

Building Techniques

Masonry and brick.

Material of Construction Stone, brick etc.

11. Condition Assessment

In General

Good / Fair

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

In Brief (Attach extra sheet if necessary)

12. Threats to the Property

- Natural
- Negligence
- Vandalism
- Urban Pressures