



Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: ARCH/ASS/KRP/008

SECTION I : IDENTIFICATION

1. Name ()

Present

North Brook Gate

Past

Other Name (if any)

Gateway of Guwahati

2. Location ()

Address

LONGITUDE E91°44'433' LATITUDE N26°11'224'

Sukriowarpar, Panbagan, Guwahati
Village (village code)

Post _____ District Kamrup
PIN _____

State

Assam

Approach

3. Property Type ()

Buildings

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

Engineering structure

- Bridge
- Tunnel
- Other engineering

Religious structures

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

Open space and related structures

- Public square
- Park or garden
- Graveyard
- Baolis, Well

Other Structures

- Wall
- Gateway
- Pillar
- Others (specify)

structure

- Tank
- Cave

4. Property Use ()

ABANDONED / IN USE

Present

Gateway and a park surrounding it

Past

Gateway.

5. Age (Source) ()

PERIOD ()

YEARS ()

Precise date of

Construction

In 1874 AD.

Completion

Subsequent changes

Destruction / Demolition

6. Ownership / Level of Protection ()

SINGLE / MULTIPLE

Public

Archaeological Survey of India / State Archaeology Department /
Any Other (Please specify) District authority

Private

Any other (Please specify)

Name

Address

Phone

7. Association ()

• WITH EVENTS

In History

In Rituals

In Building Construction

Any other (specify)

Arrival of British viceroy North
Brook.

• WITH PERSONS

Patron

Architect / Engineer

Any other (specify)

8. Statement of Significance ()

- Architectural
- Archaeological
- Historical
- Religious
- Any other (specify) _____

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

● Context

* Drawings (Attach extra sheet if necessary)

Urban / Rural Setting
Surroundings

Stand in Isolation *On the bank of river*
Integral part of a Landscape / Street / Complex *Brahmaputra*

● Quantification

Area Dimension (L x B x H) _____

_____ (m / cm/ feet / inch)

Number of Blocks _____

Number of Storeys _____

● Spatial Organization

Orientation _____

Plan _____

Allocation of Spaces _____

ARCHITECTURAL STYLE

● Ornamentation

Exteriors

Interiors

Movable Collections

* Any/Other (specify)

The gate was built to commemorate the visit of British viceroy Northbrook to Assam in 1874 AD, who announced the creation of Assam as a Chief Commissioner's province, for which the demand was in air, with its capital in Shillong.

In the same place, a victory pillar with the replica of stone inscription of Lachit Borphukan as memoir of Sarvaighat Battle of 1667 AD was also constructed

10. Construction Technology

Structural System _____

Building Techniques _____

Masonry

Material of Construction _____

11. Condition Assessment

In General

Good / Fair

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

In Brief (Attach extra sheet if necessary)

12. Threats to the Property

- Natural
- Negligence
- Vandalism
- Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs

(attach list as in page 6, in case of multiple photographs)

Photo Reference _____

CAPTION _____

15. Audio / Video

(related to rituals / performance / festivals etc.)

Reference _____

DESCRIPTION

Total duration - 00:06:34 min.

16. Maps/Plans/Drawings

17. Listers

NAME _____

NAME _____

18. Reviewers

NAME _____

NAME _____

COMMENTS _____

COMMENTS _____