



Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: ARCH/ASS/KRP/007

SECTION I : IDENTIFICATION

1. Name ()

Present

Navagraha

Past

Other Name (if any)

2. Location ()

Address

LONGITUDE 91°45'921" LATTITUDE N26°11'456"

Navagraha, Guwahati

Village (village code)

Post District Kamrup

State

Assam.

PIN

Approach

3. Property Type ()

Buildings

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

Engineering structure

- Bridge
- Tunnel
- Other engineering

Religious structures

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

Open space and related structures

- Public square
- Park or garden
- Graveyard
- Baolis, Well

Other Structures

- Wall
- Gateway
- Pillar
- Others (specify)

structure

- Tank
- Cave

4. Property Use ()

ABANDONED / IN USE

Present

Temple (new construction in the same site)

Past

Temple.

5. Age (Source) ()

PERIOD ()

YEARS ()

Precise date of

Construction

Completion

Subsequent changes

Destruction / Demolition

During Rajeswar Singha in 1752 AD.
 (An old temple was believed to be present earlier too)
 Yes.
 Earthquake of 1897 AD.

6. Ownership / Level of Protection ()

SINGLE / MULTIPLE

Public

Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)

Private

Any other (Please specify)

Name

Address

Phone

7. Association ()

• WITH EVENTS

History

In Rituals

In Building Construction

Any other (specify)

• WITH PERSONS

Patron King Rajeswar Singha (1751-1769 AD).

Architect / Engineer

Any other (specify)

8. Statement of Significance ()

- Architectural
- Archaeological
- Historical
- Religious
- Any other (specify) _____

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

● **Context**

* Drawings (Attach extra sheet if necessary)

Urban / Rural Setting
Surroundings

Stand in Isolation *A top a hillock called Chitrachal.*
Integral part of a Landscape / Street / Complex

● **Quantification**

Area Dimension (L x B x H)

_____ (m / cm/ feet / inch)

Number of Blocks

Number of Storeys

● **Spatial Organization**

Orientation

East.

Plan

Allocation of Spaces

ARCHITECTURAL STYLE

● **Ornamentation**

Exteriors

Interiors

Movable Collections

The temple contains nine plastic symbols representing nine planets. Old stone blocks are found lying around the area and in the plinth of the new construction.

* Any Other (specify)

An inscription of Rajeswar Singh (1752 AD) is placed in the front wall.

10. Construction Technology

Structural System

Not known as there is only blocks of stone lying here and there.

Building Techniques

Masonry.

Material of Construction

Stems, iron clamp (from the remains)

11. Condition Assessment

In General

Good / Fair

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

In Brief (Attach extra sheet if necessary)

12. Threats to the Property

- Natural
- Negligence
- Vandalism
- Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs

(attach list as in page 6, in case of multiple photographs)

Photo Reference _____

CAPTION _____

15. Audio / Video

(related to rituals / performance / festivals etc.)

Reference _____

DESCRIPTION *Total duration of 00:02:01 min.*

16. Maps/Plans/Drawings

17. Listers

NAME _____

NAME _____

18. Reviewers

NAME _____

NAME _____

COMMENTS _____

COMMENTS _____