



Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: ARCH/ASS/KRP/010.

SECTION I : IDENTIFICATION

1. Name ()

Present

Place of Shrikanth Sivalinga

Past

Other Name (if any)

2. Location ()

Address

LONGITUDE E 91°46'07" LATTITUDE N 26°11'35"

Navagnaha, Gurnahali

Village (village code)

Post District Kamrup.

State

Assam

PIN

Approach

3. Property Type ()

Buildings

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

Religious structures

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

Other Structures

- Wall
- Gateway
- Pillar
- Others (specify)

Engineering structure

- Bridge
- Tunnel
- Other engineering

Open space and related structures

- Public square
- Park or garden
- Graveyard
- Baolis, Well

structure

- Tank
- Cave

4. Property Use ()

ABANDONED / IN USE

Present

Small ~~Rajasth~~ Temple

Past

Probably a Temple

5. Age (Source) ()

PERIOD ()

YEARS ()

Precise date of

- Construction Not known
- Completion
- Subsequent changes
- Destruction / Demolition

6. Ownership / Level of Protection ()

SINGLE / MULTIPLE

Public Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) Private

Private

Any other (Please specify)

Name

Address

Phone

7. Association ()

• WITH EVENTS

- In History
- In Rituals
- In Building Construction
- Any other (specify)

• WITH PERSONS

- Patron
- Architect / Engineer
- Any other (specify)

8. Statement of Significance ()

- Architectural
- Archaeological
- Historical
- Religious
- Any other (specify) _____

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

● Context

* Drawings (Attach extra sheet if necessary)

Urban / Rural Setting
Surroundings

Stand in Isolation ✓ *On the campus of a govt. Residential area.*
Integral part of a Landscape / Street / Complex ✓

● Quantification

Area Dimension (L x B x H) _____

(m / cm/ feet / inch)

Number of Blocks _____

Number of Storys _____

● Spatial Organization

Orientation _____

Plan _____

Allocation of Spaces _____

ARCHITECTURAL STYLE

● Ornamentation

Exteriors

Interiors

Movable Collections

* Any Other (specify)

*Thicker plastic symbols are seen to be present in the same place.
In the site a few big big stone blocks are also lying with hole, probably fore joints with iron. Not much information about it is found.*

10. Construction Technology

Structural System _____

Building Techniques

Masonry

Material of Construction Stone, iron clamp.

11. Condition Assessment

In General

Good / Fair

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

In Brief (Attach extra sheet if necessary)

The history and context of this site is yet to be revealed.

12. Threats to the Property

- Natural
- Negligence
- Vandalism
- Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs

(attach list as in page 6, in case of multiple photographs)

Photo Reference _____

CAPTION _____

15. Audio / Video

(related to rituals / performance / festivals etc.)

Reference _____

DESCRIPTION _____

Total duration ⇒ 00:02:15 min.

16. Maps/Plans/Drawings

17. Listers

NAME _____

NAME _____

18. Reviewers

NAME _____

NAME _____

COMMENTS _____

COMMENTS _____