



Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: ARCH/ASS/ARCP/026

**SECTION I : IDENTIFICATION**

**1. Name ( )**

Present

Bal-Bhairav Temple (ASI)

Past

Other Name (if any)

**2. Location ( )**

Address

LONGITUDE N-26°09.953' LATITUDE E 091°42.202'

Kamakhya  
Village (village code)

Post Kamakhya District Kamrup  
PIN

State

Assam

Approach

Distance from Dist. Office to Kamakhya temple is 7.3 km. To Bal-Bhairav is 7.4 km. in South of Kamakhya temple.

**3. Property Type ( )**

Buildings

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

Engineering structure

- Bridge
- Tunnel
- Other engineering

Religious structures

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

Open space and related structures

- Public square
- Park or garden
- Graveyard
- Baolis, Well

Other Structures

- Wall
- Gateway
- Pillar
- Others (specify)

structure

- Tank
- Cave

**4. Property Use ( )**

ABANDONED / IN USE

Present

Past

*also used*

**5. Age (Source) ( )**

PERIOD ( )

YEARS ( ) 1568

Precise date of

Construction

Completion

Subsequent changes

Destruction / Demolition

**6. Ownership / Level of Protection ( )**

SINGLE / MULTIPLE

Public

Archaeological Survey of India / State Archaeology Department /  
Any Other (Please specify)

Private

Any other (Please specify)

Name

Address

Phone

**7. Association ( )**

• WITH EVENTS

In History

In Rituals

In Building Construction

Any other (specify)

• WITH PERSONS

Patron

Architect / Engineer

Any other (specify)

8. Statement of Significance ( )

- Architectural
- Archaeological
- Historical
- Religious
- Any other (specify) \_\_\_\_\_

**SECTION II: DESCRIPTION**

9. Physical Description and Decorative Features

- Context \* Drawings (Attach extra sheet if necessary)

Urban / Rural Setting  
 Surroundings  Stand in Isolation  
Integral part of a Landscape / Street / Complex

- Quantification
  - Area Dimension ( L x B x H) 0 → 2 feet 4 → 2 feet 4 inches  
(m / cm/ feet / inch)
  - Number of Blocks -
  - Number of Storeys -

- Spatial Organization
  - Orientation East-west direction.
  - Plan -
  - Allocation of Spaces -

**ARCHITECTURAL STYLE**

- Ornamentation
  - Exteriors Rock-cut stucco images.
  - Interiors -
  - Movable Collections -
- \* Any Other (specify) \_\_\_\_\_

10. Construction Technology

Structural System -

Building Techniques -

Material of Construction

Rock - Stone,

### 11. Condition Assessment

In General

Good / Fair

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

In Brief (Attach extra sheet if necessary)

The images are lying in the south of main kamalkhya temple around the jungle.

### 12. Threats to the Property

- Natural
- Negligence
- Vandalism
- Urban Pressures

**SECTION III: REFERENCES**

**13. Reference Sources (published and unpublished textual details)**

---

---

---

---

---

---

**14. Photographs**

(attach list as in page 6, in case of multiple photographs)

Photo Reference \_\_\_\_\_

CAPTION \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

**15. Audio / Video**

(related to rituals / performance / festivals etc.)

Reference \_\_\_\_\_

DESCRIPTION

*Duration - 00:02:14 Sec.*  
\_\_\_\_\_  
\_\_\_\_\_

**16. Maps/Plans/Drawings**

---

---

**17. Listers**

NAME \_\_\_\_\_

NAME \_\_\_\_\_

**18. Reviewers**

NAME \_\_\_\_\_

NAME \_\_\_\_\_

COMMENTS \_\_\_\_\_

COMMENTS \_\_\_\_\_