



## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: ARCH/ASS/KRP/087**SECTION I : IDENTIFICATION****1. Name ( )**

Present

Akashi Ganga

Past

Other Name (if any)

**2. Location ( )**LONGITUDE 26°10.593' LATITUDE 091°28.599'  
Address Shilguri

Village (village code) \_\_\_\_\_

Post Dharsuwas District Kamrup  
State Assam PIN 781103

Approach

Distance from P.C. Office to Dharsuwas is 40 km.  
Akashi Ganga is situated at the top of Shilguri.**3. Property Type ( )****Buildings**

- Palace  
 Fort  
 Citadel  
 Govt. building  
 Railway station  
 Defence building  
 Industrial building  
 Other public buildings  
 Residential building

**Engineering structure**

- Bridge  
 Tunnel  
 Other engineering

**Religious structures**

- Temple  
 Mosque  
 Minar  
 Church  
 Monastery  
 Stupa  
 Tomb, Mausoleum

**Open space and related structures**

- Public square  
 Park or garden  
 Graveyard  
 Baolis, Well

**Other Structures**

- Wall  
 Gateway  
 Pillar  
 Others (specify)

structure

- Tank
- Cave

4. Property Use ( )

ABANDONED / IN USE

Present

*In used as holy rain of Ganga months.*

Past

*was used.*

5. Age (Source) ( )

PERIOD ( )

YEARS ( )

*Unknown.*

Precise date of

Construction

Completion

Subsequent changes

Destruction / Demolition

6. Ownership / Level of Protection ( )

SINGLE / MULTIPLE

Public

Archaeological Survey of India / State Archaeology Department /  
Any Other (Please specify)

Private

Any other (Please specify)

Name

Address

Phone

7. Association ( )

• WITH EVENTS

- In History
- In Rituals
- In Building Construction
- Any other (specify)

• WITH PERSONS

- Patron
- Architect / Engineer
- Any other (specify) *Natural*

8. Statement of Significance ( )

- Architectural
- Archaeological
- Historical
- Religious
- Any other (specify) \_\_\_\_\_

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

• Context

\* Drawings (Attach extra sheet if necessary)

Urban / Rural Setting  
Surroundings

Stand in Isolation  
Integral part of a Landscape / Street / Complex

• Quantification

Area Dimension ( L x B x H) \_\_\_\_\_  
\_\_\_\_\_ (m / cm/ feet / inch)

Number of Blocks \_\_\_\_\_  
Number of Storys \_\_\_\_\_

• Spatial Organization

Orientation East west direction found in west.

Plan \_\_\_\_\_

Allocation of Spaces \_\_\_\_\_

ARCHITECTURAL STYLE

• Ornamentation

Exteriors lock covered.

Interiors stone-stair are seen.

Movable Collections \_\_\_\_\_

\* Any Other (specify)

10. Construction Technology

Structural System \_\_\_\_\_

Building Techniques \_\_\_\_\_

---

Material of Construction

---

---

### 11. Condition Assessment

---

In General

Good / Fair

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

In Brief (Attach extra sheet if necessary)

---

---

---

### 12. Threats to the Property

---

- Natural
- Negligence
- Vandalism
- Urban Pressures