



Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: ARCH/ASS/NGN/017

SECTION I : IDENTIFICATION**1. Name ()**

Present

Sri Sri Vishnupuri Shan

Past

Other Name (if any)

2. Location ()

Address

LONGITUDE $92^{\circ}42'45''$ ATTITUDE $N26^{\circ}07'25''$

State

Assam

Kamaimahi, Kathitali

Village (village code) VPSkupuri

Post Garukhanda District Nagaon

PIN 782428.

Approach

3. Property Type ()Buildings

- Palace
 Fort
 Citadel
 Govt. building
 Railway station
 Defence building
 Industrial building
 Other public buildings
 Residential building

Engineering structure

- Bridge
 Tunnel
 Other engineering

Religious structures

- Temple
 Mosque
 Minar
 Church
 Monastery
 Stupa
 Tomb, Mausoleum

Open space and related structures

- Public square
 Park or garden
 Graveyard
 Baolis, Well

Other Structures

- Wall
 Gateway
 Pillar
 Others (specify)

structure

- Tank
 Cave

4. Property Use ()

ABANDONED / IN USE

Present

Honshipping place

Past

Temple.

5. Age (Source) ()

PERIOD ()

YEARS ()

Precise date of

8th - 12th century AD.

Construction

Completion

Subsequent changes

Destruction / Demolition

6. Ownership / Level of Protection ()

SINGLE / MULTIPLE

Public

Archaeological Survey of India / State Archaeology Department /
Any Other (Please specify)

Private

Any other (Please specify)

Name

Address

Phone

7. Association ()

• WITH EVENTS

History

Rituals

In Building Construction

Any other (specify)

• WITH PERSONS

Patron

Architect / Engineer

Any other (specify)

8. Statement of Significance ()

- Architectural
- Archaeological
- Historical
- Religious
- Any other (specify) _____

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

• Context

* Drawings (Attach extra sheet if necessary)

Urban / Rural Setting
Surroundings

Stand in Isolation
Integral part of a Landscape / Street / Complex

• Quantification

Area Dimension (L x B x H)

Number of Blocks

Number of Storeys

The remains of the temple is only remained. But from that it can be guessed that these were the parts of a big temple.

• Spatial Organization

Orientation _____

Plan _____

Not known

Allocation of Spaces _____

ARCHITECTURAL STYLE

• Ornamentation

Exteriors

Interiors

Movable Collections

* Any Other (specify)

Parts of stone blocks contains gajasimha, kirittimukha, kalpabriksha and floral and creepery designs. Stone blocks containing different image panels are also found. Two Vishnu images (one broken), one oblong piece of long stone with inscription and an image of a male figure having a trishul in one hand and kamandaku in another are important.

10. Construction Technology

Structural System

Need further study before giving a final view, acceptable by all.

Building Techniques

Masonry

Material of Construction

Stone blocks, iron clamp.

11. Condition Assessment

In General

Good / Fair

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

In Brief (Attach extra sheet if necessary)

The stone blocks are lying unattended and some are yet to be excavated. ~~There is~~ ^{There is} a Vishnu image and the stone containing inscription need special attention.

12. Threats to the Property

- Natural
- Negligence
- Vandalism
- Urban Pressures