



## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: ARCH/ASS/NGN/024

SECTION I : IDENTIFICATION1. Name ( )

Present

Waregiding

Past

Other Name (if any)

2. Location ( )

Address

LONGITUDE  $E92^{\circ}46'014''$  LATITUDE  $N26^{\circ}02'625''$ 

State

Assam

Village (village code)

Waregiding

Post

District

PIN

Approach

3. Property Type ( )Buildings

- Palace  
 Fort  
 Citadel  
 Govt. building  
 Railway station  
 Defence building  
 Industrial building  
 Other public buildings  
 Residential building

Engineering structure

- Bridge  
 Tunnel  
 Other engineering

Religious structures

- Temple  
 Mosque  
 Minar  
 Church  
 Monastery  
 Stupa  
 Tomb, Mausoleum

Open space and related structures

- Public square  
 Park or garden  
 Graveyard  
 Baolis, Well

Other Structures

- Wall  
 Gateway  
 Pillar  
 Others (specify)

structure

- Tank  
 Cave

4. Property Use ( )

ABANDONED / IN USE

Present

Temple remains and protected document.

Past

Temple.

5. Age (Source) ( )

PERIOD ( )

YEARS ( )

Precise date of

Construction

Completion

Subsequent changes

Destruction / Demolition

7<sup>th</sup> - 11<sup>th</sup> C. AD.

6. Ownership / Level of Protection ( )

SINGLE / MULTIPLE

Public

Archaeological Survey of India / State Archaeology Department /  
Any Other (Please specify)

Private

Any other (Please specify)

Name

Address

Phone

7. Association ( )

• WITH EVENTS

- History  
 In Rituals  
 In Building Construction  
Any other (specify)

• WITH PERSONS

- Patron  
Architect / Engineer  
Any other (specify)

8. Statement of Significance ( )

- Architectural
- Archaeological
- Historical
- Religious
- Any other (specify) \_\_\_\_\_

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

• Context

\* Drawings (Attach extra sheet if necessary)

Urban / Rural Setting  
Surroundings

Stand in Isolation By the side of river Misanaai  
Integral part of a Landscape / Street / Complex

• Quantification

Area Dimension ( L x B x H)

Not known.

(m / cm / feet / inch)

Number of Blocks

Number of Storeys

• Spatial Organization

Orientation

Plan

Allocation of Spaces

ARCHITECTURAL STYLE

• Ornamentation

Exteriors

Interiors

Movable Collections

\* Any Other (specify)

Broken pillars, Yonipitha and a  
Siva linga is lying unattended  
and without any boundary.

10. Construction Technology

Structural System

needed.

Building Techniques

Masonry.

Material of Construction Cannot be concluded from the present existed remains.

### 11. Condition Assessment

In General

Good / Fair

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

In Brief (Attach extra sheet if necessary)

The site is neglected and the remains are decreased in numbers according to the local sources.

### 12. Threats to the Property

- Natural
- Negligence
- Vandalism
- Urban Pressures