



Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: ARCH/ASS/NGN/080

SECTION I : IDENTIFICATION

1. Name ()

Present

Yashajivri Vishnu Temple,
Siva Temple and Tank

Past

Other Name (if any)

2. Location ()

LONGITUDE $89^{\circ}47'966''$ LATITUDE $N26^{\circ}07'033''$

Address

Changmaji Mihir Pathar, Sabaka

Village (village code)

Post _____ District Nagpur
PIN _____

State

M.P.

Approach

Around 5KM from Sabaka

3. Property Type ()

Buildings

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

Religious structures

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

Other Structures

- Wall
- Gateway
- Pillar
- Others (specify)

Engineering structure

- Bridge
- Tunnel
- Other engineering

Open space and related structures

- Public square
- Park or garden
- Graveyard
- Baolis, Well

structure

- Tank
 Cave

4. Property Use ()

ABANDONED / IN USE

Present

Temple. (old temple non-existent
at present)

Past

Temple.

5. Age (Source) ()

PERIOD ()

YEARS ()

Precise date of
Construction 8th-11th century.
Completion
Subsequent changes
Destruction / Demolition

6. Ownership / Level of Protection ()

SINGLE / MULTIPLE

Public Archaeological Survey of India / State Archaeology Department /
Any Other (Please specify) Community

Private

Any other (Please specify)

Name

Address

Phone

7. Association ()

• WITH EVENTS

- In History
 In Rituals
In Building Construction
Any other (specify)

• WITH PERSONS

- Patron
Architect / Engineer
Any other (specify)

8. Statement of Significance ()

- Architectural
- Archaeological
- Historical
- Religious
- Any other (specify) _____

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

• Context

* Drawings (Attach extra sheet if necessary)

Urban / Rural Setting
Surroundings

Stand in Isolation
Integral part of a Landscape / Street Complex

• Quantification

Area Dimension (L x B x H)

Old Temple is non-existent -
- only remains. (m / cm / feet / inch)

Number of Blocks
Number of Storeys

• Spatial Organization

Orientation

Plan

Allocation of Spaces

ARCHITECTURAL STYLE

• Ornamentation

Exteriors

Interiors

Movable Collections

An image of Siva in tribal form
(known as 'Buhadevi'), broken parts
of door-frame, pillar found in the
region. The main image is of Vishnu.
Carved beautifully.

* Any Other (specify)

10. Construction Technology

Structural System Unknown - Need study to unfold
these facts.

Building Techniques Masonry (probably).

Material of Construction _____

11. Condition Assessment

In General

Good / Fair

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

In Brief (Attach extra sheet if necessary)

*This sensitive area needs special attention
to save the temple remains from complete extinction
and need systematic study to reveal facts*

12. Threats to the Property

- Natural
- Negligence
- Vandalism
- Urban Pressures