



Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: ARCM/ASS/NW/008.

SECTION I: IDENTIFICATION

1. Name ()

Present

Buchmath Birgab

Past

Other Name (if any)

2. Location ()

Address

LONGITUDE 86° 25.740' LATITUDE 091° 25.220'

Khajara

Village (village code)

State

Assam

Post Jagal Bazar District Nalbari
PIN

Approach

Distance from D.C. Office to Buchmath Birgab is 65.60 km.
Leads Nalbari Jalla road.

3. Property Type ()

Buildings

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

Engineering structure

- Bridge
- Tunnel
- Other engineering

Religious structures

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

Open space and related structures

- Public square
- Park or garden
- Graveyard
- Baolis, Well

Other Structures

- Wall
- Gateway
- Pillar
- Others (specify)

structure

- Tank
 Cave

4. Property Use ()

ABANDONED / IN USE

Present

for use

Past

was used

5. Age (Source) ()

PERIOD ()

YEARS () 19th century

Precise date of

Construction

Completion

Subsequent changes

Destruction / Demolition

6. Ownership / Level of Protection ()

SINGLE / MULTIPLE

Public

Archaeological Survey of India / State Archaeology Department /
Any Other (Please specify) _____

Private

Any other (Please specify) _____

Name

Address

Phone

7. Association ()

• WITH EVENTS

In History

In Rituals

In Building Construction

Any other (specify)

• WITH PERSONS

Patron

Architect / Engineer

Any other (specify)

8. Statement of Significance ()

- Architectural
- Archaeological
- Historical
- Religious
- Any other (specify) _____

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

• Context

* Drawings (Attach extra sheet if necessary)

Urban / Rural Setting
Surroundings

Stand in Isolation
Integral part of a Landscape / Street / Complex

• Quantification

Area Dimension (L x B x H)

Length = 11 ft 2 inch B = 2 feet 3 inch
(m / cm / feet / inch)

Number of Blocks

One

Number of Storeys

Single

• Spatial Organization

Orientation

the three shades faced in the south

Plan

-

Allocation of Spaces

Mandapa Garbhagruha

ARCHITECTURAL STYLE

• Ornamentation

Exteriors

Not found

Interiors

- do -

Movable Collections

Image, 'Baba', utensil etc.

* Any Other (specify)

10. Construction Technology

Structural System

Brick-butt

Building Techniques

Architectural

Material of Construction brick, cement, sand etc.

11. Condition Assessment

In General

Good / Fair

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

In Brief (Attach extra sheet if necessary)

12. Threats to the Property

- Natural
- Negligence
- Vandalism
- Urban Pressures