



Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: ARCH/ASS/SIN/036

**SECTION I : IDENTIFICATION**

**1. Name ( )**

Present

Aideu Pukhuri

Past

Other Name (if any)

**2. Location ( )**

Address

LONGITUDE E94°48'26' LATITUDE N26°59'484'

Barbaruah maidam, Hilotdharu Kanwar gram, Lakwa

Village (village code)

Post \_\_\_\_\_ District Sivasagar

State

Assam.

PIN

Approach

**3. Property Type ( )**

Buildings

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

Religious structures

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

Other Structures

- Wall
- Gateway
- Pillar
- Others (specify)

Engineering structure

- Bridge
- Tunnel
- Other engineering

Open space and related structures

- Public square
- Park or garden
- Graveyard
- Baolis, Well

structure

- Tank
- Cave

4. Property Use ( )

ABANDONED / IN USE

Present

Fishery

Past

Tank.

5. Age (Source) ( )

PERIOD ( )

YEARS ( )

Precise date of

Construction

Completion

Subsequent changes

Destruction / Demolition

18th Century AD.

6. Ownership / Level of Protection ( )

SINGLE / MULTIPLE

Public

Archaeological Survey of India / State Archaeology Department /  
Any Other (Please specify) Villagers.

Private

Any other (Please specify)

Name

Address

Phone

7. Association ( )

• WITH EVENTS

In History

In Rituals

In Building Construction

Any other (specify)

• WITH PERSONS

Patron

Architect / Engineer

Any other (specify)

In the name of Arden, wife of  
Kirtichandra Barabarath, an official  
of Akbar King.



**8. Statement of Significance ( )**

- Architectural
- Archaeological
- Historical
- Religious
- Any other (specify) \_\_\_\_\_

**SECTION II: DESCRIPTION**

**9. Physical Description and Decorative Features**

● **Context**

\* **Drawings** (Attach extra sheet if necessary)

Urban / Rural Setting  
Surroundings

Stand in Isolation  
 Integral part of a Landscape / Street / Complex

● **Quantification**

Area Dimension ( L x B x H)

2 Bighas (approx.)  
\_\_\_\_\_ (m / cm / feet / inch)

Number of Blocks

one

Number of Storeys

1

● **Spatial Organization**

Orientation

\_\_\_\_\_

Plan

Rectangular

Allocation of Spaces

\_\_\_\_\_

**ARCHITECTURAL STYLE**

● **Ornamentation**

Exteriors

\_\_\_\_\_

Interiors

NA

Movable Collections

NA

\* **Any Other** (specify)

\_\_\_\_\_

**10. Construction Technology**

Structural System

Typical tank construction methods of Ahom reign.

Building Techniques

\_\_\_\_\_

---

Material of Construction \_\_\_\_\_

---

---

### 11. Condition Assessment

---

In General

Good / Fair

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

In Brief (Attach extra sheet if necessary)

*Need protection and recognition symbol/mark.*

---

---

### 12. Threats to the Property

---

- Natural
- Negligence
- Vandalism
- Urban Pressures