



Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: ARCH/ASS/SIN/041

SECTION I : IDENTIFICATION

1. Name ()

Present

Rahdoi Pukhuri

Past

Other Name (if any)

2. Location ()

LONGITUDE E94°48'55" LATTITUDE N26°53'965"

Address

Santak

Village (village code) Paton gram

Post District Sivsoar

State

Assam

PIN

Approach

3. Property Type ()

Buildings

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

Engineering structure

- Bridge
- Tunnel
- Other engineering

Religious structures

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

Open space and related structures

- Public square
- Park or garden
- Graveyard
- Baolis, Well

Other Structures

- Wall
- Gateway
- Pillar
- Others (specify)

structure

- Tank
- Cave

4. Property Use ()

ABANDONED / IN USE

Present

Tank

Past

Tank

5. Age (Source) ()

PERIOD ()

YEARS ()

Precise date of

Construction 1683 AD

Completion

Subsequent changes

Destruction / Demolition

6. Ownership / Level of Protection ()

SINGLE / MULTIPLE

Public Archaeological Survey of India / State Archaeology Department /
Any Other (Please specify) Community

Private

Any other (Please specify)

Name

Address

Phone

7. Association ()

• WITH EVENTS

- In History
- In Rituals
- In Building Construction
- Any other (specify)

• WITH PERSONS

- Patron King Gadadhar Singh
- Architect / Engineer
- Any other (specify)

In the name of a lady ^{Rakdasi} who helped him in the days of crisis.

8. Statement of Significance ()

- Architectural
- Archaeological
- Historical
- Religious
- Any other (specify) _____

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

● Context

* Drawings (Attach extra sheet if necessary)

Urban / Rural Setting
Surroundings

Stand in Isolation
Integral part of a Landscape / Street / Complex

● Quantification

Area Dimension (L x B x H)

Area during construction is 18 acre.
(m / cm/ feet / inch)

Number of Blocks
Number of Storys

● Spatial Organization

Orientation

Plan

Rectangular

Allocation of Spaces

ARCHITECTURAL STYLE

● Ornamentation

Exteriors

Interiors

Movable Collections

* Any Other (specify)

10. Construction Technology

Structural System

Elaborate tank digging technique followed during Ahom reign

Building Techniques

Material of Construction

11. Condition Assessment

In General

Good / Fair

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

In Brief (Attach extra sheet if necessary)

12. Threats to the Property

- Natural
- Negligence
- Vandalism
- Urban Pressures