



**Documentation format for Archaeological / Heritage Sites / Monuments**

Serial No.: ARCH/ACC/SIV/043.

**SECTION I : IDENTIFICATION**

**1. Name ( )**

Present

Chelia pukhuri

Past

Other Name (if any)

**2. Location ( )**

Address

LONGITUDE E 94°49'40" LATTITUDE N 26°53'002'

State

Assam.

Nrimaigans, Narsinga  
Village (village code) Habigan  
Post Narsinga District Sivsagar  
PIN

Approach

**3. Property Type ( )**

Buildings

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

Religious structures

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

Other Structures

- Wall
- Gateway
- Pillar
- Others (specify)

Engineering structure

- Bridge
- Tunnel
- Other engineering

Open space and related structures

- Public square
- Park or garden
- Graveyard
- Baolis, Well

structure

- Tank
- Cave

4. Property Use ( )

Present

ABANDONED / IN USE

Tank

Past

Tank

5. Age (Source) ( )

PERIOD ( )

YEARS ( )

Precise date of

Construction

Completion

Subsequent changes

Destruction / Demolition

During the Ahom Kings.

6. Ownership / Level of Protection ( )

SINGLE / MULTIPLE

Public

Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) Community

Private

Any other (Please specify)

Name

Address

Phone

7. Association ( )

• WITH EVENTS

History

In Rituals

In Building Construction

Any other (specify)

• WITH PERSONS

Patron

Architect / Engineer

Any other (specify)

8. Statement of Significance ( )

- Architectural
- Archaeological
- Historical
- Religious
- Any other (specify) \_\_\_\_\_

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

Context

\* Drawings (Attach extra sheet if necessary)

Urban / Rural Setting  
Surroundings

Stand in Isolation  At present by the side of 179 no.  
Integral part of a Landscape / Street / Complex Nimaigarh  
Primary School.

Quantification

Area Dimension ( L x B x H)

Area = Approx. 4 Bighas.  
\_\_\_\_\_ (m / cm / feet / inch)

Number of Blocks \_\_\_\_\_

Number of Storys \_\_\_\_\_

Spatial Organization

Orientation \_\_\_\_\_

Plan

Square.

Allocation of Spaces \_\_\_\_\_

ARCHITECTURAL STYLE

Ornamentation

Exteriors \_\_\_\_\_

Interiors \_\_\_\_\_

Movable Collections \_\_\_\_\_

\* Any Other (specify) \_\_\_\_\_

10. Construction Technology

Structural System

Jack digging during Ahom reign  
constituted of elaborate processes

Building Techniques \_\_\_\_\_

---

**Material of Construction** \_\_\_\_\_

---

---

**11. Condition Assessment**

---

In General

Good / Fair

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

In Brief (Attach extra sheet if necessary)

---

---

---

**12. Threats to the Property**

---

- Natural
- Negligence
- Vandalism
- Urban Pressures