



Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: ARCH/ASS/SLV/051

SECTION I : IDENTIFICATION

1. Name ()

Present

Nangala mora

Past

Other Name (if any)

2. Location ()

Address

LONGITUDE E 94°46' 33" LATTITUDE N 26° 59' 618"

Nangala mora tiniali

Shitai pukhuri

Village (village code)

Post Shitai pukhuri District Sitpagan

State

Assam

PIN

Approach

9 KM from Kherpoka tiniali

3. Property Type ()

Buildings

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

Engineering structure

- Bridge
- Tunnel
- Other engineering

Religious structures

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

Open space and related structures

- Public square
- Park or garden
- Graveyard
- Baolis, Well

Other Structures

- Wall
- Gateway
- Pillar
- Others (specify)

structure

- Tank
 Cave

4. Property Use (□□□□□□ □□ □□□□□)

ABANDONED / IN USE

Present

Lying as a symbol of earlier pride.

Past

Entrance gate to the palace compound of Parkgaon.

5. Age (Source) (□□□□□□ □□ □□□)

PERIOD (□□□)

YEARS (□□□□)

Precise date of

Construction

Completion

Subsequent changes

Destruction / Demolition

16th century AD.

6. Ownership / Level of Protection (□□□□□□ □□ □□□□□ □□□ □□□□□ □□ □□□□)

SINGLE / MULTIPLE

Public

Archaeological Survey of India / State Archaeology Department /
Any Other (Please specify) No protection

Private

Any other (Please specify)

Name

Address

Phone

7. Association (□□□□□)

• WITH EVENTS

In History

In Rituals

In Building Construction

Any other (specify)

• WITH PERSONS

Patron

Architect / Engineer

Any other (specify)

8. Statement of Significance (□ □ □ □ □ □ □ □ □ □ □ □)

- Architectural
- Archaeological
- Historical
- Religious
- Any other (specify) _____

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

● Context

* Drawings (Attach extra sheet if necessary)

Urban / Rural Setting
Surroundings

Stand in Isolation
Integral part of a Landscape / Street / Complex

● Quantification

Area Dimension (L x B x H)

H = 2 feet 6 inch (present pieces)
_____ (m / cm / feet / inch)

Number of Blocks
Number of Storeys

Two double holed vertical
stone pieces lying on the chawk.

● Spatial Organization

Orientation

Along NE-SW direction.

Plan

NA

Allocation of Spaces

NA

ARCHITECTURAL STYLE

● Ornamentation

Exteriors

No ornamentation except two rounded
hole

Interiors

—

Movable Collections

—

* Any Other (specify)

10. Construction Technology

Structural System

This used to be the security gate
before entering the palace complex of Jahangir.

Building Techniques

Stone.

Material of Construction Stone.

11. Condition Assessment

In General

Good / Fair

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

In Brief (Attach extra sheet if necessary)

Loss of some parts is seen. This pile is seen lying on the corner of a road, where the structure is made to symbolically represent the old gateway.

12. Threats to the Property

- Natural
- Negligence
- Vandalism
- Urban Pressures