



Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: ARCH/ASS/SIV/058

SECTION I : IDENTIFICATION

1. Name ()

Present

Barbaruah pukhuri

Past

Other Name (if any)

2. Location ()

Address

LONGITUDE E 94°43'716" LATITUDE N 26°54'345"

Near Nazira SDO office.
Nazira

Village (village code)

Post _____ District Sivasagar
PIN _____

State

Assam

Approach

3. Property Type ()

Buildings

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

Engineering structure

- Bridge
- Tunnel
- Other engineering

Religious structures

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

Open space and related structures

- Public square
- Park or garden
- Graveyard
- Baolis, Well

Other Structures

- Wall
- Gateway
- Pillar
- Others (specify)

structure

- Tank
- Cave

4. Property Use ()

ABANDONED / IN USE

Present

Tank

Past

Tank

5. Age (Source) ()

PERIOD ()
YEARS ()

Precise date of
Construction
Completion
Subsequent changes
Destruction / Demolition

During Atom Kings.

6. Ownership / Level of Protection ()

SINGLE / MULTIPLE

Public Archaeological Survey of India / State Archaeology Department /
Any Other (Please specify) Local people

Private

Any other (Please specify)

Name

Address

Phone

7. Association ()

• WITH EVENTS

- History
- In Rituals
- In Building Construction
- Any other (specify)

• WITH PERSONS

- Patron
- Architect / Engineer
- Any other (specify)

8. Statement of Significance ()

- Architectural
- Archaeological
- Historical
- Religious
- Any other (specify) _____

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

● Context

* Drawings (Attach extra sheet if necessary)

Urban / Rural Setting
Surroundings

Stand in Isolation
Integral part of a Landscape / Street / Complex

(on the side of Nagina SDO office & other govt buildings)

● Quantification

Area Dimension (L x B x H)

Area = 20 pucca with the banks. (m / cm / feet / inch)

Number of Blocks

Number of Storeys

● Spatial Organization

Orientation

Plan

Allocation of Spaces

—
Square
—

ARCHITECTURAL STYLE

● Ornamentation

Exteriors

NA

Interiors

NA

Movable Collections

NA

* Any Other (specify)

10. Construction Technology

Structural System

Lack digging during Ahom reign involved detail / elaborate methodology.

Building Techniques

—

Material of Construction _____

11. Condition Assessment

In General

Good / Fair

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

In Brief (Attach extra sheet if necessary)

The context of the tank is forgotten due to negligence and lack of awareness. The tanks are under ingrossment.

12. Threats to the Property

- Natural
- Negligence
- Vandalism
- Urban Pressures