



Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: ARCH/ASS/SW/097

SECTION I : IDENTIFICATION

1. Name ()

Present

Charaiduu Aasal

Past

Other Name (if any)

2. Location ()

Address

LONGITUDE 94° 51' 689" LATTITUDE N 26° 56' 010"

Charaiduu

Village (village code)

Post

District

Sivasagar

State

Assam

PIN

Approach

3. Property Type ()

Buildings

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

Religious structures

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

Other Structures

- Wall
- Gateway
- Pillar
- Others (specify)

Engineering structure

- Bridge
- Tunnel
- Other engineering

Open space and related structures

- Public square
- Park or garden
- Graveyard
- Baolis, Well

structure

- Tank
- Cave

4. Property Use ()

ABANDONED / IN USE

Present

Past

Temple

5. Age (Source) ()

PERIOD ()
YEARS ()

Precise date of

- Construction *Later 13th cr AD - later 14th cr. AD.*
- Completion
- Subsequent changes
- Destruction / Demolition

6. Ownership / Level of Protection ()

SINGLE / MULTIPLE

Public Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) _____

Private *Lying in midst of jungle*

Any other (Please specify) _____

Name _____

Address _____

Phone _____

7. Association ()

• WITH EVENTS

- In History
- In Rituals
- In Building Construction
- Any other (specify)

• WITH PERSONS

- Patron
- Architect / Engineer
- Any other (specify)

8. Statement of Significance ()

- Architectural
- Archaeological
- Historical
- Religious
- Any other (specify) Evidence of early Aham Kingdom (13th-14th Cr. AD)

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

● **Context**

* **Drawings** (Attach extra sheet if necessary)

Urban / Rural Setting
Surroundings

Stand in Isolation Above a hillock
Integral part of a Landscape / Street / Complex

● **Quantification**

Area Dimension (L x B x H)

Unknown.

(m / cm / feet / inch)

Number of Blocks

—

Number of Storeys

—

● **Spatial Organization**

Orientation

—

Plan

Allocation of Spaces

ARCHITECTURAL STYLE

● **Ornamentation**

Exteriors

Not known

Interiors

Not known

Movable Collections

—

* **Any Other** (specify)

Three pillars and remains of brick are only present

10. Construction Technology

Structural System

—

Building Techniques

Masonry and brick

Material of Construction Stone, brick

11. Condition Assessment

In General

Good / Fair

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

In Brief (Attach extra sheet if necessary)

The study is needed to unfold the facts about it. Presently, arrangements for oil and gas production is being going on which can exist the remains completely.

12. Threats to the Property

- Natural
- Negligence
- Vandalism
- Urban Pressures