



## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: ARCH/A44/SW/103

**SECTION I : IDENTIFICATION****1. Name ( )**

Present

Central Baptist Church

Past

Other Name (if any)

**2. Location ( )**

Address

LONGITUDE  $94^{\circ}38'41''$  LATITUDE  $N26^{\circ}59'32''$ 

Sivasagar Rudhupur

Village (village code)

Post

District

Sivasagar

State

Assam

PIN

Approach

**3. Property Type ( )****Buildings**

- Palace  
 Fort  
 Citadel  
 Govt. building  
 Railway station  
 Defence building  
 Industrial building  
 Other public buildings  
 Residential building

**Engineering structure**

- Bridge  
 Tunnel  
 Other engineering

**Religious structures**

- Temple  
 Mosque  
 Minar  
 Church  
 Monastery  
 Stupa  
 Tomb, Mausoleum

**Open space and related structures**

- Public square  
 Park or garden  
 Graveyard  
 Baolis, Well

**Other Structures**

- Wall  
 Gateway  
 Pillar  
 Others (specify)

structure

- Tank
- Cave

4. Property Use ( )

ABANDONED / IN USE

Present

Church

Past

Church

5. Age (Source) ( )

PERIOD ( )

YEARS ( )

Precise date of

Construction

Completion

Subsequent changes

Destruction / Demolition

19th century AD. - 1845 AD.

Yes.

6. Ownership / Level of Protection ( )

SINGLE / MULTIPLE

Public

Archaeological Survey of India / State Archaeology Department /

Any Other (Please specify)

Community

Private

Any other (Please specify)

Name

Address

Phone

7. Association ( )

• WITH EVENTS

History

In Rituals

In Building Construction

Any other (specify)

• WITH PERSONS

Patron

Architect / Engineer

Any other (specify)

American missionaries Nathan Brown, Oliver Cutter etc who work for Assamese language and literature

**8. Statement of Significance ( )**

- Architectural
- Archaeological
- Historical
- Religious
- Any other (specify) \_\_\_\_\_

**SECTION II: DESCRIPTION**

**9. Physical Description and Decorative Features**

● **Context**

\* **Drawings** (Attach extra sheet if necessary)

Urban / Rural Setting  
Surroundings

Stand in Isolation  
Integral part of a Landscape / Street / Complex

● **Quantification**

Area Dimension ( L x B x H)

\_\_\_\_\_ (m / cm / feet / inch)

Number of Blocks

Number of Storeys

● **Spatial Organization**

Orientation

On the southwest bank of Sivsagar

Plan

Rectangular

Allocation of Spaces

**ARCHITECTURAL STYLE**

● **Ornamentation**

Exteriors

Interiors

Movable Collections

The iron pillars reminds of the  
golden past.

Old benches.

\* **Any Other** (specify)

**10. Construction Technology**

Structural System

Church structure with considerable  
regional elements

Building Techniques

Concrete.

---

**Material of Construction**

---

---

**11. Condition Assessment**

In General

Good / Fair ✓

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

In Brief (Attach extra sheet if necessary)

---

---

---

**12. Threats to the Property**

- Natural
- Negligence
- Vandalism
- Urban Pressures