INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, <u>www.ignca.gov.in</u>

# Documentation format for Archaeological / Heritage Sites / Monuments

### Serial No.: OR/JPR-28

		SECT		ENTIFICATI	ON	
1. Name						
Present Past Other Name	(if any):	:				n Temple, Trilochanesvara Town, Dist Jajpur
2. Location						
2. Location						
LONGITUDE	86 <sup>0</sup> 20' 24" E	LAT	ITUDE	20 <sup>0</sup> 49' 44"	Ν	ELEVATION 30 ft
Address		:	Village	(village cod	e)	Trilochanesvara Temple
				Devidwar Jajpur Town Orissa		Complex, Trilochanapada Via: Devidwar District: Jajpur PIN: 755007
Approach		:	within tł stream Jajpur-	ne complex a Hamsarekha	nd or is lo	e Trilochanesvara temple n the right bank of the dried cated on the left side of It a distance of 1 km south of
3. Property	Туре					
Bu	ıildings	R	eliaious	structures		Other Structures
Palace	0		mple		Γ	Wall
Fort		Mc	sque			Gateway
Citadel		Mii	ner			Pillar
Govt. bu	ilding	Ch	urch			Others (specify):
Railway	station	Mc	nastery			
Defence		Sp	uta			
Industria	I building	-	mb, Maus	oleum		
	blic buildings				1	Note :
	tial building					It is a dilapidated temple that
	Ū					exists only up to the bada,
Enginee	ring structure	Open s	space an	d related		enshrining a Chaturmukha Siva
-		struct				inga in the sanctum.
Bridge		Pu	blic squar	е		
Tunnel		Pa	k or gard	en		
Other en	gineering structure	Gra	aveyard			
		Ba	olis, Well			
		Tai	nk			
		Ca	ve			

4. Property Use		
		ABANDONED / IN USE : In use
Present	:	Living temple, the presiding deity is a Chaturmukha Sivalinga which is 2.00 mtrs below the present ground level.
Past	:	Worshipped.
5. Age (Source)		
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition		Somavamsi rule 11 <sup>th</sup> century A.D.   
6. Ownership / Level of Protection	<u>on</u>	
		SINGLE /MULTIPLE : Multiple
<b>Public</b> : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	:	Protected Monument of Archaeological Survey of India.
Private	:	
Any other (Please specify)	:	Trilochanesvara Temple Trust Board under the presidentship of Amulya Ku. Mohanty
Name	:	
Address Phone	:	Archaeological Survey of India, Bhubaneswa Circle, 153 VIP Area, Nayapalli, Bhubaneswar, Orissa 0674-2558170
FIIONE	•	0074-2330170
7. Association		
WITH EVENTS		
In History	:	 Civeratui Kentika Dumima ete
In Rituals In Building Construction		Sivaratri, Kartika Purnima, etc. 
Any other (specify)	:	
WITH PERSONS		
Patron	:	Presently under the care of Archaeological Survey of India.
Architect / Engineer	÷	 Trilophonopyara Tompla Trust Doord
Any other (specify)		Trilochanesvara Temple Trust Board
8. Statement of Significance		
Architectural Archaeological Historical	:	<ul> <li>✓ Architectural</li> <li>✓ Archaeological</li> </ul>

	Religious	:	$\checkmark$	Religi	ous					
	Any other (specify)	:					iconographical			
<i>parsvadevatas</i> , the temple can be dated to t A.D. i.e. the Somavamsi rule in Orissa.					d to the 11	<sup>n</sup> cer	ntury			
			A.D.	1.e. th	ie Soma	vams	si rule in Orissa.			

# **SECTION II: DESCRIPTION**

# 9. Physical Description and Decorative Features \_

<ul> <li>Context</li> <li>Urban / Rural Setting</li> <li>Surroundings</li> </ul>	:	* <b>Drawings (Attach extra sheet if necessary)</b> : No Urban setting
j-		Stand in Isolation Integral part of a Landscape / Complex Street / Complex :
• <b>Quantification</b> Area Dimension ( L x B x H)	:	1.20 mtrs x 1.20 mtrs x 1.10 mtrs (existing height)
Number of Blocks Number of Storys	:	One N.A.
• <b>Spatial Organization</b> Orientation Plan Allocation of Spaces	:	Facing towards west. Consists of a square <i>vimana</i> only. 4.50 mtrs (L) x 2.65 mtrs (W)
ARCHITECTURAL STYLE     Ornamentation		
Exteriors Interiors Movable Collections * <b>Any Other</b> (specify)	:	Decorated with scroll work, <i>kirtimukha</i> design, <i>dvarapala</i> at the base of the doorjambs and a ten- armed Mahisasuramardini Durga in the northern <i>parsvadevata</i> niche. Plain Nil The temple is <i>triratha</i> on plan and <i>triangabada</i> in elevation.
10. Construction Technology		
Structural System Building Techniques Material of Construction	:	As the temple exists up to the <i>bada</i> portion, the order of the temple could not be ascertained. Ashlar dry masonry Khandolite stone is used for the construction of the temple.
11. Condition Assessment		
In General Good / Fair	:	Fair
Sign of Deterioration		

Serious Deterioration
Danger of Disappearance

### In Brief (Attach extra sheet if necessary):

The temple is broken above its *bada* and water stagnates in the temple during rainy season as it is 2.00 mtrs below the present ground level.

### **12. Threats to the Property**

1	Natural
	Negligence
	Vandalism
	Urban Pressures

## **SECTION III:** REFERENCES

- 1. K. C. Biswal, 2005, Monuments In and Around Jajpur, in G. Mohanty et al. (eds), *Cultural Heritage of Jajpur*, Bhubaneswar.
- 2.
- 3.

# 14. Photographs: 13 nos. (attach list as in page 6, in case of multiple photographs) Photo Reference : CAPTION : 15. Audio / Video (related to rituals / performance / festivals etc.) Reference : DESCRIPTION : 16. Maps/Plans/Drawings :

### 17. Listers

NAME: Jaya Shankar Naik <b>NAME</b> :	NAME :	Jaya Shankar Naik	NAME :	
---------------------------------------	--------	-------------------	--------	--

### 18. Reviewers

NAME :	Dr. S. Pradhan
COMMENTS	

NAME : COMMENTS :