

## INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR/JPR-60 **SECTION I: IDENTIFICATION** 1. Name Present Ganesa Temple, Siddhesvara Temple Complex, Siddhesvara, Dist. - Jajpur Past Other Name (if any): 2. Location 86<sup>0</sup> 22' 53" E 20<sup>0</sup> 51' 43" N LATITUDE LONGITUDE **ELEVATION** 23 ft Address Village (village code) Siddhesvara Post: Rambag Via: Rambag **Tehsil:** Jajpur Town District: Jajpur State: Orissa **PIN:** 755038 Approach The temple is located on the north-eastern corner of the main shrine Siddhesvara and situated on the right bank of the river Vaitarani. It can be approached on the left side of Jajpur-Mangalpur road, at a distance of 2.5 kms branching from Sundureimuhan chowk. It is about 6 kms from Jajpur town. 3. Property Type Religious structures Other Structures Buildings Palace Temple Wall Mosque Fort Gateway Pillar Citadel Minar Others (specify) Govt. building Church Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: structures The temple has a pidha vimana Bridge Public square of Kalingan order. Tunnel Park or garden Graveyard Other engineering structure Baolis. Well Tank

Cave

## 4. Property Use

ABANDONED / IN USE: In use

Present : Living temple, the presiding deity is a four-armed

Ganesa image.

Past : Worshipped

5. Age (Source)

**PERIOD** : Ganga rule **YEARS** : 15<sup>th</sup> century A.D.

**Precise date of Construction**: First quarter of the 15<sup>th</sup> century AD.

Completion : --

**Subsequent changes** : The temple is entirely plastered in later period.

Destruction / Demolition : ---

6. Ownership / Level of Protection

**SINGLE /MULTIPLE:** Multiple

Public: Archaeological Survey of : Endowment Department, Government of Orissa

India / State Archaeology Department / Any Other (Please

specify)

Private : ---

Any other (Please specify) : Siddhesvara Temple Managing Trust Board

Name : --

Address : AT-Siddhesvara, PO.- Rambag, Dist.- Jajpur, Orissa

Phone : ---

7. Association

WITH EVENTS

In History : ---

In Rituals : Ganesa chauthi

In Building Construction : --Any other (specify) : ---

WITH PERSONS

Patron : Presently under the care of Endowment Department,

Government of Orissa.

Architect / Engineer : ---

Any other (specify) : Siddhesvara Temple Managing Trust Board

## 8. Statement of Significance

Architectural
Archaeological
Historical

✓ Architectural
✓ Archaeological

HISTORICAL

Religious 

Religious

Any other (specify) : On architectural ground and iconographical features, the

temple can be dated to the first quarter of the 15<sup>th</sup> century

	AD. I.e. the Ganga rule in Onssa.					
SECTION II: DESCRIPTION  9. Physical Description and Decorative Features						
<ul> <li>Context</li> <li>Urban / Rural Setting</li> <li>Surroundings</li> </ul>	* <b>Drawings</b> (Attach extra sheet if necessary): No Rural setting					
	Stand in Isolation Integral part of a Landscape / Complex Street / Complex :					
<ul> <li>Quantification</li> <li>Area Dimension ( L x B x H)</li> </ul>	: 4.00 mtrs x 4.00 mtrs x 7.00 mtrs (approximate height) (m / cm/ feet / incl	h)				
Number of Blocks Number of Storys	: One : N.A.	'/				
<ul> <li>Spatial Organization</li> <li>Orientation</li> <li>Plan</li> <li>Allocation of Spaces</li> </ul>	<ul> <li>Facing towards south</li> <li>The <i>vimana</i> is square on plan.</li> <li>39.62 mtrs. (L) X 21.33 mtrs.(W)</li> </ul>					
• Ornamentation Exteriors Interiors Movable Collections * Any Other (specify)  10. Construction Technology	<ul> <li>Plain</li> <li>Plain</li> <li>Bust part of Siva, Parvati, divine figures etc.</li> <li>The temple is <i>triratha</i> on plan.</li> </ul>					
Structural System Building Techniques Material of Construction	<ul> <li>: Pidha vimana of Kalingan order.</li> <li>: Ashlar masonry.</li> <li>: Khandolite is used for the construction of the temporand presently the entire surface is white washed.</li> </ul>	le				
11. Condition Assessment						
In General Good / Fair  ✓ Sign of Deterioration Serious Deterioration Danger of Disappearance	: Fair					
In Brief (Attach extra sheet if necessary):						

During rainy season the flood water stagnates in the temple complex.

12. Threats	to the Property		_		
		<b>✓</b>	Natural		
			Negligence		
			Vandalism		
			Urban Pressures		
xxxx	<pre></pre>	ххх			
SECTION III: REFERENCES					
13. Reference	e Sources (publishe	ed and	d unpublished textual details)		
1					
2					
44 51 4					
14. Photogra	phs: 16 nos.		(attach list as in page 6, in case of multiple photographs		
			(attach list as in page o, in case of multiple photographs		
Photo Refere	nce	:			
CAPTION		:			
15. Audio / Vi	ideo				
			(related to rituals / performance / festivals etc.		
Reference		:			
DESCRIPTIO	N	:			
16. Maps/Pla	ns/Drawings				
17. Listers					
NAME :	D.B. Garnayak		NAME:		
18.Reviewers	•				
NAME :	Dr. S. Pradhan		NAME :		
COMMENTS	DI. S. FIAUIIAII		COMMENTS:		