

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

		Serial No.: OR/JPR- 72
1. Name	SECTION I: IDENTIFICATION	I
Present	: Hara-Gouri Temple, V Jajpur Town, Dist. – Jaj	/arahanatha Temple Complex,
Past Other Name (if any):	: :	
2. Location		
LONGITUDE 86 ⁰ 05' 08" E	LATITUDE 20 ⁰ 51' 30" N	ELEVATION 15 ft
Address	: Village (village code) Post : Jajpur Town Tehsil: Jajpur Town State : Orissa	Varahanatha Temple Complex, Varahanatha Via: Jajpur Town District: Jajpur PIN: 755001
Approach	Varahanatha temple w an island with picture river Vaitarani has bee	ice of 20 mtrs south-east of the ithin the complex is located on sque surroundings, where the n branched off on both sides. It our town bus stand and opposite hata.
3. Property Type		
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building	Religious structures Temple Mosque Miner Church Monastery Sputa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify):
Other public buildings Residential building	Tomb, Madsoleam	Note: The temple has a <i>pidha vimana</i> of impoverished <i>Kalingan</i> orde
Bridge Tunnel Other engineering structure	Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank	and half of its <i>bada</i> is buried ir the ground.

	Cave

4. Property Use

ABANDONED / IN USE: In use

Present Living temple, the presiding deity is an Ekamukhi

Sivalinga within a circular yonipitha, which is locally

called as Hara-Gouri Siva.

Worshipped. **Past**

5. Age (Source)

PERIOD Late Ganga rule YEARS 15th century A.D.

First half of the 15th century A.D. **Precise date of Construction**

Completion

Subsequent changes **Destruction / Demolition**

6. Ownership / Level of Protection

SINGLE /MULTIPLE: Multiple

Public: Archaeological Survey of : Protected Monument of Archaeological Survey of India

State Archaeology / Department / Any Other (Please

specify)

Private

Any other (Please specify) **Endowment Department, Government of Orissa**

Name

Address Archaeological Survey of India, Bhubaneswar Circle,

153 VIP Area, Nayapalli, Bhubaneswar, Orissa

0674-2558170 Phone

7. Association

WITH EVENTS

In History

In Rituals Sivaratri, Kartika Purnima, etc are held here.

In Building Construction

Any other (specify) Thread ceremony, marriage, engagements, etc are

held here.

WITH PERSONS

Patron Presently under the care of Archaeological Survey of

India.

Architect / Engineer

Any other (specify) Endowment Department, Government of Orissa

8. Statement of Significance

Architectural Architectural :

Archaeological

Historical Religious Any other (specify)	 : ✓ Religious : On architectural ground and iconographical features of the loose sculptures, the temple can be dated to the first half of the 15th century A.D. i.e. the late Ganga rule in Orissa. 			
SECTION II: DESCRIPTION 9. Physical Description and Decorative Features				
Context Urban / Rural Setting	* Drawings (Attach extra sheet if necessary) : No : Urban setting			
Surroundings	Stand in Isolation Integral part of a Landscape / Complex Street / Complex :			
• Quantification Area Dimension (L x B x H)	: 3.20 mtrs x 2.90 mtrs x 4.00 mtrs (existing height) (m / cm/ feet / inch)			
Number of Blocks Number of Storys	: One : N.A.			
 Spatial Organization Orientation Plan Allocation of Spaces 	 Facing towards south. The <i>vimana</i> is square on plan. 5.20 mtrs (L) x 5.20 mtrs (W) 			
ARCHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections * Any Other (specify)	 Devoid of any decoration, except an existing projecting lion on the northern <i>raha</i>. Plain A four-armed standing Visnu image and a four-armed Ganesa are fixed on the frontal wall of the <i>vimana</i>. 			
10. Construction Technology				
Structural System Building Techniques Material of Construction	 Pidha vimana of impoverished Kalingan order. Ashlar masonry Khandolite stone & lime plaster			
11. Condition Assessment				
In General Good / Fair	: Fair			
Sign of Deterioration Serious Deterioration Danger of Disappearance				

In Brief (Attach extra sh	eet if necessary):
---------------------------	--------------------

The sanctum is submerged during rainy season due to the high water level of the adjoining river Vitarani.

12. Threats to	the Property				
	. ,	✓ Natural			
		✓ Negligence			
		Vandalism			
		Urban Pressures			
x x x x x x x	X X X X X X X X X X X	(
SECTION III: REFERENCES					
13. Reference Sources (published and unpublished textual details)					
1					
2.					
14. Photograp	ohs : 06 nos.				
		(attach list as in page 6, in case of multiple photographs)			
Photo Reference CAPTION	nce :				
45 A. dia /\/:	-l				
15. Audio / Vi	aeo	(related to rituals / performance / festivals etc.)			
		(related to fituals / performance / restivals etc.)			
Reference	:				
DESCRIPTION	N :				
16. Maps/Plans/Drawings					
17. Listers					
17. LISTEIS					
NAME:	Jaya Shankar Naik	NAME:			
18. Reviewers	S				
NAME: COMMENTS	Dr. S. Pradhan	NAME: COMMENTS:			