INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, <u>www.ignca.gov.in</u>

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR/JPR-29

1. Name	SECTION I : IDENTIFICATI	ON
Present	: Kali Temple, Trilocha Town, Dist. – Jajpur	anesvara Temple Complex, Jajpur
Past Other Name (if any):	:	
2. Location		
LONGITUDE 86 ⁰ 20' 24" E	LATITUDE 20 ⁰ 49' 44"	N ELEVATION 30 ft
Address	: Village (village code Post : Devidwar Tehsil: Jajpur Town State : Orissa	Complex, Trilochanapada Via: Devidwar
Approach	within the complex a stream Hamsarekha	nt of the Trilochanesvara temple and on the right bank of the dried a is situated on the left side of ad, at a distance of 1 km south of
3. Property Type		
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public buildings Residential building Engineering structure Bridge Tunnel Other engineering structure	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Cave	Other Structures Wall Gateway Pillar Others (specify): Note: It has a single pidha vimana of impoverished Kalingan order fronted by an open RCC mandapa. The presiding deity is an image of eighteen armed Chamunda and the temple is locally known as Na Hate Deulare Athara Hate Kali (eighteen armed Kali within 9 hand's height temple).

4. Property Use		
		ABANDONED / IN USE : In use
Present	:	Living temple that enshrines an eighteen-arm Chamunda image. Due to heavy costumes and dre
Past	:	the detail iconographical features could not be studie Worshipped.
5. Age (Source)		
PERIOD	:	Bhaumakara rule
YEARS	:	8 th / 9 th century A.D.
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	The present shine is recent construction and the original temple has no trace.
Destruction / Demolition	:	
6. Ownership / Level of Protectic	<u>n</u>	
		SINGLE /MULTIPLE : Multiple
Public : Archaeological Survey of	:	Protected Monument of Archaeological Survey of Ind
India / State Archaeology		
Department / Any Other (Please		
specify)		
Private	:	
Any other (Please specify)	:	Trilochanesvara Temple Trust Board under th presidentship of Amulya Ku. Mohanty
Name		
Address		Archaeological Survey of India, Bhubaneswar Circl
AUU1692	•	
Phone		153 VIP Area, Nayapalli, Bhubaneswar, Orissa
Phone	:	0674-2558170
7. Association		
• WITH EVENTS		
In History	:	
In Rituals	:	Kali Puja, Asokastami etc.
In Building Construction	:	
Any other (specify)	:	
WITH PERSONS		
Patron	:	Now under the care of Archaeological Survey of India
Architect / Engineer	:	
Any other (specify)	:	Trilochanesvara Temple Trust Board
8. Statement of Significance		
Architectural	:	✓ Architectural
Archaeological	:	ArchitecturalArchaeological
Architectural Archaeological Historical	:	 Archaeological
Architectural Archaeological	: : : : : : : : : : : : : : : : : : : :	

deity, the original temple can be dated to the 8^{th} / 9^{th} century AD. i. e. the Bhaumakara rule in Orissa.

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features _____

 Context Urban / Rural Setting Surroundings 	:	* Drawings (Attach extra sheet if necessary) : No Rural setting	
ouriounungo		Stand in Isolation Integral part of a Landscape / Complex Street / Complex :	
• Quantification Area Dimension (L x B x H)	:	8.20 mtrs x 3.00 mtrs x 5.00 mtrs (approximate height) (m / cm/ feet / inch	
Number of Blocks Number of Storys	:	Two NA	
• Spatial Organization Orientation Plan Allocation of Spaces	:	Facing towards north The <i>vimana</i> is square on plan whereas the RC0 <i>mandapa</i> is rectangular on plan. 8.20 mtrs x 3.00 mtrs in length and width respectively.	
ARCHITECTURAL STYLE			
Ornamentation Exteriors Interiors Movable Collections * Any Other (specify)		Plain Plain Nil The frontal wall of the <i>vimana has</i> two independen images of Chamunda in seated posture but the left on is four-armed measuring 1.08 mtrs x 0.70 mtrs x 0.2 mtrs while the right one is eight-armed measuring 0.6 mtrs x 0.44 mtrs x 0.20 mtrs in dimension.	
10. Construction Technology			
Structural System Building Techniques Material of Construction		<i>Pidha vimana</i> of impoverished <i>Kalingan</i> order. Ashlar masonry Sandstone are used both for the temple and the sculptures.	
11. Condition Assessment			
In General Good / Fair	:	Fair	
 Sign of Deterioration Serious Deterioration Danger of Disappearance 			

In Brief (Attach extra sheet if necessary):

Regularl application of vermilion and oil conceals the artistic beauty of the image.

12. Threats to the Property

✓ Natural
 Negligence
 Vandalism
 Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

1. S.K. Rath, 2005, The Cult of Chamunda, In G. Mohanty et al. (eds.), *Cultural Heritage of Jajpur*, Bhubaneswar.

2.

14. Photographs: 09 nos.

	(attach list as in page 6, in case of multiple photographs)
Photo Reference CAPTION	: :
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	:
DESCRIPTION	:
16. Maps/Plans/Drawings	

17.	Listers

NAME : A. R. Sahoo NAME :

18. Reviewers

NAME : Dr. S. Pradhan COMMENTS

NAME : COMMENTS :