

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, <u>www.ignca.gov.in</u>

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR/JPR-37

SECTION I : IDENTIFICATION						
1. Name						
Present	: Kapilesvara Mahadeva Dist Jajpur	Temple, Kapilesvara,				
Past Other Name (if any):	:					
2. Location						
LONGITUDE 86 ⁰ 20' 26" E	LATITUDE 20 ⁰ 49' 10" N	ELEVATION 38 ft				
Address Approach	Binjharpur road, bran	Kapilesvara Via: Devidwar District: Jajpur PIN: 755007 d on the right side of Jajpur- ching at a distance of ½ km owk towards west and 4 kms n.				
3. Property Type						
Buildings Palace Fort Citadel Govt. building Railway station Defence building	✔ Temple ✓ Mosque ✓ Minar ✓ Church ✓ Monastery ✓ Stupa	Other Structures Wall Gateway Pillar Others (specify):				
Industrial building Other public buildings Residential building Engineering structure Bridge Tunnel Other engineering structure	 Tomb, Mausoleum Open space and related structures Public square Park or garden 	Note: The temple has a <i>rekha vimana</i> and a recently added R.C.C. <i>mandapa</i> in front of the temple.				

	Baolis, Wel	
	Tank	
	Cave	

		ABANDONED / IN USE : In use
Present		Living temple, the presiding deity is a Sivalinga w a circular <i>yonipitha</i> . However, the sanctum submerged throughout the year due to high water t
		in the adjoining tank.
Past	:	Worshipped
5. Age (Source)		
PERIOD		Somavamsi rule.
YEARS		10 ^{th-} 11 th centuries A.D.
Precise date of Construction	:	
Completion	:	
Subsequent changes	÷	
Destruction / Demolition	:	
6. Ownership / Level of Protectic	on	
· · · · · · · · · · · · · · · · · · ·		SINGLE /MULTIPLE : Multiple
Public : Archaeological Survey of	:	
India / State Archaeology		
Department / Any Other (Please		
specify)		
Private	:	
Any other (Please specify)	:	People of Kapilesvara village under the priestship Ravi Narayana Padhi.
Name	:	,
Address	:	AT- Kapilesvara, PO- Mirchandpur, Via- Devid
		Dist. – Jajpur, Pin – 755007, Orissa
Phone	:	
7. Association		
• WITH EVENTS		
In History	:	
In Rituals	:	Sivaratri, Sankranti, etc are observed here.
In Building Construction	:	
Any other (specify)	:	<i>Mundana, thread ceremony, kirtana,</i> etc are performere.
WITH PERSONS		
Patron		Villagers of Kapilesvara.
Architect / Engineer	:	
Any other (specify)	;	
	•	
8. Statement of Significance		
Architectural	÷	 Architectural
	-	
Archaeological	:	Delisious
Historical Religious	:	Religious

entrance lintel, the temple can be dated to the 10th-11th centuries AD. SECTION II: DESCRIPTION 9. Physical Description and Decorative Features * Drawings (Attach extra sheet if necessary): No Context • Urban / Rural Setting Rural setting Surroundings Stand in Isolation Integral part of a Landscape / Complex Street / Complex : Quantification Area Dimension (L x B x H) : 8.80 mtrs x 5.20 mtrs x 7.65 mtrs (existing height) $(\mathbf{m} / \mathbf{cm} / \mathbf{feet} / \mathbf{inch})$ Number of Blocks Two N.A. Number of Storys Spatial Organization • Orientation Facing towards west. Plan Consists of a square vimana and a square RCC : mandapa. 8.80 mtrs (L) x 5.20 mtrs (W) Allocation of Spaces ARCHITECTURAL STYLE Ornamentation Devoid of any decoration, except a projecting lion on Exteriors the eastern and northern raha and a miniature rekha mundi over the projecting eave of the entrance. Interiors Plain Movable Collections A broken bust part of a four-armed Siva canopied by a seven hooded snake. The upper right hand holds a trident, a *dambru* in the upper left and the rest two hands are broken. Besides, votive nandi images (04 nos.) and a projecting lion are found. The temple is pancharatha on plan and the bada is * Any Other (specify) completely buried in the ground. **10. Construction Technology** Structural System Rekha vimana of Kalingan order. : Building Techniques : Ashlar masonry with mortar. Material Of Construction Stone and lime mortar are used for the construction of : the temple and now the entire temple is thickly plastered and white washed. **11. Condition Assessment** In General Good / Fair • Fair

:

On architectural ground and the remains of the

✓ Sign of Deterioration

Any other (specify)

`

Serious Deterioration
Danger of Disappearance

In Brief (Attach extra sheet if necessary):

The sanctum is buried throughout the year due to high water table in the adjoining tank which is weakening the structure.

12. Threats to the Property



SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

1. K. C. Biswal, 2005, Monuments In and Around Jajpur, In G. Mohanty et al. (eds.) *Cultural Heritage of Jajpur*, Bhubaneswar.

14. Photograp	ohs: 11 nos.					
_ .			(attach list as in page 6, in case of multiple photographs)			
Photo Referen	nce	:				
15. Audio / Vi	deo					
			(related to rituals / performance / festivals etc.)			
Reference DESCRIPTION	N	:				
16. Maps/Plans/Drawings						
17. Listers						
NAME :	Jaya Shankar Naik		NAME :			
18. Reviewers						

NAME : Dr. S. Pradhan **COMMENTS**

NAME : COMMENTS :