

## INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, <a href="www.ignca.gov.in">www.ignca.gov.in</a>

## **Documentation format for Archaeological / Heritage Sites / Monuments**

Serial No.: OR/JPR-73

1. Name	SECTION I: IDENTIFICATION
Present	: Kharakhia Varaha Temple, Varahanatha Temple Complex, Jajpur Town, Dist Jajpur
Past Other Name (if any):	: :
2. Location	
<b>LONGITUDE</b> 86 <sup>0</sup> 20' 08" E	<b>LATITUDE</b> 20 <sup>0</sup> 51'30" N <b>ELEVATION</b> 15 ft
Address	: <b>Village (village code)</b> Varahanatha Temple Complex, Varahanatha
	Post : Jajpur Town Tehsil: Jajpur Town State : Orissa Via: Jajpur Town District: Jajpur PIN: 755001
Approach	: The temple is located south of the Varahanatha temple within the complex, which is in an island with picturesque surroundings, where the river Vaitarani has been branched off on both sides. It is about 1 km from Jajpur town bus stand and opposite to the Dasasvamedhaghata.
3. Property Type	
Desil diamen	Dell'uriano atmostrare
<b>Buildings</b> Palace	Religious structures Other Structures  ✓ Temple Wall
Fort	✓ Temple Wall Mosque Gateway
Citadel	Miner Pillar
Govt. building	Church Others (specify):
Railway station	Monastery Cities (specify).
Defence building	Sputa
Industrial building	Tomb, Mausoleum
Other public buildings	Note:
Residential building	
Tresidential ballaring	It is a <i>pidha</i> temple o impoverished <i>Kalingan</i> order.
Engineering structure	Open space and related
	structures
Bridge	Public square
Tunnel	Park or garden
Other engineering structure	Graveyard
	Baolis, Well
	Tank

Cave
Ouv

## 4. Property Use

ABANDONED / IN USE: In use

Present : Living temple and the presiding deity is Varaha, an

incarnation of lord Visnu. The enshrined deity is the representative of lord Varaha of the main temple, when the main temple is closed, the rituals are performed

here.

Past : Worshipped.

5. Age (Source)

**PERIOD** : Suryavamsi Gajapati rule **YEARS** : 15<sup>th</sup> /16<sup>th</sup> century A.D.

Precise date of Construction : ---Completion : ---

Subsequent changes : It was renovated and repaired by Maratha ruler

Raghuji Bhonsle.

Destruction / Demolition : ---

6. Ownership / Level of Protection

**SINGLE / MULTIPLE**: Multiple

Public: Archaeological Survey of : Protected Monument of Archaeological Survey of India

India / State Archaeology Department / Any Other (Please

specify)

Private : ---

Any other (Please specify) : Endowment Department, Government of Orissa

Name

Address : Archaeological Survey of India, Bhubaneswar Circle,

153 VIP Area, Nayapalli, Bhubaneswar, Orissa

**Phone** : 0674-2558170

7. Association

WITH EVENTS

In History : ---

In Rituals : Chandana Yatra, Sri Gundicha, Sunia, Kartika

Purnima, Varaha Janma, Bakul Amabasya, & Baruni

Yatra, etc.

In Building Construction : ---Any other (specify) : ---

WITH PERSONS

Patron : Now care is taken by Archaeological Survey of India.

Architect / Engineer : --

Any other (specify) : Endowment Department, Government of Orissa

8. Statement of Significance

Architectural : ✓ Architectural

Archaeological Historical Religious Any other (specify)	<ul> <li>:         Religious     </li> <li>: On the basis of the iconography of the enshrined image, the original temple can be dated to the Suryavamsi Gajapati rule i.e 15<sup>th</sup> /16<sup>th</sup> century A.D. although the present temple is a modern construction.</li> </ul>				
SECTION II: DESCRIPTION  9. Physical Description and Decorative Features					
Context Urban / Rural Setting Surroundings	* Drawings (Attach extra sheet if necessary) : No : Rural setting				
ourroundings	Stand in Isolation Integral part of a Landscape / Complex Street / Complex :				
Quantification					
Area Dimension (L x B x H)	: 5.25 mtrs x 5.15 mtrs x 5.00 mtrs (approximate height) (m / cm/ feet / inch)				
Number of Blocks Number of Storys	: Two : N.A.				
<ul> <li>Spatial Organization         Orientation         Plan     </li> <li>Allocation of Spaces</li> </ul>	<ul> <li>: Facing towards north.</li> <li>: The <i>vimana</i> is square on plan whereas the frontal porch is rectangular on plan.</li> </ul>				
ARCHITECTURAL STYLE  Ornamentation Exteriors Interiors Movable Collections * Any Other (specify)  10. Construction Technology	<ul><li>Plain</li><li>Plain</li><li>Three images of Varaha and an image of Laxmi.</li><li></li></ul>				
Structural System	: Pidha vimana and nidha order shallow frontal norch of				
Structural System  Building Techniques  Material of Construction	<ul> <li>Pidha vimana and pidha order shallow frontal porch of impoverished Kalingan order.</li> <li>English bond technique.</li> <li>Bricks and cement mortar.</li> </ul>				
11. Condition Assessment					
In General Good / Fair	: Good				
Sign of Deterioration Serious Deterioration Danger of Disappearance					

The temple is i	n a good state of p	reserva	ation.
12. Threats to		· !	Natural Negligence Vandalism Urban Pressures x x x x x x x x x x x x x x x x x x x
	<u>s</u>	ECTIO	ON III: REFERENCES
13. Reference	Sources (publishe	ed and	unpublished textual details)
1 2.			
14. Photograp	hs: 11 nos.		
		(	attach list as in page 6, in case of multiple photographs
Photo Referer CAPTION	ice	: :	
15. Audio / Vid	deo		
			(related to rituals / performance / festivals etc.
Reference DESCRIPTION	ı	: :	
16. Maps/Plan	s/Drawings		
17. Listers			
NAME :	B. B. Satpathy		NAME:
18. Reviewers			
NAME: COMMENTS	Dr. S. Pradhan		NAME: COMMENTS:

In Brief (Attach extra sheet if necessary):