

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR/JPR - 09

SECTION I: IDENTIFICATION 1. Name Muktesvara Siva Temple, Jagannath Temple Complex, Present Jajpur Town, Dist. - Jajpur **Past** Other Name (if any): 2. Location **LONGITUDE** 86° 20' 12" E 20⁰ 51' 19" N LATITUDE **ELEVATION** 24 ft **Address** Village (village code) Jagannath Temple Complex, Dasasvamedha Ghat, Jajpur Town Via: Jaipur Town Post: Badabazar **Tehsil:** Jajpur Town **District:** Jaipur State: Orissa **PIN:** 755001 Approach The temple, on the north-west corner of the Jagannath temple complex at Dasasvamedhaghata is situated at a distance of 50 mtrs from the right bank of the river Vaitarani and about one km from Jajpur bus stand. 3. Property Type **Buildings** Religious structures Other Structures Palace Temple Wall Fort Mosque Gateway Citadel Minar Pillar Govt. building Church Others (specify): Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Note: Residential building The temple has a rekha vimana of Kalingan order. Engineering structure Open space and related structures Bridge Public square Park or garden Tunnel Other engineering structure Graveyard Baolis, Well Tank Cave

		ABANDONED / IN USE: In use
Present		Living temple that enshrines a Sivalinga within a circular <i>yonipitha</i> made of khandolite stone.
Past	:	Worshipped.
5. Age (Source)		
PERIOD		Ganga rule
YEARS		14 th century A.D.
Precise date of Construction		
Completion	:	
Subsequent changes	:	Renovated and repaired by the Marathas ruler.
Destruction / Demolition	:	
6. Ownership / Level of Protection	on	
		SINGLE /MULTIPLE : Single
Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please		Protected Monument of Archaeological Survey of India
specify) Private		
	:	
Any other (Please specify) Name		Archaeological Survey of India, Bhubaneswar Circle,
Address		153 VIP Area, Nayapalli, Bhubaneswar, Orissa
Phone	:	0674-2558170
7. Association		
WITH EVENTS		
In History	:	
In Rituals		Sivaratri, Kartika Purnima, etc are observed here.
In Building Construction		
Any other (specify)		
WITH PERSONS		
Patron	:	Now under the care of Archaeological Survey of India.
Architect / Engineer		
Any other (specify)	:	
8. Statement of Significance		
Architectural	:	Architectural
Archaeological		✓ Archaeological
	•	/ worked diagram
Historical Religious	:	✓ Religious

On the basis of architectural features, the temple is assigned to the 14th century AD. But the images kept inside the temple are of different period. The four-armed Visnu image is of Bhaumakara period i.e 8th/9th century AD, Parvati of Ganga period i.e. 14th century AD and the other two images such as Siva and Visnu are of later period.

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

Context
 Urban / Rural Setting

Surroundings

* Drawings (Attach extra sheet if necessary): No Urban setting

Stand in Isolation

Integral part of a Landscape /

Complex

Street / Complex:

Quantification

Area Dimension (L x B x H) : 5.70 mtrs x 5.10 mtrs x 8.00 mtrs (approximate height)

(m / cm/ feet / inch)

Number of Blocks : One Number of Storys : ---

Spatial Organization

Orientation : Facing towards east Plan : Square on plan.

Allocation of Spaces : 72.60 mtrs (L) x 42.60 mtrs (B)

ARCHITECTURAL STYLE

Ornamentation

Exteriors : Plain, except udyotasimha on each raha, dopichha

simhas & deulacharinis over the beki, amorous couple and a stucco figurine of tiger. The parsvadevata niche

is represented as miniature pidha shrine.

Interiors : Plain

Movable Collections : Image of four-armed Visnu, four-armed Siva and four-

armed Parvati and numbers of nandis.

* Any Other (specify) : The temple is pancharatha on plan and panchanga

bada in elevation.

10. Construction Technology

Structural System : Rekha vimana of impoverished Kalingan order.

Building Techniques : Ashlar masonry **Material of Construction** : Khandolite stone

11. Condition Assessment

In General Good / Fair : Fair

Sign of Deterioration

Serious Deterioration Danger of Disappearance					
In Brief (Attach extra sheet if necessary): Water stagnates in the sanctum during rainy season.					

12. Threats to the Property V					
13. Reference Sources (published and unpublished textual details)					
2. K. C. Bisv Heritage	val, 2005, Monumen o <i>f Jajpur</i> , Bhubanesv	eology in Orissa, Vol. – II, Delhi. ts In and Around Jajpur, in G. Mohanty et al. (eds), <i>Cultural</i> var			
14. Photograp	ohs: 17nos.	(attach list as in page 6, in case of multiple photographs)			
Photo Reference CAPTION	nce	:			
15. Audio / Vi	deo				
		(related to rituals / performance / festivals etc.)			
Reference DESCRIPTION	N	: :			
16. Maps/Plans/Drawings					
17. Listers					
17. LISTEIS					
NAME:	A. R. Sahoo	NAME:			
18. Reviewers					
NAME: COMMENTS	Dr. S. Pradhan	NAME: COMMENTS:			