

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR/JPR-61

SECTION I: IDENTIFICATION			
1. Name			
Present	: Parvati Temple, Siddhesvara, Dist	Siddhesvara Temple Complex, . – Jajpur	
Past Other Name (if any):	: :		
2. Location			
LONGITUDE 86 ⁰ 22' 53" E	LATITUDE 20 ⁰ 51' 4	43" N ELEVATION 33 ft	
Address	: Village (village con Post : Rambag Tehsil: Jajpur To State : Orissa	Via: Rambag	
Approach 3. Property Type	Siddhesvara and s Vaitarani. It can Jajpur-Mangalpur	eated on the west of the main shrine situated on the right bank of the river be approached on the left side of road, branching at a distance of 2.5 reimuhan chowk. It is about 6 kms	
Buildings	Religious structures	Other Structures	
Palace	Temple	Wall	
Fort	Mosque	Gateway	
Citadel	Minar	Pillar	
Govt. building	Church	Others (specify)	
Railway station	Monastery		
Defence building	Stupa		
Industrial building	Tomb, Mausoleum		
Other public buildings			
Residential building			
Engineering structure	Open space and related structures	Note: The temple has a <i>rekha</i>	
Bridge	Public square	vimana of Kalingan order.	
Tunnel	Park or garden	3	
Other engineering structure	Graveyard		
	Baolis, Well		
	Tank		
	Cave		

4. Property Use

ABANDONED / IN USE: In Use

Present : Living temple, the presiding deity is an eight-armed

Chamunda image seated in lalitasana over a prostrate demon which is worshipped as Parvati by the local

people.

Past : Worshipped

5. Age (Source)

PERIOD : Ganga rule **YEARS** : 14th century A.D.

Precise date of Construction : --Completion : ---

Subsequent changes: The temple is entirely plastered in later period.

Destruction / Demolition : ---

6. Ownership / Level of Protection

SINGLE /MULTIPLE: Multiple

Public: Archaeological Survey of : Endowment Department, Government of Orissa

India / State Archaeology Department / Any Other (Please

specify)

Private : --

Any other (Please specify) : Siddhesvara Temple Managing Trust Board

Name : -

Address : AT-Siddhesvara, PO.- Rambag, Dist.- Jajpur, Orissa

Phone : ---

7. Association

WITH EVENTS

In History : Ganga dynasty

In Rituals : Durga puja , Kali puja, etc.

In Building Construction : ---

Any other (specify) : Marriage is performed here.

WITH PERSONS

Patron : Presently under the care of Endowment Department,

Government of Orissa

Architect / Engineer : ---

Any other (specify) : Siddhesvara Temple Managing Trust Board

8. Statement of Significance

Architectural

Archaeological

✓ Archaeological

✓ Archaeological

Historical

Religious

✓ Religious

Any other (specify)	:	On architectural features, the temple can be dated to the last decade of the 14 th century AD. i.e. the Ganga rule in Orissa.		
SECTION II: DESCRIPTION				
9. Physical Description and Decorative Features				
 Context Urban / Rural Setting Surroundings 	:	* Drawings (Attach extra sheet if necessary) : No Rural setting		
J		Stand in Isolation Integral part of a Landscape / Complex Street / Complex :		
• Quantification Area Dimension (L x B x H)	:	3.75 mtrs x 3.75 mtrs x6.15 mtrs (approximate height) (m / cm/ feet / inch)		
Number of Blocks Number of Storys	:	One N.A.		
Spatial Organization				
Orientation Plan Allocation of Spaces	: : :	Facing towards south. The <i>vimana</i> is square on plan. 8.00 mtrs (L) x 6.00 mtrs (W)		
ARCHITECTURAL STYLE • Ornamentation				
Exteriors	:	The frontal <i>raha</i> is decorated with the <i>mastaka</i> of a temple including an <i>amlakasila</i> and a <i>chakra</i> . The eastern <i>raha</i> has a projecting lion. The lower <i>jangha</i> of the western wall has a <i>nabagraha</i> slab and a Gaja-laxmi image.		
Interiors	:	Plain		
Movable Collections	:	An image of standing Ganesa is kept in the right corner of the entrance.		
* Any Other (specify)	:	The temple is <i>triratha</i> on plan and <i>panchangabada</i> in elevation.		
10. Construction Technology	1			
Structural System Building Techniques Material of Construction	:	Rekha vimana of Kalingan order. Ashlar masonry. Khandolite is used for the construction of the temple and presently the entire surface is thickly plastered and white washed.		
		and while washed.		
11. Condition Assessment				
In General Good / Fair Sign of Deterioration Serious Deterioration Danger of Disappearance	:	Good		

12. Threats t	o the Property	
		✓ Natural
		Negligence
		Vandalism
		Urban Pressures
x x x x	x x x x x x x x x x	x x x x x x x x x x x x x x x x x x x
	<u>s</u>	ECTION III: REFERENCES
13. Reference	Sources (publishe	ed and unpublished textual details)
1		
2		
14. Photograp	hs: 15 nos.	
		(attach list as in page 6, in case of multiple photographs
Photo Refere	nce	:
CAPTION		:
15. Audio / Vi	deo	
		(related to rituals / performance / festivals etc.
Reference		:
DESCRIPTION	N	:
16. Maps/Plan	s/Drawings	
4-11		
17. Listers		
NAME:	Binod Satpathy	NAME:
IAWINT .	Diriou Salpatily	NAME.
18.Reviewers		
NAME .	Dr S Dradhan	NAME .

COMMENTS:

In Brief (Attach extra sheet if necessary):
The temple is in a good state of preservation.

COMMENTS