INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

## Documentation format for Archaeological / Heritage Sites / Monuments

## Serial No.: OR/JPR-13

SECTION I : IDENTIFICATION				
1. Name				
Present Past Other Name (if any): 2. Location	<ul> <li>Pranayamesvara Siva T</li> <li>Dist. – Jajpur</li> <li></li> <li></li> </ul>	emple, Jajpur Town,		
<b>LONGITUDE</b> 86 <sup>0</sup> 20' 23" E	<b>LATITUDE</b> 20 <sup>0</sup> 49' 58" N	ELEVATION 43 ft		
Address	: Village (village code) Post : Devidwar Tehsil: Jajpur Town State : Orissa	Jajpur Town (Devidwar) Via: Devidwar District: Jajpur PIN: 755007		
Approach		t a distance of 100 mtrs east of Devidwar in Jajpur town. It is In bus stand.		
3. Property Type				
BuildingsPalaceFortCitadelGovt. buildingRailway stationDefence buildingIndustrial buildingOther public buildingsResidential building	Religious structures         Image: Church         Monastery         Stupa         Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify)		
Engineering structure Bridge Tunnel Other engineering structure	structures Public square Park or garden	<b>Note:</b> The temple exists up to its <i>bada</i> portion. It is one of the earliest temples of <i>Kalingan</i> style in Jajpur town.		

4. Property Use ABANDONED / IN USE : In use Present Living temple, the presiding deity is a Sivalinga of 1.10 2 mtrs high within a circular yonipitha made of black chlorite. Past Worshipped 2 5. Age (Source) Bhaumakara rule PERIOD 2 8<sup>th</sup> century A.D. YEARS 2 Precise date of Construction : \_\_\_\_ Completion 2 Subsequent changes The temple is not a protected monument, even though 5 the State Archaeology renovated this temple under X and XI Finance Commission Award. **Destruction / Demolition** 5 \_\_\_\_ 6. Ownership / Level of Protection SINGLE / MULTIPLE : Multiple **Public** : Archaeological Survey of : State Archaeology India ---Department / Any Other (Please specify) Private 2 Any other (Please specify) People of Devidwar : Name 5 AT /PO - Devidwar, , Dist- Jajpur, Pin-755007, Orissa Address : Phone 7. Association WITH EVENTS In History 2 In Rituals Sivaratri, Kartika Purnima, etc are observed here. 5 In Building Construction As per mythological view it is one of the Sivalinga : named Pranayamesvara within 108 Sivalingas of Virajakshetra Any other (specify) 2 \_\_\_\_ • WITH PERSONS Now it is looked after by the people of Devidwar. Patron 2 Architect / Engineer 2 \_\_\_\_ Any other (specify) : \_\_\_\_ 8. Statement of Significance Architectural Architectural  $\checkmark$ ✓ Archaeological Archaeological Historical Religious

Any other (specify) : On the basis of detached sculptures, the temple can be dated to the 8<sup>th</sup> century A.D. i.e. the Bhaumakara rule in Orissa.

## **SECTION II: DESCRIPTION**

<ul> <li>Context</li> <li>Urban / Rural Setting</li> <li>Surroundings</li> </ul>	* <b>Drawings (</b> Attach extra sheet if necessary): No : Urban setting	
Surroundings	Stand in Isolation Integral part of a Landscape/ Stand in isolation Street / Complex :	
Quantification Area Dimension (L x B x D)	4.80 mtrs x 4.80 mtrs x 5.00 mtrs (existing height) (m / cm/ feet / inc One N.A.	
Number of Blocks Number of Storys		
Spatial Organization		
Orientation Plan	<ul> <li>Facing towards east.</li> <li>Consists of a square <i>vimana</i> that stands over a logista.</li> </ul>	
Allocation of Spaces	4.80 mtrs x 4.80 mtrs in length and width respectively.	
ARCHITECTURAL STYLE  Ornamentation		
Exteriors Interiors	<ul> <li>Devoid of decorations</li> <li>A two- armed Surya image is fixed in the rear wall of th vimana.</li> </ul>	
Movable Collections	Images of Ganesa, Surya, defaced female deity, number of nandis and a large number of architectural fragments. The temple is <i>triratha</i> on plan and has plain <i>bada</i> ir elevation.	
* Any Other (specify)		
10. Construction Technology		
Structural System	As the temple exists upto the <i>bada</i> portion, the order o the temple could not be ascertained.	
Building Techniques Material of Construction	: Ashlar masonry : Khandolite stone	
11. Condition Assessment		
In General	Good / Fair : Fair	
<ul> <li>✓ Sign of Deterioration</li> <li>✓ Serious Deterioration</li> <li>✓ Danger of Disappearance</li> </ul>		

Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Growth of vegetations, lichen and moss are found on the walls of the temple and crack is noticed in the *yonipitha* 

## 12. Threats to the Property

x	x x x x x x x x x x x x x x x x x x x	<ul> <li>Natural</li> <li>Negligence</li> <li>Vandalism</li> <li>Urban Pressures</li> <li>x x x x x x x x x x x x x x x x x x x</li></ul>		
SECTION III: REFERENCES				
13. Reference Sources (published and unpublished textual details)				
1 2.				
14. Photograp	ohs: 25 nos.			
		(attach list as in page 6, in case of multiple photographs)		
Photo Referen CAPTION	ice :			
15. Audio / Vi	deo			
		(related to rituals / performance / festivals etc.)		
Reference DESCRIPTIO	N :			
16. Maps/Plar	16. Maps/Plans/Drawings			
17. Listers				
NAME :	Jaya Shankar Naik	NAME :		
18. Reviewers				
NAME : COMMENTS	Dr. S. Pradhan	NAME : COMMENTS :		