

## **INDIRA GANDHI NATIONAL CENTROE FOR THE ARTS**

Janpath, New Delhi -110 001, www.ignca.gov.in

## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR/JPR- 17

SECTION I : IDENTIFICATION			
1. Name			
Present  Past Other Name (if any):  2. Location	<ul> <li>Sahasralinga Shrine-I, Viraja Temple Complex, Jajpu Town, Dist. – Jajpur</li> <li></li> <li>Deva Sabha</li> </ul>		
<b>LONGITUDE</b> 86 <sup>0</sup> 20' 17" E	LATITUDE 20 <sup>0</sup> 50' 01" N ELEVATION 35 ft		
Address	: Village (village code) Devidwar Post : Devidwar Tehsil: Jajpur Town State : Orissa  Devidwar Via: Devidwar District: Jajpur PIN: 755007		
Approach	: The Sahasralinga shrine-I is located on the north eastern corner of Viraja temple complex a Devidwar. It is situated on the left side of Jajpur Binjharpur road at a distance of 2.5 kms from Jajpur bus stand.		
3. Property Type			
Buildings  Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures  Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum  Other Structures Wall Gateway Pillar Others (specify)—Shrine		
Engineering structure  Bridge Tunnel Other engineering structure	Open space and related structures  Public square Park or garden Graveyard Baolis, Well Tank Cave  Note: It is a recently built G.I. shee roof shrine that houses 54 Sivalingas made of khandolite sandstone and chlorite stone.		

4. Property Use ABANDONED / IN USE: In use It is a living shrine and the presiding deities are Siva Present lingas (54 in no). **Past** Worshipped 5. Age (Source) Somavamsi rule PERIOD 10<sup>th</sup> /11<sup>th</sup> century AD YEARS **Precise date of Construction** Completion Subsequent changes ---**Destruction / Demolition** 6. Ownership / Level of Protection SINGLE /MULTIPLE : Multiple **Public**: Archaeological Survey of : Endowment Department, Government of Orissa. India State Archaeology Department / Any Other (Please specify) Private Any other (Please specify) Maa Viraja TempleTrust Board Name Vidyadhara Pani, the chief priest AT/PO. - Devidwar, Dist - Jajpur, Orissa Address Phone 7. Association WITH EVENTS In History In Rituals Sivaratri In Building Construction Any other (specify) WITH PERSONS Now under the care of Viraja TempleTrust Board. Patron Architect / Engineer Any other (specify) **Endowment Department, Government of Orissa** 8. Statement of Significance Architectural :

Archaeological : ✓ Archaeological
Historical :
Religious : ✓ Religious
Any other (specify) : On the basis of circumstantial evidence the lingas can be

dated to the Somavamsi period.

## ${\bf SECTION~II:\_DESCRIPTION}$

9. Physical Description and Decora	tive Features
Context Urban / Rural Setting Surroundings	* <b>Drawings (</b> Attach extra sheet if necessary) No Urban setting
Carroundings	Stand in Isolation Integral part of a Landscape / Complex Street / Complex :
Quantification  Area Dimension ( L x B x H) :  Number of Blocks Number of Storys :	10.50 mtrs x 6.00 mtrs x 4.00 mtrs (m / cm/ feet / inch) One N.A
• Spatial Organization Orientation : Plan : Allocation of Spaces :	Facing towards west Rectangular on plan. 10.50 mtrs x 6.00 mtrs in length and width respectively.
ARCHITECTURAL STYLE  • Ornamentation  Exteriors : Interiors : Movable Collections :   * Any Other (specify) :   10. Construction Technology	N.A N.A Fragment of a pillar base which decorated with dancing <i>nayikas</i> and <i>kirtimukha</i> designs. Out of 54 Sivalingas, 24 are represented as Sahasralingas and the rest are cylindrical lingas except one which is a votive temple depicting a Sivalinga in the niche of the temple. The <i>yonipithas</i> of the lingas are recently made with cement.
Structural System : Building Techniques : Material of Construction :  11. Condition Assessment	Monolithic Each <i>lingam</i> hewed out of a boulder. Khandolite, Sandstone and Chlorite stone.
In General Good / Fair :  Sign of Deterioration Serious Deterioration Danger of Disappearance	Good.

In Brief (Attach extra sheet if necessary):

The Sivalingas are in good state of preservation.

12. Threats to	the Property	
	Ţ-	✓ Natural
		Negligence
	,	Vandalism
	L	Urban Pressures
x x x x x x x		
	SEC	TION III: REFERENCES
13. Reference	Sources (published a	and unpublished textual details)
<i>Jajpur,</i> Bl	da, 2005, Saivite Mon nubaneswar.	uments, In G. Mohanty et al. (eds.) Cultural Heritage o
2.		
14. Photograp	ohs: 14 nos	
		(attach list as in page 6, in case of multiple photograph
Photo Refere	nce :	
CAPTION	:	
15. Audio / Vi	deo	
		(related to rituals / performance / festivals etc
Reference	:	
DESCRIPTION	<b>N</b> :	
16. Maps/Plar	ns/Drawings	
10. Map3/1 Idi	13/Diawings	
17. Listers		
	A.D. O. I.	
NAME :	A.R. Sahoo	NAME:
18. Reviewers	5	
NAME:	Dr. S. Pradhan	NAME: