

INDIRA GANDHI NATIONAL CENTR0E FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR/JPR-18

SECTION I: IDENTIFICATION				
1. Name				
Present Past	: Sahasralinga Shrine–II Town, Dist. – Jajpur :	, Viraja Temple Complex, Jajpur		
Other Name (if any):	: Deva Sabha			
2. Location				
LONGITUDE 86 ⁰ 20' 17" E	LATITUDE 20 ⁰ 50' 01" N	ELEVATION 35 ft		
Address	: Village (village code) Post : Devidwar Tehsil: Jajpur Town State : Orissa	Devidwar Via: Devidwar District: Jajpur PIN: 755007		
Approach	eastern corner of Devidwar. It is situat	rine-II is located on the north- Viraja temple complex at ted on the left side of Jajpur- a distance of 2.5 kms from		
3. Property Type				
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify) - Shrine		
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Cave	Note: It is a recently built GI. sheet roof shrine that houses 37 Sivalingas and five votive temples. Stylistically the votive temples can be dated to the Somavamsi period.		

4. Property Use

ABANDONED / IN USE: In use

Present : It is a living shrine that enshrines 37 Sivalingas and 5

votive temples out of which four are carved with Uma -

Mahesvaramurty.

Past : Worshipped

5. Age (Source)

PERIOD : Somavamsi rule
YEARS : 10th /11th century AD

Precise date of Construction : --

Completion :

Subsequent changes : The lingas are donated by devotees but the votive

temples are collected from the temple premises.

Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE / MULTIPLE : Multiple

Public: Archaeological Survey of : Endowment Department, Government of Orissa.

India / State Archaeology Department / Any Other (Please

specify)

Private

Any other (Please specify) : Maa Viraja Temple Trust Board : Vidyadhara Pani, the chief priest. Address : At/PO – Devidwar, Dist – Jajpur, Orissa

Phone

7. Association

WITH EVENTS

In History : ---

In Rituals : Sivaratri, Kartika Purnima etc. are observed here.

In Building Construction : --Any other (specify) : ---

WITH PERSONS

Patron : Originally by the Somavamsis but now under the care

of Viraja Temple Trust Board.

(Chief priest.) Architect / :

Engineer

Any other (specify) : Endowment Department, Government of Orissa

8. Statement of Significance

Architectural :

Archaeological Historical Religious Any other (specify)	 ∴ Archaeological ∴ Religious ∴ On the basis of circumstantial evidence and the architectural features of the votive temples these can be dated to the 10th/11th century A.D.
	SECTION II:_DESCRIPTION
9. Physical Description	and Decorative Features
 Context Urban / Rural Setting Surroundings 	* Drawings (Attach extra sheet if necessary) No Urban setting
·	Stand in Isolation Integral part of a Landscape / Street / Complex Complex:
 Quantification 	
Area Dimension (LxBx	,
Number of Blocks Number of Storys	(m / cm/ feet / inch) : One : N.A
Spatial Organiza	tion
Orientation Plan Allocation of Spaces	 Facing towards east Rectangular on plan. 10.20 mtrs x 5.80 mtrs in length and width respectively.
A DOLUTEOTUDAL OTV	_
• Ornamentation	<u>.E</u>
Exteriors	: N.A
Interiors Movable Collections	: N.A
* Any Other (specify)	Votive temples (05 nos.), Nandi
10. Construction Techn	ology
Structural System	: The votive temples and the <i>lingam</i> inside are
Building Techniques	monolithic.Lingam and votive temples are hewed out of a single boulder
Material of Construction	
11. Condition Assessm	ent
In General Good / F	air : Good.
Sign of Deterioration Serious Deterioration	

Danger o	of Disappearance	
In Brief (Attac	ch extra sheet if neces	ssary):
The Sivalinga	s and the votive temple	s are in a good state of preservation.
12. Threats to	the Property	
x x x x x x x	× × × × × × × × × ×	Natural Negligence Vandalism Urban Pressures
		TION III: REFERENCES
13. Reference	e Sources (published a	nd unpublished textual details)
	da, 2005, Saivite Mon hubaneswar.	uments, In G. Mohanty et al. (eds.) Cultural Heritage of
14. Photogra	phs: 10 nos	
Photo Refere CAPTION	:	(attach list as in page 6, in case of multiple photographs)
15. Audio / Vi	ldeo	(related to rituals / performance / festivals etc.)
Reference DESCRIPTIO 16. Maps/Plai		
	gc	
17. Listers		
NAME:	A.R. Sahoo	NAME:
18. Reviewers	s	
NAME: COMMENTS	Dr. S. Pradhan	NAME: COMMENTS: