

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Serial No.: OR/JPR-11

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

1. Name	SECTION I: IDENTIFICATION	N
Present Past Other Name (if any):	: Siddha Ganesa Templ : :	e, Jajpur Town, Dist. – Jajpur
2. Location		
LONGITUDE 86 ⁰ 20' 12" E	LATITUDE 20 ⁰ 51' 19" N	ELEVATION 20 ft
Address	: Village (village code) Post : Badabazar Tehsil: Jajpur Town State : Orissa	Dasasvamedhaghata, Jajpur Town Via: Jajpur Town District: Jajpur PIN: 755001
Approach	Vaitarani at Dasasvan northern compound complex and Saptam	d on the right bank of the river nedhaghata and in between the wall of Jagannatha temple atrika shrine. It is situated at a as from Jajpur bus stand.
3. Property Type		
Buildings Palace Fort Citadel Govt. building Railway station Defence building	Religious structures Temple Mosque Miner Church Monastery Sputa	Other Structures Wall Gateway Pillar Others (specify):
Industrial building Other public buildings Residential building	Tomb, Mausoleum	Note: The temple has a rekha vimana
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Cave	and a pidha jagamohana of impoverished Kalingan order. The presiding deity is a colossatimage of Ganesa. A number of Brahmanical images and a Jaina Tirthankara image of Shant natha are kept in the jagamohana.

4. Property Use	
	ABANDONED / IN USE: In use
Present Past	Living temple and the presiding deity is a four-armed colossal image of seated Ganesa.Worshipped.
E Ara (Cauras)	• •
5. Age (Source)	
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition	 Somavamsi rule 10th /11th century A.D. The temple was renovated during the Maratha rule in Orissa.
6. Ownership / Level of Protection	on
	SINGLE /MULTIPLE : Multiple
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please	: Endowment Department, Government of Orissa.
specify) Private Any other (Please specify) Name	: : Temple Committee
Address Phone	: :
7. Association	
WITH EVENTS In History In Rituals In Building Construction	: : Ganesa puja is performed here. :
Any other (specify) WITH PERSONS Patron	:: Originally the Somavamsis but now under the care of Endowment Department, Government of Orissa.
Architect / Engineer Any other (specify)	: : Temple Committee
8. Statement of Significance	
Architectural Archaeological Historical Religious Any other (specify)	 ∴ Architectural ∴ Archaeological ∴ Religious ∴ On the basis of iconographical feature of the presiding deity and the loose sculptures, the original temple can be dated to the 10th /11th century AD

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features		
Context Urban / Rural Setting Surroundings	* Drawings (Attach extra sheet if necessary) : No Urban setting	
	Stand in Isolation Integral part of a Landscape / Complex Street / Complex :	
• Quantification Area Dimension (L x B x H)	4.50 mtrs x 3.00 mtrs x 10.00 mtrs (approximate height) (m / cm/ feet / inch)	
Number of Blocks Number of Storys	Two,	
Spatial Organization Orientation Plan Allocation of Spaces	Facing towards north. Square on plan. 4.50 mtrs (L) x 3.00 mtrs (W)	
• Ornamentation		
Exteriors	Plain, except a <i>gaja-simha</i> and a rampart lion on each <i>raha pagas</i> , and few sculptural specimens like- Krisna, Ganesa, Kartikeya, and royal figures on the northern wall of the temple.	
Interiors : Movable Collections :	Plain Sivalinga (02 no), Visnu, Yama, Dasanana Ravana, Jaina Tirthankara, Shantinatha, Balakrushna Uma - Mahesvaramurty, etc.	
* Any Other (specify)	The temple is <i>pancharatha</i> on plan and <i>panchanga</i> bada in elevation.	
10. Construction Technology		
Structural System	Rekha vimana and pidha jagamohan of Kalingan order.	
Building Techniques Material of Construction	Ashlar masonry Khandolite stone and lime plaster.	
11. Condition Assessment		
In General Good / Fair	Good	
Sign of Deterioration Serious Deterioration Danger of Disappearance		
In Brief (Attach extra sheet if necessary):		

The temple is in a good state of preservation.

12. Threats to	x x x x x x x x x x x x	Natural Negligence Vandalism Urban Pressures x x x x x x x x x x x x x x x x x x x
13. Reference	Sources (published a	nd unpublished textual details)
Heritage of 2.	of Jajpur, Bhubaneswa	In and Around Jajpur, in G. Mohanty et al. (eds), <i>Cultural</i> r.
14. Photograp	ons: 36 nos.	(attach list as in page 6, in case of multiple photographs)
Photo Reference CAPTION		(attach not do in page o, in eace of mattiple photographs)
15. Audio / Vi	deo	(related to rituals / performance / festivals etc.)
Reference DESCRIPTION 16. Maps/Plan		(related to rituals / periorifiance / restivals etc.)
17. Listers		
NAME :	A. R. Sahoo	NAME:
18. Reviewers NAME: COMMENTS	Dr. S. Pradhan	NAME: COMMENTS: