

## INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR/JPR-21

1. Name	SECTION I: IDENTIFICATION
Present Past Other Name (if any): 2. Location	: Somesvara Siva Temple, Jajpur Town, Dist Jajpur :
<b>LONGITUDE</b> 86° 20' 15" E	<b>LATITUDE</b> 20 <sup>0</sup> 49' 43" N <b>ELEVATION</b> 25 ft
Address	: Village (village code) Post : Devidwar Tehsil: Jajpur Town State : Orissa  Jajpur Tow (Trilochanapada) Via: Devidwar District: Jajpur PIN: 755007
Approach  3. Property Type	: The temple is located on the right side of Jajpur-Binjharpur road and situated at a distance of half kilometer from the Viraja temple and 150 mtrs from the Trilochanesvara temple complex in Jajpur town.
3. Property Type	
Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures  Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum  Other Structures Wall Gateway Pillar Others (specify)  Others (specify)
Engineering structure  Bridge Tunnel Other engineering structure	Open space and related structuresNote:Public squareThe present temple was built over the original structure by the local zamindar Raisaheb Choudhury Narasimha Charana Mohapatra in Baolis, WellBaolis, Well1942. It has a rekha vimana of impoverished Kalingan order.Cave

. Property Use		
		ABANDONED / IN USE: In use
Present	:	It is living temple and the presiding deity is a Sivalinga within a circular <i>yonipitha</i> , made of black chlorite.
Past	:	Worshipped
5. Age (Source)		
PERIOD		Bhaumakara rule
YEARS	:	8 <sup>th</sup> /9 <sup>th</sup> century A.D.
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	It was repaired and renovated by the local zamindar Raisaheb Choudhury Narasimha Charana Mohapatra in 1942.
Destruction / Demolition	:	
6. Ownership / Level of Protection	n	
-		SINGLE / MULTIPLE : Multiple
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	:	
Private Any other (Please specify)	:	Villagers of Trilochanapada under the chief priest Kuni Dixit
Name Address Phone 7. Association	:	AT-Trilochanapada, PO Devidwar, Dist-Jajpur, Orissa
WITH EVENTS		
In History	:	
In Rituals	:	Sivaratri, Kartika Purnima, etc are observed here.
In Building Construction	:	
Any other (specify)	:	
WITH PERSONS Patron	:	Originally by the Bhaumakaras but now it is looked after by the chief priest Kuni Dixit.
Architect / Engineer	:	
Any other (specify)	:	
8. Statement of Significance		
Architectural	1	Architectural
Archaeological	/	Archaeological
Historical	./	Religious
Religious Any other (specify)	:	Religious

On the basis of iconographical features and the detached architectural fragments , the original temple can be dated to the Bhaumakara rule i.e. about the  $8^{th}/9^{th}$  century A.D.

## **SECTION II: DESCRIPTION**

9. Physical Description and De	corative Features
<ul> <li>Context</li> <li>Urban / Rural Setting</li> <li>Surroundings</li> </ul>	* <b>Drawings</b> (Attach extra sheet if necessary): No : Urban setting
-	Stand in Isolation Integral part of a Landscape/ Street / Complex :
<ul> <li>Quantification</li> </ul>	
Area Dimension (LxBxD)	: 4.40 mtrs x 4.15 mtrs x 8.50 mtrs (approximate height) (m / cm/ feet / inch)
Number of Blocks	: One
Number of Storys	: NA
Spatial Organization	
Orientation	: Facing towards east
Plan	: Square on plan.
Allocation of Spaces	: 22.00 mtrs x 15.50 mtrs in length and width respectively.
ARCHITECTURAL STYLE  • Ornamentation	
Exteriors	: Devoid of decoration, except the <i>parsvadevata</i> niches where images of Ganesa, Parvati and Uma-Mahesvara murti (02 nos) are housed.
Interiors	<ul> <li>Plain, except a ten- armed Mahisasuramardini Durga image attached in the rear wall.</li> </ul>
Movable Collections	: Images of Surya, Parvati, Lakulisa, Sivalinagas, votive temples relieved with linga worship, large number of architectural members and votive Buddhist stupa etc.
* Any Other (specify)	: The temple is <i>triratha</i> on plan and <i>panchangabada</i> in elevation.
10. Construction Technology	
Structural System Building Techniques Material of Construction	<ul><li> Rekha vimana of impoverished Kalingan order</li><li> Ashlar masonry</li><li> Khandolite stone and lime plaster</li></ul>
11. Condition Assessment	
In General	Good / Fair : Fair
Sign of Deterioration	

	Deterioration of Disappearance	
	h extra sheet if nece	essary):
Growth of vege mastaka portio	•	d trees are noticed over the temple from the bottom to t
12. Threats to	the Property	
x	* * * * * * * * * * * * * * * * * * * *	✓ Natural ✓ Negligence Vandalism Urban Pressures x x x x x x x x x x x x x x x x x x x
	SEC	CTION III: REFERENCES
42 Deference	Courses (nublished	and unpublished textual details)
2. <b>14. Photograp</b>	of Jajpur, Bhubanesw ohs: 55 nos.	
Photo Referen	ce	(attach list as in page 6, in case of multiple photograps:
15. Audio / Vid	deo	
		(related to rituals / performance / festivals e
Reference DESCRIPTION	1 :	
16. Maps/Plan	s/Drawings	
17. Listers		
	A.R. Sahoo	NAME :
18. Reviewers		
NAME : COMMENTS	Dr. S. Pradhan	NAME : COMMENTS :