INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR/JPR- 38

	SECTION I : IDENTIFICATION	l
1. Name		
Present Past Other Name (if any):	 Visesvara Mahadev Tel Dist Jajpur 	mple, Kapilesvara,
2. Location		
LONGITUDE 86 ⁰ 20'26" E	LATITUDE 20 ⁰ 49'10" N	ELEVATION 38 ft
Address	: Village (village code) Post : Mirchandpur Tehsil: Jajpur Town State : Orissa	Kapilesvara Via: Devidwar District: Jajpur PIN: 755007
Approach	Binjharpur road, at a	d on the right side of Jajpur- distance of ½ km branching chowk towards west and from Jajpur town
3. Property Type		
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public buildings Residential building Engineering structure	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify): Note: It is a single rekha vimana standing over a low pista measuring 0.48 mtrs in height.
Bridge Tunnel Other engineering structure	structures Public square Park or garden Graveyard Baolis, Well Tank Cave	into in noight.

4. Property Use		
	ABANDONED / IN USE : In use	
Present	Living temple, the enshrined deity i Sivalinga.	s a patalaphuta
Past	Worshipped.	
5. Age (Source)		
PERIOD	Ganga rule	
YEARS	14 th century A.D.	
Precise date of Construction		
Completion		
Subsequent changes		
Destruction / Demolition		
6. Ownership / Level of Protection		
	SINGLE /MULTIPLE : Multiple	9
Public : Archaeological Survey of India / State Archaeology		
Department / Any Other (Please		
specify)		
Private		
Any other (Please specify)	People of Kapilesvara village under Babu Panda	the priestship of
Name		
Address		
Phone		
7. Association		
• WITH EVENTS		
In History	 Pana Sankranti Jagara Kartika Purni	ma ata
In Rituals In Building Construction	Pana Sankranti, Jagara, Kartika Purni	na, elc.
Any other (specify)	Mundana, thread ceremony, kirtana, e	tc are performed
Any other (speeny)	here.	
WITH PERSONS		
Patron	Presently looked after by the villagers	of Kapilesvara.
Architect / Engineer		
Any other (specify)		
8. Statement of Significance		
Architectural	 Architectural 	
Archaeological		
Historical		
Religious	 Religious 	
Any other (specify)	On the basis of iconographical feature of	the <i>parsvadevatas</i>

On the basis of iconographical feature of the *parsvadevatas* and detached sculptures, the temple can be dated to the 14th century AD. i.e. the Ganga rule in Orissa.

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features		
• Context Urban / Rural Setting Surroundings	:	* Drawings (Attach extra sheet if necessary) : No Rural setting
Surroundings		Stand in Isolation Integral part of a Landscape / Street Street / Complex :
• Quantification Area Dimension (L x B x H)	:	5.80 mtrs x 5.10 mtrs x 10.75 mtrs (approximate height) (m / cm/ feet / inch)
Number of Blocks Number of Storys	:	One NA
• Spatial Organization Orientation Plan Allocation of Spaces	::	Facing towards east The <i>vimana</i> is square on plan that stands over a <i>pista</i> of 0.48 mtrs high 8.80 mtrs x 8.80 mtrs in length and width respectively.
ARCHITECTURAL STYLE • Ornamentation		
Exteriors	:	Decorated with <i>pidhamundi</i> design in both <i>talajangha</i> and <i>uparajangha</i> , a <i>miniature rekhamundi</i> on the frontal <i>raha</i> , rampant lion on each <i>rahapaga</i> , <i>beki- bhairava</i> and <i>dopichhasimhas</i> over the <i>beki</i> . <i>Parsvadevata</i> images are Ganesa, Kartikeya & Parvati
Interiors	:	Plain
Movable Collections	•	Lingodbhavamurti, Kartikeya (02 no.), Ganesa, Sivalinga, Nandis etc.
* Any Other (specify)	:	The temple is <i>pancharatha</i> on plan and <i>panchanga bada</i> in elevation. A square well made of khandolite stone is found in the north-east corner of the temple.
10. Construction Technology		
Structural System Building Techniques Material of Construction	:	<i>Rekha vimana</i> of <i>Kalingan</i> order Ashlar masonry Khandolite stone is used for the construction of the

washed.

temple and the entire surface is plastered and white

11. Condition Assessment

In General Good / Fair	:	Fair
------------------------	---	------

Sign of Deterioration
 Serious Deterioration
 Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Growth of vegetations are noticed in the *pista* and around the temple.

12. Threats to the Property



SECTION III: REFERENCES

13. Reference Sources	(published and u	inpublished textual details)
-----------------------	------------------	------------------------------

- 1. ---
- 2.

14. Photograp	ohs: 24 nos.		
			(attach list as in page 6, in case of multiple photographs)
Photo Refere CAPTION	nce	:	
15. Audio / Vi	deo		
			(related to rituals / performance / festivals etc.)
Reference DESCRIPTIO	N	:	
16. Maps/Plar	ns/Drawings		
17. Listers			
NAME :	A. R. Sahoo		NAME :
18. Reviewers	6		
NAME : COMMENTS	Dr. S. Pradhan		NAME : COMMENTS :