

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA/ BSR-99

1. Name	SECTION I: IDENTIFICATION
Present	: Kotitirthesvara Siva Temple, Bhubaneswar,
Past Other Name (if any):	DistKhurda : :
2. Location	
LONGITUDE 85 ⁰ 51'28"E	LATITUDE 20°14'48"N ELEVATION 70 ft.
Address	: Village (village code) Post: Old Town Tehsil: Bhubaneswar State: Orissa Kotitirthesvara Lane Via: Bhubaneswar District: Khurda PIN: 751002
Approach	 The temple is located on the left side of the Kotithirtesvara lane, leading from Parasuramesvara temple to Bindusagar tank.
3. Property Type	
Buildings Palace Fort Citadel Govt. building Railway station Defense building Industrial building Other public building Residential building	Religious structures ✓ Temple wall Mosque Gateway Minar Pillar Church Others (specify) Monastery Stupa Tomb, Mausoleum
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Cave Note: It is a rekha temple of Kalingan order. Originally it had a jagamohana which is missing now.

4. Property Use

ABANDONED / IN USE: In use

Present : It is a living temple and enshrines a Sivalinga within a

circular yonipitha.

Past : Worshipped.

5. Age (Source)

PERIOD : Somavamsi rule. **YEARS** : 11th century A.D.

Precise date of Construction : --- Completion : ---

Subsequent changes: The temple was renovated and reconstructed during X

& XI Finance Commission Award by Orissa State

Archaeology.

Destruction / Demolition : ---

6. Ownership / Level of Protection

SINGLE /MULTIPLE : Multiple

Public: Archaeological Survey of: India / State Archaeology

Department / Any Other (Please

specify)

Private : Maintained by the Kotitirthesvara Thakura

Development Committee

Any other (Please specify)

Name : --

Address : Kotitirthesvara lane, Old town, Bhubaneswar.

Phone : ---

7. Association

• WITH EVENTS

In History : ---

In Rituals : Sivaratri, Kartikapurnima, Sankranti are observed.

In Building Construction : --

Any other (specify) : The temple is considered as sacred on account of

adjoining tank as one of the *panchatirtha*, the other four being Gana-Yamuna Kunda, Bindusagar,

Devipadhara and Papanasini.

WITH PERSONS

Patron : Originally the Somavamsis, but now it is looked after

by the Kotitirthesvara Thakura Development

Committee.

Architect / Engineer : --Any other (specify) : ---

8. Statement of Significance

Architectural ✓ Architectural

Archaeological Historical Religious Any other (specify) 9. Physical Description and De	 : ∴ Religious : On the basis of architectural features the temple can be assigned to the Somavamsi period (11th century AD). On religious point of view it is one among the panchatirtha of Ekamra nagara (Bhubaneswar). SECTION II: DESCRIPTION
Context Urban / Rural Setting	* Drawings (Attach extra sheet if necessary) : No : Urban setting
Surroundings	Stand in isolation Complex Integral part of a landscape / Street / Complex :
 Quantification 	
Area Dimension (LxBxH)	: 6.10 mtrs x 5.30 mtrs x 11.60 mtrs (m / cm/ feet / inch)
Number of Blocks Number of Storys	: One :
 Spatial Organization Orientation Plan 	: The temple is facing towards West.: The <i>viman</i> is square on plan over a rectangular platform.
Allocation of Spaces	: 6.40 mtrs(L) x 6.20 mtrs (W)
ARCHITECTURAL STYLE • Ornamentation Exteriors Interiors Movable Collections * Any Other (specify)	 The outer wall, except the raha paga is plain, due to renovation work. The raha paga is decorated with bho type vajramastaka and udyotasimha. Plain Not found It is a pancharatha temple.
10. Construction Technology	
Structural System Building Techniques Material of Construction 11. Condition Assessment	The <i>vimana</i> is of <i>rekha order</i>.Ashlar dry Masonry.The temple is made of light fine grained sandstone.
In General Good / Fair	: Fair
Sign of Deterioration Serious Deterioration Danger of Disappearance	

Kotitirthesvara	lane road.	
12. Threats to	the Property	
		Natural Negligence Vandalism ✓ Urban Pressures
x x x x x x x	(× × × × × × × × × × × × × × × × × × ×
	<u>s</u>	ECTION III: REFERENCES
13. Reference	Sources (publishe	d and unpublished textual details)
	- · · · · · · · · · · · · · · · · · · ·	of Orissa, Vol. II Calcutta. Temple Art of Orissa, Vol I, Lieden.
14. Photograp	ohs: 15 nos	
		(Attach list as in page 6, in case of multiple photographs)
Photo Reference CAPTION	nce	: :
15. Audio / Vi	deo	
Reference DESCRIPTIOI 16. Maps/Plar		(Related to rituals / performance / festivals etc.) :
17. Listers		
NAME :	D. B. Garnayak	NAME :
18. Reviewers	S	
NAME:	Dr. S. Pradhan	NAME:

COMMENTS:

COMMENTS

In Brief (Attach extra sheet if necessary):
Roof of the temple has cracks and encroachment is severe on the south-west corner of the