INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, <u>www.ignca.gov.in</u>

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA/ BSR- 106

SECTION I : IDENTIFICATION				
1. Name				
Present Past Other Name (if any):	 Laksmanesvara Siva Temple, Bhubaneswar, DistKhurda. 			
Other Name (ir arry).	. —			
2. Location				
LONGITUDE 85 ⁰ 50'09"E	LATITUDE 20 ⁰ 15'12"N ELEVATION 80 ft			
Address	: Village (village code) Post : Old Town Tehsil: Bhubaneswar State : Orissa Old Town , Bhubaneswar Via: Bhubaneswara District: Khurda PIN: 751002			
Approach	: The temple located on the left side of the road leading from Kalpana chowk to Lingaraja temple & just opposite of the Ramesvara temple.			
3. Property Type				
BuildingsPalaceFortCitadelGovt. buildingRailway stationDefense buildingIndustrial buildingOther public buildingsResidential building	Religious structures Other Structures			
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structuresNote:Public squareThe temple has a rekha vimana of Kalingan order.Park or garden GraveyardVimana of Kalingan order.Baolis, Well Tank CaveTank			

		ABANDONED / IN USE : In use
Present	:	Living temple the presiding deity is a sivalinga within a
Past	:	square <i>yonipitha</i> made of sandstone. Worshipped.
5. Age (Source)		
PERIOD		Sailodbhavas rule.
YEARS	:	Later half of 6 th century A.D.
Precise date of Construction	÷	Later half of 6 th century A.D.
Completion	÷	
Subsequent changes	:	Renovated by Orissa State Archaeology.
Destruction / Demolition	:	Now the <i>mastaka</i> is missing.
6. Ownership / Level of Protecti	on	
		SINGLE /MULTIPLE : Multiple
Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	:	Protected Monument of Orissa State Archaeology.
Private	:	
Any other (Please specify)	:	
Name	:	Orissa State Archaeology.
Address	:	Paryatan Bhavan, BJB Nagar, Bhubaneswar, Orissa
Phone	:	0674-2432147
7. Association		
WITH EVENTS		
In History	:	
In Rituals	:	Sivaratri, Sankranti etc. observed here
In Building Construction	:	
Any other (specify)	:	
WITH PERSONS	_	Originally the Opiledheause but see the Opile Of
Patron	:	Originally the Sailodbhavas, but now the Orissa Stat
Anabita at / English an	_	Archaeology.
Architect / Engineer	÷	
Any other (specify)	:	
8. Statement of Significance		
, a child o cardi	✓	Architectural
Archaeological		
Historical	:	
Religious Any other (specify)		Religious
		The temple can be assigned to the closing years of the 6 th of

SECTION II: DESCRIPTION

 Context Urban / Rural Setting Surroundings 	:	* Drawings (Attach extra sheet if necessary) : No Urban setting
		Stand in isolationComplexIntegral part of a landscape /Street / Complex :
Quantification		
Area Dimension (L x B x H)	:	6.85 mtrs x 6.35 mtrs x 5.00 mtrs (Approximately) (m / cm/ feet / inch
Number of Blocks	:	Single
Number of Storys	:	
Spatial Organization		
Orientation		Facing towards west
Plan		It is a square <i>vimana</i>
Allocation of Spaces	:	90 mtrs(L) x 70.50 mtrs(W).
ARCHITECTURAL STYLE		
Ornamentation Exteriors		Departed with chaitys motif hames motif and acro
Extendis	•	Decorated with <i>chaitya</i> motif, <i>hamsa</i> motif, and scro work in the <i>basanta</i> of <i>pabhaga</i> and lion, elephan <i>deul</i> acharini, flying <i>vidyadhara, makara</i> motif, <i>hams</i> found in the <i>janga</i> .
Interiors	:	Plain
Movable Collections		Scattered architectural members are found in th
		northern corner of the complex.
* Any Other (specify)	:	The temple is <i>triratha</i> in plan & <i>triangabada</i> i elevation.
10. Construction Technology		
Structural System	:	Rekha vimana of Kalingan style.
Building Techniques	:	Ashlar dry Masonry
Material of Construction	:	Sandstone is used for the temple Construction.
11. Condition Assessment		
In General Good / Fair	:	Fair
 Sign of Deterioration Serious Deterioration Danger of Disappearance 		

In Brief (Attach extra sheet if necessary):

The temple is conserved up to the half of *jangha* portion and core of the *gandi*.

12. Threats to the Property

	Natural
	Negligence
	Vandalism
~	Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

1. Debala Mitra, 1958, *Bhubaneswar*, New Delhi.

2. T.E.Doraldson, 1985, *Hindu Temple Art of Orissa*, Vol. I. Leiden.

14. Photographs: 09 nos

			(Attach list as in page 6, in case of multiple photographs)		
Photo Refere CAPTION	nce	:			
15. Audio / Vi	deo				
			(Related to rituals / performance / festivals etc.)		
Reference DESCRIPTIO	N	:			
16. Maps/Plans/Drawings					
17. Listers					
NAME :	Jayasankar Naik		NAME :		
18. Reviewers					
NAME : COMMENTS	Dr. S. Pradhan		NAME : COMMENTS :		