

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA/ BSR- 107

1. Name	SECTION I: IDENTIFICATION				
Present	: Lingaraja Bisrama Ghara, Old Town, Bhubaneswar, Dist.Khurda				
Past Other Name (if any): 2. Location	: :				
LONGITUDE 85 ⁰ 50'09" E	LATITUDE 20 ⁰ 14'41" N ELEVATION 56 ft				
Address	: Village (village code) Post : Old Town Tehsil: Bhubaneswar State : Orissa Old Town Via: Bhubaneswar District: Khurda PIN: 751002				
Approach	: The <i>Bisrama Ghara</i> is situated on the western embankment of Bindusagara tank in <i>Gyanaghara</i> (Hadi Sahi) of Old town. One can approach the temple on the left side of the road leading from Kedara Gouri chowk to Vaitala temple.				
3. Property Type					
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum Other Structures Wall Gateway Pillar Others (specify) Others (specify)				
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Cave Note: Kalingan Order. There is no presiding deity as served as the rest house of Lord Lingarajaa, when the lord comes here to take rest in course of the Chandana Yatra, which is held in the month of May in every year.				

4. Property Use

ABANDONED / IN USE: Multiple **Present** It acts as a Bishrama ghara of Lord Lingarajaa during the Chandana Yatra. In Use **Past** 5. Age (Source) PERIOD Ganga rule 14th century A.D. YEARS Last guarter of the 14th century A.D. Precise date of Construction Completion Subsequent changes **Destruction / Demolition** 6. Ownership / Level of Protection SINGLE /MULTIPLE : Multiple **Public**: Archaeological Survey of : / State Archaeology Department / Any Other (Please Lingaraja Temple Trust Board specify) **Private** Lingaraja Temple Trust Board Any other (Please specify) Name Address Old town, Bhubaneswar, Dist-Khurda, Orissa. Phone 7. Association WITH EVENTS In History In Rituals It is related with the Chandana Yatra of Lord Lingaraja Temple. In Building Construction Any other (specify) ---**WITH PERSONS** Patron Originally, the Gangas but now it is looked after by the Lingaraja Temple Trust Board. Architect / Engineer Any other (specify) ---8. Statement of Significance Architectural ✓ Architectural Archaeological Historical Religious Religious Any other (specify) On the basis of the architectural features, the temple can be dated to the 14thcentury A.D.

SECTION II: DESCRIPTION

9. Physical Description and De	cora	ative Features		
Context Urban / Rural Setting Suggested in the setting		* Drawings (Attach extra sheet if necessary) : No Urban setting		
Surroundings		Stand in Isolation Integral part of a Landscape / Street / Complex :	Street	
• Quantification Area Dimension (L x B x H)	:	4.25mtrs X 4.25mtrs X6.23mtrs	(m / cm/ feet / inch	
Number of Blocks Number of Stories	:	One 	(III / GIII ICCE / IIIGII	
• Spatial Organization Orientation Plan	:	The rest house is facing towards south. The Rest house is square on plan that stands on a love platform of 0.66mtrs in height.		
Allocation of Spaces	:	4.25mtrs X 4.25mtrs in length and	d width respectively.	
ARCHITECTURAL STYLE • Ornamentation Exteriors Interiors Movable Collections * Any Other (specify)	: : : :	Plain plain The Bishrama Ghara/ Rest house and pachanga bada in elevation.	e is <i>pancharatha on</i> plar	
10. Construction Technology				
Structural System Building Techniques Material of Construction	:	The <i>Bishrama Ghara is</i> impoverished <i>Kalingan</i> Order. Ashlars dry masonry. Sandstone	a pidha temple of	
11. Condition Assessment				
In General Good / Fair ✓ Sign of Deterioration Serious Deterioration Danger of Disappearance		: Fair		

In Brief (Attach extra sheet if necessary):

The northern wall has developed cracks and the rain water enters through these cracks into the rest house. This temple is encroached by Government office in the northern side.

12. Threats to	o the Property	
	✓ Natural ✓ Negligence ✓ Vandalism ✓ Urban Pressures	
x x x x x x x x	× × × × × × × × × × × × × × × × × × ×	
	SECTION III: REFERENCES	
13. Reference	Sources (published and unpublished textual details)	
1. 2.		
14. Photograp		
	(attach list as in page 6, in case of multiple photographs)	
Photo Referer CAPTION	nce :	
15. Audio / Vid	deo	
	(related to rituals / performance / festivals etc.)	
Reference DESCRIPTION	: N :	
16. Maps/Plan	s/Drawings	
17. Listers		
NAME :	Ashis Ranjan Sahoo. NAME:	
NAME: COMMENTS	Dr. S. Pradhan NAME: COMMENTS:	