

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA / 10

	SECTION I: IDENTIFICATION						
1. Name							
Present Past Other Name (if any): 2. Location	Madhukesvar Temple, Deulidharpur, Dist Khurda						
LONGITUDE 86 ⁰ 00'54" E	LATITUDE 20 ⁰ 08'39" N ELEVATION 20 ft						
Address	: Village (village code) Post : Deulidharpur Tehsil: Bhubaneswar State : Orissa Deulidharpur Via: Banamalipur District: Khurda PIN: 752103						
Approach	: The temple is located on the left bank of the river Kushabhadra and it is about 22 kms from Balianta on the right side of Balianta-Nimapada road. The Gop branch canal is also flowing very close to the temple.						
3. Property Type							
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures ✓ Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum Other Structures Wall Gateway Pillar Others (specify)						
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Cave Note: The temple has a rekha vimana and a pidha jagamohana of Kalingan order. The important features of this temple is a torana which resemblances with Mukteswar temple's torana in Bhuabaneswar.						

4. Property Use

ABANDONED / IN USE: In use

Present : It is a living temple, enshrining a Sivalinga within a

square yonipitha.

Past : Worshiped.

5. Age (Source)

PERIOD : Somavamsi rule YEARS : 15th century A.D.

Precise date of Construction: The existing inscription in the temple suggests that the

present temple was renovated during the Gajapati period and earlier there was a brick temple prior to this temple. The available brick size indicates the earlier temple was constructed during Somavamsi period.

The Completion : --

Subsequent changes : Renovated and conserved by Orissa State

Archaeology under X & XI Finance Commission

Award.

Destruction / Demolition : ---

6. Ownership / Level of Protection

SINGLE /MULTIPLE: Multiple

Public: Archaeological Survey of : Protected monument of Orissa State Archaeology.

India / State Archaeology Department / Any Other (Please

specify)

Private : --

Any other (Please specify) : Budhikesvar Yajna Committee under the president

ship of Sudarsan Jena.

Name : ---

Address : Orissa State Archaeology, Paryatan Bhawan, B.J.B.

Nagar, Bhubaneswar, Orissa

Phone : 0674-2432147

7. Association

WITH EVENTS

In History : ---

In Rituals: Kartika Purnima, Jagara, etc are observed here.

In Building Construction : --Any other (specify) : ---

WITH PERSONS

Patron : Presently the temple is looked after by the

Budhikesvar Yajna Committee.

Architect / Engineer : --

Any other (specify) : Orissa State Archaeology

8. Statement of Significance

Architectural

Archaeological

✓ Architectural

✓ Archaeological

Historical Religious Any other (specify)	 ✓ Historical Religious On the basis of epigraphical record (12 lines in proto- Oriya script) found in the rear wall of <i>jagamohana</i>, the present temple was renovated during the Gajapati rule. However, the available brick size indicates that the earlier temple was constructed during Somavamsi period.
	SECTION II: DESCRIPTION
 9. Physical Description and Description Context Urban / Rural Setting 	* Drawings (Attach extra sheet if necessary): No : Rural setting
Surroundings	Stand in Isolation Stand in isolation Integral part of a Landscape / Street / Complex :
 Quantification Area Dimension (L x D x H) 	: 15.80 mtrs x 9.20 mtrs x 10.00 mtrs (approximate height) (m / cm/ feet / inch)
Number of Blocks Number of Storys	: Two :
 Spatial Organization Orientation Plan Allocation of Spaces 	 The temple is facing towards east. Both the <i>vimana</i> and <i>jagamohana</i> are square on plan.
ARCHITECTURAL STYLE Ornamentation Exteriors	. The exterior well of the temple is devoid of any coulptural
Exteriors	: The exterior wall of the temple is devoid of any sculptural embellishment, except the parsvadevata images. Khakharamundis are the only architectural motifs of the temple along with angasikharas at raha paga.
Interiors	 The inner ceiling of the jagamohana is decorated with a huge lotus medalion.
Movable Collections	 It includes pillar members of both laterite and sand stone, udyotasimha, deulacharini, broken image of Visnu and Ganesa (only head portion)
* Any Other (specify)	: The temple is <i>pancharatha</i> on plan and <i>panchangabada</i> in elevation.
10. Construction Technology	
Structural System	: It has curvilinear <i>rekha vimana</i> and <i>pidha jagamohana</i> of <i>Kalingan</i> order.
Building Techniques Material of Construction	: Ashlar dry masonry.: Sandstone and bricks.

11. Condition Assessment

In General		✓ Si	/ Fair : Faign of Deterior erious Deterio anger of Disap	ration				
In Brief (Attac	h extra sheet if	necessa	ary):					
between Kush water logging p	eason, wild vego abhadra river a problem during r	nd Gop	canal, particul					
X x	x x	✓ ✓ ✓	Natural Negligence Vandalism Urban Pressu x x	ıres x x	x	x	x	
		SECTION	<u>ON III :</u> REFE	RENCES				
13. Reference	Sources (publis				ils)			
1. 2. 14. Photogra p	hs: 13 nos		(attach list as	in nage 6 i	n case of	multiple	e nhoto	
Photo Reference CAPTION	ce	:	(attaon not as	iii page o, i	ir case or	типри	o prioto;	gı
15. Audio / Vid	leo							
Reference DESCRIPTION	I	:	(rela	ated to ritua	ıls / perfoi	rmance	/ festiva	al
16. Maps/Plan	s/Drawings							
17. Listers	<u> </u>							
NAME :	Ashis Ranjan	Sahoo	NAME :					
18.Reviewers								
NAME : COMMENTS	Dr. S. Pradhan		NAME : COMMEI	NTS :				