

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA/ BSR- 110

SECTION I: IDENTIFICATION 1. Name Mahakala-Mahakali Temple, Old Town, Bhubaneswar, Present Dist.-Khurda **Past** Other Name (if any): 2. Location 20⁰14'26" N 85°50'05" E LATITUDE LONGITUDE **ELEVATION** 71 ft Address Village (village code) Old Town Post: Old Town Via: Bhubaneswar **Tehsil:** Bhubaneswar **District:** Khurda State: Orissa **PIN:** 751002 Approach The temple is located beyond the eastern compound wall of Lingarajaa temple on the right side of the temple road leading to Hata Sahi of Old town. 3. Property Type **Buildings** Religious structures Other Structures Palace Temple Wall Fort Mosque Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: structures is shrine without а Public square Bridge superstructure. On the basis of the Tunnel Park or garden architectural features, the temple Other engineering structure Graveyard can be dated to the 11thcentury Baolis, Well A.D. Tank Cave

4. Property Use

4. Property Ose					
		ABANDONED / IN USE: In Use			
Present	:	In this open but living temple, the presiding deity is a Sivalinga within a square <i>Yonipitha</i> The enshrining deity is a			
		Sivalinga within a square <i>Yonipitha</i> at the depth of 4.00mtrs below the present ground level.			
Past	:	Worshipped			
5. Age (Source)					
PERIOD	:	Somavamsi rule			
YEARS	:	11 th century A.D.			
Precise date of Construction	:	Last quarter of the 11 th century A.D.			
Completion	•				
Subsequent changes	•				
Destruction / Demolition	:				
	•				
6. Ownership / Level of Protection					
		SINGLE /MULTIPLE : Multiple			
Public: Archaeological Survey of	:				
India / State Archaeology					
Department / Any Other (Please					
specify)					
Private					
Any other (Please specify)	•	Lord Lingaraja Temple Trust Board.			
Name	:	Lord Emgaraja Tompio Tradi Board.			
Address	:	Old Town, Bhubaneswar, Dist-Khurda, Orissa.			
Phone	:	Old Town, Dhubaneswar, Dist-Miurua, Olissa.			
7. Association	•				
WITH EVENTS In History					
In History In Rituals	÷				
	•				
In Building Construction	:				
Any other (specify)	:				
WITH PERSONS					
Patron	:	Originally by the Somavamsis but presently under the			
		Lord lingaraja Temple Trust Board.			
Architect / Engineer	:				
Any other (specify)	:				
8. Statement of Significance					
Architectural	/	Architectural			
Archaeological					
Historical					
✓ Religious	1	Religious			
Any other (specify)	:	On the basis of the architectural features, the shrines can be			

dated to the last guarter of the 11th century A.D. Close to the main deity is another small Sivalinga within another Yonipitha which is known as Mahakali, while the central lingam is known as Mahakala. According to the local tradition, they are the parents of Lord Lingaraja

SECTION II: DESCRIPTION

9.	Phy	ysical	Description	and	Decorative	Features
----	-----	--------	-------------	-----	------------	-----------------

Context **Urban / Rural Setting**

* **Drawings** (Attach extra sheet if necessary): No

Urban setting

Surroundings

Stand in Isolation

Street

Integral part of a Landscape /

Street / Complex:

Quantification

Area Dimension (LxBxH)

4.50 mtrs x 3.70 mtrs x 4.00 mtrs (height of the existing

temple)

(m / cm/ feet / inch)

Number of Blocks One Number of Stories

Spatial Organization

Orientation It is an open shrine.

The vimana is square on plan. Plan

4.50 mtrs x 3.70 mtrs in length and width respectively. Allocation of Spaces

ARCHITECTURAL STYLE

Ornamentation

Exteriors Plain Interiors plain

Movable Collections An image of Ganesa, two nayikas, udyota simhas, and

amlakas etc.

Fair

* Any Other (specify) A flight of steps are provided in the southern side of the

temple to approach the sanctum

10. Construction Technology

Structural System Can not be ascertained **Building Techniques** Ashlar dry masonry.

Material of Construction Sandstone

11. Condition Assessment

In General Good / Fair

✓ | Sign of Deterioration

Serious Deterioration

Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Since the shrine is 4.00mtrs down to the road level, there is no outlet for discharge of offering water and rain water directly enters into the shrine. Growth of vegetation and cracks are found in all walls of the cella. In the northern side, the temple is partially encroached by local individuals.

12. Threats to the Property						
x x x x x x x x	✓ Ne Va ✓ Urb	tural gligence ndalism pan Pressures				
SECTION III: REFERENCES						
13. Reference	Sources (published and un	published textual details)				
1. 2.						
14. Photograp	ohs: 05 nos					
	(attach li	st as in page 6, in case of multiple photographs)				
Photo Reference CAPTION	nce : :					
15. Audio / Vi						
	(related to ritu	ials / performance / festivals etc.)				
Reference DESCRIPTION	· :					
16. Maps/Plans/Drawings						
17. Listers						
NAME: Ashis Ranjan Sahoo.		NAME:				
18. Reviewers						
NAME: COMMENTS	Dr. S. Pradhan	NAME: COMMENTS:				