INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, <u>www.ignca.gov.in</u>

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA/ BSR- 123

1. Name	SECTION I: IDENTIFICATION	
Present Past Other Name (if any):	: Muktesvara Temple, Br : : Muktesvara Temple	ubaneswar,DistKhurda
2. Location		
LONGITUDE 85 ⁰ 50'26"E	LATITUDE 28 ⁰ 14'33"N	ELEVATION 52 ft.
Address	: Village (village code): Post : Old Town Tehsil: Bhubaneswar State : Orissa	Old Town, Bhubaneswar Via: Old Town District: Khurda PIN: 751002
Approach	: It is located on the righ Bhubaebswar to Puri.	t side of the road leading from
3. Property Type		
Buildings Palace Fort Citadel Govt. building Railway station Defense building	Religious structures ✓ Temple Mosque Minar Church Monastery Stupa	Other Structures Wall Gateway Pillar Others (specify):
Industrial building Other public buildings Residential building	Tomb, Mausoleum	Note: The temple <i>has a rekha vimana</i>
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Cave	and <i>pidha jagamohan</i> of <i>Kalingan</i> order.

4. Property Use	
	ABANDONED / IN USE : In use
Present	: It is a living temple, enshrining <i>Sivalinga</i> within a circular <i>yonipitha</i> .
Past	: Worshipped.
5. Age (Source)	
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition	 Somavansis rule 10th century A.D. 10th century A.D.
6. Ownership / Level of Protection	
	SINGLE /MULTIPLE : Single
Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	: Protected Monument of Archaeological Survey of India
Private	: Load Lingaraja Temple Management Trust.
Any other (Please specify) Name	: Archaeological Survey of India
Address	 Bhubaneswar Circle, 153, VIP Area, Nayapalli, Bhubaneswar
Phone	: 0674-2558170
7. Association	
WITH EVENTS	
In History In Rituals	: : Sivaratri, Kartikapurnima, Jalasaya etc observed here.
In Building Construction	:
Any other (specify)	:
WITH PERSONS Patron	: Archaeological Survey of India, Bhubaneswar Circle
Architect / Engineer	:
Any other (specify)	:
8. Statement of Significance	
Architectural Archaeological Historical Religious Any other (specify)	 Architectural Religious From the point of art and architecture, the temple is assigned to the transitional phase of temple building tradition. Fergusson described it as the gems of Orissan architecture. R. L. Mitra described it as "the handsomest –a charming epitome of the perfection of Orissan temple architecture.

SECTION II: DESCRIPTION

Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) : No Urban setting		
Surroundings		Stand in IsolationComplexIntegral part of a Landscape /Street / Complex :		
• Quantification Area Dimension (L x B x H)	:	13.68mtrs x 8.10mtrs x 10.67mtrs. (m / cm/ feet / inch		
Number of Blocks Number of Storys	:	Two		
• Spatial Organization Orientation Plan Allocation of Spaces	::	Facing towards west The <i>vimana</i> is square on plan and the <i>jagamohana</i> is rectangular on plan. 68.50mtrs (L) x 61.00 mtrs (B)		
ARCHITECTURAL STYLE				
Ornamentation Exteriors	:	The temple is highly decorated with proper symmetrical order. The <i>nayika</i> figures, scrollwork <i>chaitya</i> motifs, social scene like <i>sikhyadana</i> , bab nursing scene and architectural motifs like <i>naga-nag</i> <i>stamba</i> etc. enriched the sculptural embellishment of the temple.		
Interiors	:	Decorated with the eight-petalled lotus medallion in the center. <i>Matruka</i> images are carved on each petal with the least petal containing an image of Virabhadra. The truncated and panels of the coffer are filled with Kartikeya and a dancing Ganesa. The corner panel are filled with seated figures, male and female, flanke by Virala motifs. Every inch of the ceiling is ornated carved.		
Movable Collections * Any Other (specify)	:	 The temple stands on a low platform, is a <i>pancharath</i> on plan and <i>triranga bada</i> in elevation. Exemption: <i>Pabhaga</i> consists of five moulding except for the corner rather which have only four.		
10. Construction Technology		,		
Structural System	:	A rekha types vimana with curvilinear spire and pidh		
Building Techniques	:	type <i>jagamohana</i> with a stepped pyramidal roof. Ashlar dry masonry with corbelled technique construction.		
Material of Construction	:	Ocher colour sand stone.		

11. Condition Assessment

In	General Good	/ Fair	:	Good
	Sign of Deteriorat	ion		
	Serious Deteriora	tion		
	Danger of Disapp	earance		

In Brief (Attach extra sheet if necessary):

The temple is in a good state of preservation.

12. Threats to the Property



SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

- 1. T. E. Donaldson, 1985, *Hindu Temple Art of Orissa*, Vol. I, Leiden.
- 2. Debala Mitra, 1958, *Bhubaneswar*, New Delhi.
- 3. R. P. Mohapatra, 1986, Archaeology in Orissa, Vol. I, Delhi.
- 4. James Fergusson, 1970, A History of Indian and Eastern Architecture, Vol. II, London
- 5. K.C. Panigrahi, 1961, *Archaeological Remains at Bhubaneswar*, Calcutta.

14. Photographs: 99 nos

			(attach list as in page 6, in case of multiple photographs)
Photo Referen CAPTION 15. Audio / Vi		:	
			(related to rituals / performance / festivals etc.)
Reference DESCRIPTIOI 16. Maps/Plar		:	
17. Listers			
NAME : 18. Reviewers	D. B. Garnayak.		NAME :
NAME : COMMENTS	Dr. S. Pradhan		NAME : COMMENTS :