

## INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

## **Documentation format for Archaeological / Heritage Sites / Monuments**

Serial No.: OR / KDA/ BSR- 97

-			
1. Name	SECTION I: IDENTIFICATI	ON	
Present	: Nilakantha Siva Te DistKhurda	emple, Old Town, Bhubaneswar,	
Pact			
Past	:		
Other Name (if any): 2. Location	:		
<b>LONGITUDE</b> 85 <sup>0</sup> 50'00" E	<b>LATITUDE</b> 20 <sup>0</sup> 14'06"	N <b>ELEVATION</b> 85ft	
	24111032 201100		
Address	: Village (village cod  Post : Old Town Tehsil: Bhubaneswa State : Orissa	Old Town <b>Via:</b> Bhubaneswar	
Approach	: The temple is located within the Kharakhia Vaidyanatha temple precinct in Old town area of Bhubaneswar. One can approaches from the left side of the Vaidyanatha road leading from Lingaraja temple to Kapilesvara.It is about 1km. south-east of the Lingaraja temple.		
2 Proporty Type	Lingaraja temple.		
3. Property Type			
Buildings	Religious structures	Other Structures	
Palace	✓ Temple	Wall	
Fort	-		
	Mosque	Gateway	
Citadel	Minar	Pillar	
Govt. building	Church	Others (specify)	
Railway station	Monastery		
Defence building	Stupa		
Industrial building	Tomb, Mausoleum		
Other public buildings			
Residential building			
Resideritial building			
Engineering structure	Open space and related structures	Note:	
Pridge		The temple has a rekha vimana	
Bridge	Public square	and <i>pidha jagamohana</i> of	
Tunnel	Park or garden	Kalingan Order.	
Other engineering structure	Graveyard		
	Baolis, Well		
	Tank		
	Cave		

4. Property Use ABANDONED / IN USE: In use Present It is a living temple and the presiding deity is Sivalinga within a square Yonipitha and the latter one is made of laterite. Worshipped. **Past** 5. Age (Source) PERIOD Somavamsi rule 11<sup>th</sup> century A.D. YEARS **Precise date of Construction** First quarter of the 11<sup>th</sup> century A.D. Completion Subsequent changes The temple is repaired by the Orissa State Archaeology under the X and XI Finance Commission Award. **Destruction / Demolition** 6. Ownership / Level of Protection SINGLE /MULTIPLE : Single **Public**: Archaeological Survey of : State Archaeology / Department / Any Other (Please specify) **Private** Any other (Please specify) The temple is looked after by Babulal Makaddam Badu Mohapatra Name Address Kharakhia Vaidyanatha temple, Old town, Bhubaneswar, Dist-Khurda, Orissa. **Phone** 7. Association WITH EVENTS In History The Saivite rituals like Sivaratri, Sankranti are In Rituals celebrated here. In Building Construction Any other (specify) \_\_\_ WITH PERSONS Patron The present owner **Architect / Engineer** Any other (specify) 8. Statement of Significance ✓ Architectural Architectural

Archaeological Historical

Religious Any other (specify)	<ul> <li>Religious</li> <li>On the basis of the architectural style, the temple can be dated to the 11<sup>th</sup> century A.D.</li> </ul>	е			
SECTION II: DESCRIPTION					
9. Physical Description and Decorative Features					
<ul> <li>Context</li> <li>Urban / Rural Setting</li> <li>Surroundings</li> </ul>	* <b>Drawings (</b> Attach extra sheet if necessary) : No Urban setting				
	Stand in Isolation Complex Integral part of a Landscape / Street / Complex :				
<ul> <li>Quantification</li> <li>Area Dimension ( L x B x H)</li> </ul>	: 9.79mtrs x 5.32mtrs x 8.64mtrs				
Number of Blocks Number of Stories	: Two :	cn)			
<ul> <li>Spatial Organization         Orientation         Plan     </li> <li>Allocation of Spaces</li> </ul>	<ul> <li>The <i>vimana</i> is facing towards west.</li> <li>The <i>vimana</i> and <i>jagamohana</i> are square on pleasuring 4.40sq.mtrs and 6.20sq.mtrs respectively.</li> <li>53.00mtrs X 53.00mtrs in length and width respectively.</li> </ul>				
• Ornamentation Exteriors Interiors Movable Collections * Any Other (specify)	<ul> <li>Due to the cement plaster all over the structure to decorative programmes are concealed.</li> <li>Plain</li> <li></li> <li>Both the <i>vimana</i> and <i>jagamohana</i> are <i>pancharatha</i> plan and <i>panchangabadabada</i> in elevation. To doorjambs are decorated with three ornamented vertic bands. At the base of the door jamb, there are Dvarapa niches housing Saivite Ganas surmounted by chair motifs. Gajalaxmi is depicted in the <i>lalatabimba</i> and <i>navagraha</i> in the <i>graha</i> architrave.</li> </ul>	on he cal las tya			
10. Construction Technology					
Structural System  Building Techniques  Material of Construction	<ul> <li>The vimana is a rekha temple whereas the jagamohana is a pidha temple of Kalingan Order.</li> <li>Ashlar dry masonry.</li> <li>Laterite</li> </ul>	ne			
11. Condition Assessment					
In General Good / Fair Sign of Deterioration	: Good				

Serious Det Danger of D	erioration Disappearance	
In Brief (Attac	h extra sheet if necessa	ry):
	ring rainy season. The c	ot growth of vegetation and wild grasses in and around cement plaster all over has concealed the decorative
12. Threats to	o the Property	
		Natural Negligence Vandalism Urban Pressures
x x x x x x x		ON III: REFERENCES
13. Reference	Sources (published and	unpublished textual details)
1. 2.	u .	,
14. Photograp		Cattoria list on in many C. in account moulting a marks were less
Photo Referer CAPTION		attach list as in page 6, in case of multiple photographs
15. Audio / Vid	deo	
		(related to rituals / performance / festivals etc.
Reference DESCRIPTION	: I :	
16. Maps/Plan	s/Drawings	
17. Listers		
NAME :	Ashis Ranjan Sahoo.	NAME:
18. Reviewers		
NAME: COMMENTS	Dr. S. Pradhan	NAME: COMMENTS: