

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA/ BSR- 137

SECTION I: IDENTIFICATION 1. Name Present Nilakanthesvra Siva temple, Old Town, Bhubaneswar, Dist.- Khurda **Past** Other Name (if any): 2. Location 85⁰50'09" E 20⁰14'41" N LONGITUDE LATITUDE **ELEVATION** 56 ft **Address** Village (village code) Old Town Post: Old Town Via: Bhubaneswar **Tehsil:** Bhubaneswar **District**: Khurda State: Orissa **PIN:** 751002 **Approach** The temple is located on the western embankment of the Bindusagar tank. It is situated on the left side of the lane branching from the road leading from Kedar-Gouri chowk to Vaitala temple in Gyana nagar (Hadi Sahi) of old town, Bhubaneswar. 3. Property Type Other Structures Buildings Religious structures Palace Temple Wall Fort Mosque Gateway Minar Pillar Citadel Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: structures The present temple is a recent Bridge Public square construction over the remains of Tunnel Park or garden an earlier one. The building Other engineering structure Graveyard material is old but the entire Baolis, Well structure now has a cement Tank plaster and enamel paint. Cave

4. Property Use ABANDONED / IN USE: In Use It is a living temple and the presiding deity of the temple is a **Present** Sivalinga within a circular yonipitha. Past Worshipped 5. Age (Source) PERIOD Somavamsi rule **YEARS** 10th century A.D. Last guarter of the 10th century A.D. **Precise date of Construction** Completion Subsequent changes **Destruction / Demolition** 6. Ownership / Level of Protection SINGLE /MULTIPLE : Single **Public**: Archaeological Survey of: / State Archaeology Department / Any Other (Please specify) **Private** Jitu Mishra is the chief priest and custodian of the temple. Any other (Please specify) Name Address Mishra Sahi, Old Town, Bhubaneswar, Dist-Khurda, Orissa. **Phone** 7. Association WITH EVENTS In History In Rituals Sankranti and Sivaratri are observed here. In Building Construction The local people ascribe it to the Kesaris(Somavamsis). Sradha, Rudrabhiseka, Mangula, Marriage and Thread Any other (specify) ceremony etc are observed here. WITH PERSONS Patron **Chief Priest** Architect / Engineer Any other (specify) 8. Statement of Significance ✓ Architectural Architectural Archaeological

✓ Religious

Historical Religious

Any other (specify)	: On the basis of the iconographical features of the <i>parvadevatas</i> , the original temple can be dated to the 10 th century A.D.
	SECTION II: DESCRIPTION
9. Physical Description and D	ecorative Features
Context Urban / Rural Setting Surroundings	* Drawings (Attach extra sheet if necessary): No Urban setting
Carroanianigo	Stand in Isolation Complex Integral part of a Landscape / Street / Complex :
 Quantification 	
Area Dimension (L x B x H)	: 4.90 mtrs x 4.30 mtrs x 4.55 mtrs
Number of Blocks	(m / cm/ feet / inch) : Two
Number of Stories	:
Spatial Organization	
Orientation	: The temple is facing towards east.
Plan	: The <i>vimana</i> is square on plan and fronted by a shallow porch measuring 0.60 mtrs in length in front of the <i>vimana</i> in the eastern wall there is a concrete structure that serves as the <i>jagamohana</i> .
Allocation of Spaces	: 9.50 mtrs x 9.50 mtrs in length and width respectively.
ARCHITECTURAL STYLE Ornamentation	
Exteriors	: Plain except the <i>udyotasimhas</i> above the <i>raha pagas</i> of each wall.
Interiors	: plain
Movable Collections	: A Sivalinga within a circular <i>yonipitha</i> and four eroded sculptures are found which are not clearly identifiable.
* Any Other (specify)	: The <i>vimana</i> is <i>triratha on</i> plan and <i>trayangabada</i> in elevation.
10. Construction Technology	
Structural System Building Techniques Material of Construction	: Pidha vimana of impoverished Kalingan order.: Ashlars dry masonry with cement plaster.: Sandstone
11. Condition Assessment	
In General Good / Fair Sign of Deterioration Serious Deterioration Danger of Disappearance	: Good

The temple is in a good state of preservation.
12. Threats to the Property
 ✓ Natural Negligence Vandalism Urban Pressures x x x x x x x x x x x x x x x x x x x
SECTION III: REFERENCES
13. Reference Sources (published and unpublished textual details)
1. 2.
14. Photographs
(attach list as in page 6, in case of multiple photographs)
Photo Reference : CAPTION :
15. Audio / Video
(related to rituals / performance / festivals etc.)
Reference : DESCRIPTION :
16. Maps/Plans/Drawings
17. Listers
NAME: Ashis Ranjan Sahoo NAME:
18. Reviewers
NAME: Dr. S. Pradhan NAME: COMMENTS:

In Brief (Attach extra sheet if necessary):