

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi - 110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA / 14

1. Name	SECTION I: IDENTIFICATION
Present Past Other Name (if any): 2. Location	: Nrusinghanatha Temple, Jasuapur, Dist Khurda : :
LONGITUDE 85 ⁰ 53' 22" E	LATITUDE 20 ⁰ 13' 44" N ELEVATION 25 ft
Address	: Village (village code) Post: Bramhana Suanla Tehsil: Bhubaneswara State: Orissa Jasuapur Via: Balakati District: Khurda PIN: 752100
Approach	: The temple, on the left bank of the river Bhargavi is situated on the right side of the road leading from Balakati to Hansapal and at a distance of 2 kms from Umadei Brahmapura canal bridge and about 5 kms from Balakati.
3. Property Type	
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures ✓ Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum Other Structures Wall Gateway Pillar Others (specify)
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Cave Note: The temple has pidha vimana and jagamohana of impoverished Kalingan order.

4. Property Use	
	ABANDONED / IN USE: In use
Present	: It is a living temple that enshrines an image of Narasimha and Laxmi and their <i>Chalantipratima</i> .
Past	: Worshipped
5. Age (Source)	
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition	: British rule : 19 th century A.D. : : :
6. Ownership / Level of Protection	on
	SINGLE /MULTIPLE : Multiple
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	:
Private	: Under the care and maintenance of Maqadamas of Jasuapur.
Any other (Please specify) Name	Nilakantha Mohapatra, the chief priest of the temple.
Address	At-Jasuapur, PO-Bramhana Suanla, Dist-Khurda, Pin- 752100
Phone	:
7. Association	
WITH EVENTS In History In Rituals In Building Construction	:: Nrusimha janma, Radhastami, Janmastami and Rasa Purnima.
In Building Construction Any other (specify) • WITH PERSONS	: : Thread ceremony is only performed here.
Patron Architect / Engineer Any other (specify)	: Maqadama families of Jasupur.::
8. Statement of Significance	
Architectural Archaeological Historical Religious Any other (specify)	✓ Architectural ✓ Religious : On the basis of architectural and sculptural ground, the temple
	can be assigned to the 19 th century A.D.

SECTION II: DESCRIPTION

9. Physical Description and De	corative Features
Context Urban / Rural Setting Surroundings	* Drawings (Attach extra sheet if necessary): No Rural setting
Carroanianigo	Stand in Isolation Street Integral part of a Landscape / Street / Complex :
 Quantification 	
Area Dimension (LxBxH)	: 12.00 mtrs x 5.70 mtrs x 8.00 mtrs (approximate height) (m / cm/ feet / inch)
Number of Blocks	: Three
Number of Storys	:
Spatial Organization	
Orientation	: Facing towards east.
Plan	It consists of a square vimana and jagamohana having a ganthiala and a rectangular modern verandah in front of the temple.
Allocation of Spaces	
ARCHITECTURAL STYLE • Ornamentation	
Exteriors	The exterior of the temple is devoid of decorations, except the <i>pidhamundi</i> over the <i>raha</i> niches, <i>udyotasimha</i> in each <i>raha</i> , lion over the <i>beki</i> of the <i>jagamohana</i> , <i>garuda</i> and three other images over the <i>beki</i> of the <i>vimana</i> to support the <i>ghanta</i> .
Interiors Movable Collections	: Plain
Movable Collections	: <i>Gaja-vidala</i> , pedestal of an image, amorous couple and two-armed Hanumana.
* Any Other (specify)	: The <i>vimana</i> is <i>pancharatha</i> on plan and <i>panchangabada</i> in elevation.
10. Construction Technology	
Structural System	: Both the <i>vimana</i> and <i>jagamohana</i> are <i>pidha</i> order of
Building Techniques	impoverished <i>Kalingan</i> style. : Ashlar dry masonry.
Material of Construction	: Sandstone is used for the temple and laterite for the compound wall. The entire surface is plastered and white washed.
11. Condition Assessment	
In General	Good / Fair : Good
	Cian of Deterioration
	Sign of Deterioration Serious Deterioration

	[Danger of Disappearance
In Brief (Attac	n extra sheet if nec	essary)
Due to proper of	are and maintenanc	e, the temple is in a good state of preservation.
12. Threats to	the Property	
		✓ Natural Negligence Vandalism Urban Pressures
* * * * * * * *	* * * * * * * * * * *	******
	<u>SE</u>	CTION III: REFERENCES
13. Reference	Sources (published	and unpublished textual details)
14. Photograp	hs: 06 nos	(attach list as in page 6, in case of multiple photographs)
Photo Reference CAPTION	e :	
15. Audio / Vid	leo	
		(related to rituals / performance / festivals etc.)
Reference DESCRIPTION	: :	
16. Maps/Plans	s/Drawings	
17. Listers		
NAME :	Jaya Shankar Naik	NAME :
NAME : COMMENTS	Dr. S Pradhan	NAME : COMMENTS :