

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA / 24

SECTION I: IDENTIFICATION 1. Name Nrusinghanath Temple, Paribasudeipur, Dist.- Khurda Present Past Other Name (if any): 2. Location **LONGITUDE** 85⁰57'11"E 20⁰14'48"N LATITUDE **ELEVATION** 51 ft **Address** Village (village code) Paribasudeipur **Post**: Bhatapatana Via: Balianta **Tehsil:** Bhubaneswar District: Khurda State: Orissa **PIN:** 752101 Approach It is located on the left side of the road leading from Hansapal to Nimapada. It is about 12 kms from Hansapal chowk and on the left bank of Gop canal. 3. Property Type **Buildings** Religious structures Other Structures Palace **Temple** Wall Mosque Fort Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: structures Rekha and *pidha* vimana Bridge Public square jagamohana of impoverished Tunnel Park or garden Kalingan order. Other engineering structure Graveyard Baolis, Well Tank Cave

4. Property Use

ABANDONED / IN USE: In use

Present : It is a living temple and the presiding deities are

Narasimha and Varaha.

Past : Worshipped

5. Age (Source)

PERIOD : Ganga rule
YEARS : 14th century A.D.
Precise date of Construction : 14th century A.D.

Completion : --

Subsequent changes : Renovated by Orissa State Archaeology under X and

XI Finance Commission Award.

Destruction / Demolition : ---

6. Ownership / Level of Protection

SINGLE /MULTIPLE: Multiple

Public: Archaeological Survey of : Protected Monument of Orissa State Archaeology

India / State Archaeology Department / Any Other (Please

specify)

Private : --

Any other (Please specify) : The temple is looked after by the chief priest, Padma

Charan Panda.

Name : ---

Address : Orissa State Archaeology, Paryatan Bhawan, B.J.B.

Nagar, Bhubaneswar, Orissa

Phone : 0674-2432147

7. Association

• WITH EVENTS

In History : --

In Rituals : Janmasthami, Dola Purnima, etc are observed.

In Building Construction : --Any other (specify) : ---

WITH PERSONS

Patron: Now under the care of Orissa State Archaeology.

Architect / Engineer : ---

Any other (specify) : Padma Charan Panda, priest

8. Statement of Significance

| | Architectural | ✓ | Architectural |
|--|---------------------|--------------|---|
| | Archaeological | : | |
| | Historical | : | |
| | Religious | \checkmark | Religious |
| | Any other (specify) | | The architectural features such as the nilaster designs |

The architectural features such as the pilaster designs

and building material assign the temple to the late Ganga

period.

SECTION II: DESCRIPTION

| Context Urban / Rural Setting Surroundings | * Drawings (Attach extra : | sheet if necessary): No Rural setting |
|--|---|--|
| Ourroundings | Stand in Isolation Integral part of a Landscape / Street / Complex : | Stand in Isolation(within paddy fields) |
| • Quantification | | |
| Area Dimension (LxBxH) | : 12.70 mtrs x 07.20 mtrs x | (11.00 mtrs (m / cm/ feet / inch) |
| Number of Blocks Number of Storys | : Two (<i>vimana</i> and <i>jagamo</i> : | , |
| Spatial Organization Orientation Plan Allocation of Spaces | The temple is facing towaThe temple is square on30.00 mtrs x 15.00 mtrs i respectively. | plan |
| ARCHITECTURAL STYLE | | |
| Ornamentation | | |
| Exteriors | conjunction of the p gajavidalas and nayikas | d with pilaster designs and the projections are housed with like Sukasarika, Padmagandha. es are in a dilapidated and in |
| Interiors | : Plain | |
| Movable Collections | : An image of Trivikrama broken images are found | a in the <i>jagamohana</i> and few |
| * Any Other (specify) | | ha on plan and panchangabada |
| 10. Construction Technology | | |
| Structural System Building Techniques Material of Construction | : Ashlar masonry.: Laterite is used for the the presiding deities a | construction of the temple. But are made of chlorite and the conjunctions are made of sand |
| 11. Condition Assessment | | |
| In General | Good / Fair : Fair | |
| | ✓ Sign of Deterioration Serious Deterioration Danger of Disappearar | nce |

In Brief (Attach extra sheet if necessary):

The temple is recently renovated by the Orissa State Archaeology, even though the temple faces several problems like water seepage during the rainy season and growth of vegetation. Due to its low elevation the temple faces water logging problem during rainy season. And most sculptures are in a dilapidated condition, feared to be obliterated in course of time.

| 12. Threats to the Property | | | | | | |
|---|-----------------------------|--|--|--|--|--|
| x | | ✓ Natural ✓ Negligence Vandalism Urban Pressures x x x x x x x x x x x x x x x x x x x | | | | |
| | _ | SECTION III: REFERENCES | | | | |
| 13. Reference Sources (published and unpublished textual details) | | | | | | |
| 1. R. P. Moh | napatra, 1986, <i>Arc</i> i | haeology in Orissa, Vol I, New Delhi. | | | | |
| 14. Photograp | ohs | | | | | |
| <u> </u> | | (attach list as in page 6, in case of multiple photographs) | | | | |
| Photo Referen CAPTION 15. Audio / Vi | | | | | | |
| | | (related to rituals / performance / festivals etc.) | | | | |
| Reference DESCRIPTION 16. Maps/Plar | | : : | | | | |
| 17. Listers | | | | | | |
| 17. 213(013 | | | | | | |
| NAME : | D.B. Garnayak | NAME : | | | | |
| 18.Reviewers | | | | | | |
| NAME : COMMENTS | Dr. S. Pradhan | NAME : COMMENTS : | | | | |