

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, <u>www.ignca.gov.in</u>

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA/ BSR- 64

1. Name	SECTION I: IDENTIFICATIO	N
Present Past Other Name (if any): 2. Location	: Paradaresvara Siva T DistKhurda : :	emple,Old Town, Bhubaneswar,
LONGITUDE 85 ⁰ 49'96" E	LATITUDE 20 ⁰ 14'71" N	ELEVATION 67 ft
Address	: Village (village code) Post : Old Town Tehsil: Bhubaneswar State : Orissa	Gosagaresvara temple precinct, Old Town Via: Bhubaneswar District: Khurda PIN: 751002
Approach 3. Property Type	: The temple, in the precinct of Gosagaresvara temple, is located on the left side of the Ratha Road leading from Mausima chowk to Badheibanka chowk. It is located at a distance 200 mtrs west of Vaitala temple.	
Buildings	Religious structures	Other Structures
Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Wall Gateway Pillar Others (specify)
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Cave	Note: It has a <i>rekha vimana</i> and fronted by a porch of <i>Kalingan</i> order. The temple is dated to the 13 th century A.D on the basis of its architectural features, building materials and iconographical features of the sculpture.

4. Property Use

ABANDONED / IN USE: In use

Present : It is a living temple and the enshrining deity is only a

circular Yonipitha in the cella where the Lingam is

missing.

Past : Worshipped.

5. Age (Source)

PERIOD : Ganga rule **YEARS** : 13th century A.D.

Precise date of Construction: Last quarter of the 13th century A.D.

Completion : --

Subsequent changes : The temple was repaired and renovated by Orissa

State Archaeology under the X and XI Finance

Commission Award.

Destruction / Demolition : ---

6. Ownership / Level of Protection

SINGLE /MULTIPLE : Multiple

Lingaraja Temple Administration

Public: Archaeological Survey of : India / State Archaeology

Department / Any Other (Please

specify)
Private

Any other (Please specify) : The temple is looked after by Mahendra Garabadu

and Bhaga Garabadu as special caretaker of the

temple complex.

Name :

Address : Gosagaresvara chowk, Old Town, Bhubaneswar.

Phone : ---

7. Association

WITH EVENTS

In History : ---

In Rituals : Sivaratri, Kartikapurnima etc. observed here.

In Building Construction : --

Any other (specify) : Lord Lingaraja visits this temple once a year. Marriage,

thread ceremony and public meetings are also

practiced here.

WITH PERSONS

Patron : Originally, the Gangas but now the temple is looked

after by the chief priests Mahendra Garabadu and

Bhaga Gharabadu.

Architect / Engineer : ---

Any other (specify) : Lingaraja Temple Administration

8. Statement of Significance

Architectural Archaeological
Historical Architectural

Religious

Religious

Any other (specify) : On the basis of architectural features, the temple can be

dated to the 13th century AD.

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

Context
 Urban / Rural Setting

Surroundings

* **Drawings (**Attach extra sheet if necessary) : No

Urban setting

Stand in Isolation

Integral part of a Landscape

/ Street / Complex :

Quantification

Area Dimension (L x B x H) : 6.35 mtrs x 4.55mtrs x 9.00mtrs

(m / cm/ feet / inch)

Complex

Number of Blocks : One Number of Stories : ---

Spatial Organization

Orientation : The *vimana* is facing towards east.

Plan : The *sanctum* is square on plan measuring 3.00 square

mtrs and a frontal porch.

Allocation of Spaces : 50.40mtrs X 52.60mtrs in length and width respectively.

ARCHITECTURAL STYLE

Ornamentation

Exteriors : The exterior of the temple is decorated with *talagarbhika*

and *urdhagarbhika* on the *parsvadevata* niches, a series of miniature *rekha* deulas surmounted by *udyotasimhas* in each *paga* at the base of the *gandi* above the

varanda.

Interiors : Plain Movable Collections : ----

* Any Other (specify) : The temple is pancharatha on plan and panchanga bada

in elevation. The doorjambs are carved with three vertical bands and at the *lalatabimba* there is a

Gajaluxmi sitted in lalitasana.

10. Construction Technology

Structural System : The *vimana* is a *rekha* temple of *Kalingan* order.

Building Techniques : Ashlar dry masonry.

Material of Construction : Laterite

11. Condition Assessment
In General Good / Fair : Fair Sign of Deterioration ✓ Serious Deterioration Danger of Disappearance
In Brief (Attach extra sheet if necessary):
It is not in good state of preservation as rain water percolates into the sanctum through the cracks in the roof and <i>gandi</i> junctions.
12. Threats to the Property
✓ Natural ✓ Negligence Vandalism Urban Pressures XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX
SECTION III: REFERENCES
13. Reference Sources (published and unpublished textual details)
1. 2.
14. Photographs
(attach list as in page 6, in case of multiple photographs)
Photo Reference : CAPTION :
15. Audio / Video
(related to rituals / performance / festivals etc
Reference : DESCRIPTION :
16. Maps/Plans/Drawings
17. Listers
NAME: Ashis Ranjan Sahoo. NAME:
18. Reviewers
NAME: Dr. S. Pradhan NAME: COMMENTS: