

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA/ BSR- 145

SECTION I : IDENTIFICATION					
1. Name					
Present Past Other Name (if any): 2. Location	: Rajarani Temple, Bhubane: : :	swar, Dist Khurda			
LONGITUDE 85 ⁰ 50' 75" E	LATITUDE 20 ⁰ 15' 67" N	N ELEVATION 42 ft			
Address	Post : B.J.B. Nagar V Tehsil: Bhubaneswar D	Old Town /ia: Bhubaneswar District: Khurda PIN: 751014			
Approach		on the right side of the ng from N.H - 203 at Ravi			
3. Property Type					
Buildings Palace Fort Citadel Govt. building Railway station Defense building Industrial building Other public building Residential building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify)			
Engineering structure Bridge Tunnel Other engineering structure		has a <i>rekha vimana</i> and ha jagamohana of Kalingan			

4. Property Use

ABANDONED / IN USE: Abandoned

Present : Non living temple, the presiding deity is missing now.

Past : Not known

5. Age (Source)

PERIOD : Somavamsi rule
YEARS : 10th -11th centuries AD

Precise date of Construction : End of the 10th century AD or beginning of the 11th

centuries A.D.

Completion : ---

Subsequent changes : Repaired and conserved by Archaeological Survey of

India in 1903.

Destruction / Demolition : ---

6. Ownership / Level of Protection

SINGLE /MULTIPLE : Multiple

Public: Archaeological Survey of: Protected Monument of Archaeological Survey of

India / State Archaeology India.

Department / Any Other (Please

specify)

Private : --Any other (Please specify) : --Name : ---

Address : Archaeological Survey of India, Bhubaneswar Circle,

153, VIP Area, Navapali, Bhubaneswar, Orissa

Phone : 0674 - 2558170

7. Association

• WITH EVENTS

In History : --In Rituals : --In Building Construction : --Any other (specify) : ---

WITH PERSONS

Patron : Now the Archaeological Survey of India

Architect / Engineer : --Any other (specify) : ---

8. Statement of Significance

Architectural	\checkmark	Architectural
Archaeological		

Historical :

Any other (specify) : On the basis of architectural and sculptural embellishments,

the temple can be dated to the Somavamsi rule i.e end of the 10^{th} century A.D. or the beginning of the 11^{th}

century A.D.

SECTION II: DESCRIPTION

9. Physical Description and Dec	orat	ive Features	
 Context Urban / Rural Setting Surroundings 	:	* Drawings (Attach extra sheet	if necessary) : No Urban setting
Surroundings		Stand in Isolation Integral part of a Landscape / Street / Complex :	Stand in isolation
 Quantification 			
Area Dimension (L x B x H)	:	20.47 mtrs x 11.05 mtrs x17.98	
Number of Blocks		Two	(m / cm/ feet / inch)
Number of Storys	:		
Spatial Organization			
Orientation	:	Facing towards east.	
Plan	:	The temple consists of a rect jagamohana enclosed by an irre	
Allocation of Spaces	:	26.80 mtrs (L) x 23.05 mtrs (B)	galar compound wall.
• Ornamentation			
Interiors	:	The temple is decorated with a as <i>kumbha stamba, vajramastal</i> scroll work, <i>chaitya</i> motif, jali like - elephants, lion; divinities s Ardhanarisvara, Lakulisa, Hari-ldivinities like Vidyadharas, <i>bhar mithuna</i> figures.	ka; decorative motif like pattern, <i>vidala</i> , animal such as Surya, Nataraj, Hara, Parvati and semi-
Movable Collections * Any Other (specify)	:	The temple has <i>triangabada</i> in jagamohana a miniature <i>rekha</i> of the four sides are added white by the <i>panchayatana</i> plan.	temple at each corner
10. Construction Technology			
Structural System	:	The <i>vimana</i> is a <i>khakhara</i> temp is a flat roofed temple of the ear	
Building Techniques	:	Ashlar dry masonry	ly of Kamigan order.
Material of Construction	:	Sandstone is used for the con and laterite for the compound w	
11. Condition Assessment			
In General Good / Fair Sign of Deterioration Serious Deterioration Danger of Disappearance	:	Good	

In Brief (Attach extra sheet if necessary):

Water stores in the temple complex during rainy season as there is no out let facilities. Large and high-storied buildings have been unsafely allowed to be constructed by the authorities, very close to the walls of this famous temple which is known for its excellent architectural beauty.

12. Threats to	the Property	
	✓ 	Natural Negligence Vandalism Urban Pressures
x x x x x x x		x x x x x x x x x x x x x x x x x x x
	SEC ⁻	TION III: REFERENCES
13. Reference	e Sources (published ar	nd unpublished textual details)
 Debala M T.E. Dona 	litra, 1958, <i>Bhubaneswa</i> aldson, 1987, <i>Hindu ten</i>	logy in Orissa, Vol I, New Delhi. ar, New Delhi. aple Art of Orissa, Vol I, Leiden. rissa District Gazetteers, Puri, Cuttack.
14. Photograp	ohs: 119	
		(attach list as in page 6, in case of multiple photographs)
Photo Refere CAPTION	nce :	
15. Audio / Vi	deo	
		(related to rituals / performance / festivals etc.)
Reference DESCRIPTIO	N :	
16. Maps/Plar	ns/Drawings	
17. Listers		
NAME:	Jaya Shankar Naik	NAME:
18. Reviewers	S	
NAME :	Dr. S. Pradhan	NAME: