INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, <u>www.ignca.gov.in</u>

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA/ BSR- 148

1. Name	SECTION I : IDENTIFICATION
Present Past Other Name (if any): 2. Location	: Sari Temple, Bhubaneswar, Dist Khurda : :
LONGITUDE 85 ⁰ 50' 04" E	LATITUDE 20 ⁰ 14' 35" N ELEVATION 68 ft
Address	: Village (village code) Post : Old Town Tehsil: Bhubaneswar State : Orissa Old Town Via: Bhubaneswar District: Khurda PIN: 751002
Approach	: The temple is situated on the right side of the road branching from Ratha road to Bindusagar, on the southern embankment of the Bindusagar.
3. Property Type	
BuildingsPalaceFortCitadelGovt. buildingRailway stationDefense buildingIndustrial buildingOther public buildingsResidential building	Religious structures Other Structures Y Temple wall Mosque Gateway Minar Pillar Church Others (specify) Monastery Stupa Tomb, Mausoleum Tomb, Mausoleum
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structuresNote: It is a rekha temple and pidha jagamohan of Kalingan order.Public square Park or gardenIt is a rekha temple and pidha jagamohan of Kalingan order.Graveyard Baolis, Well Tank CaveCave

4. Pro	operty	Use
--------	--------	-----

		ABANDONED / IN USE : Abandoned		
Present Past	:	Non-living temple Worshipped, the sculptural embellishment suggests it to be Saivite temple dedicate to lord Siva.		
5. Age (Source)				
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition		Ganga period 13 th century A.D. 		
6. Ownership / Level of Protection	on			
		SINGLE /MULTIPLE : Multiple		
Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	:	Protected Monument of Archaeological Survey of India.		
Private	:	Lingaraja Temple Management Trust.		
Any other (Please specify)	:			
Name Address	÷	 Archaeological Survey of India, Phyloneswar Circle		
Address	•	Archaeological Survey of India, Bhubaneswar Circle, 153, VIP Area, Nayapalli, Bhubaneswar, Orissa		
Phone	:	0674-2558170		
7. Association				
WITH EVENTS				
In History	:			
In Rituals	:			
In Building Construction	:			
Any other (specify) WITH PERSONS 	•			
Patron	:	Lingaraja Temple Management Trust		
Architect / Engineer	:			
Any other (specify)	:	A. S. I, Bhubaneswar circle		
8. Statement of Significance				
Architectural	\checkmark	Architectural		
Archaeological	:			
Historical	: ✓	Paligious		
Religious	· ·	Religious		
Any other (specify)	•	On the basis of architectural features & sculptural embellishments, the temple can be assigned to circa 13 th century A.D.		

SECTION II: DESCRIPTION

Context Urban / Rural Setting Surroundings	:	* Drawings (Attach extra sheet if necessary) : No Urban setting	
		Stand in Isolation Integral part of a Landscape / Street / Complex :	Complex
Quantification Area Dimension (L x B x H)	:	17.50 mtrs x 10.00 mtrs x19.20 mtrs	(m / cm/ feet / incl
Number of Blocks Number of Storys	:	: Two :	
Spatial Organization Orientation Plan Allocation of Spaces	:	Facing towards west. The temple consists of a square <i>vimana</i> and a <i>jagamohana</i> 17.70 mtrs (L) x 13.85 mtrs (B)	
ARCHITECTURAL STYLE			
Ornamentation Exteriors	:	Decorated with architectural motifs like <i>khakharamundi</i> , <i>pidhamundi</i> , <i>naga-nagi stambha</i> ; decoravative motifs like scroll work, meandering creepers, flowers, <i>chaitya</i> motifs mythological animals like <i>gaja-kranta</i> , <i>virala</i> ; animals like elephants, lions, etc; divinities like <i>Dikpalas</i> and their counter parts, Parvati, Gopinatha, Mahayogi, secular motifs like warriors, royal figures, <i>risi</i> , <i>alasakanyas</i> and erotics like <i>mithuna</i> and <i>maithuna</i> figures.	
Interiors Movable Collections * Any Other (specify)	:	 Plain Nil Both the <i>vimana</i> and <i>jagamohana</i> are <i>panchangabada</i> elevation. The <i>vimana</i> is <i>saptaratha</i> on plan while the <i>jagamohana</i> is <i>navaratha</i> on plan. Now the crowning elements above the <i>amlaka</i> are missing. 	
10. Construction Technology			
Structural System Building Techniques Material of Construction	:	 Rekha vimana and a pyramidal jagamohana of matu phase of Kalingan order. Ashlar dry masonry. Soft sandstone is used for the temple construction a laterite for the compound wall. 	
11. Condition Assessment			
In General Good / Fair	:	Fair	
Sign of Deterioration Serious Deterioration Danger of Disappearance			

In Brief (Attach extra sheet if necessary):

The temple is abandoned. Some locals used the temple as a store room for keeping earthen pots; leafplates etc. and use the temple's soft sand stones as building material. Most of the delicate carvings are lost due to exfoliation and breakage.

12. Threats to the Property

\checkmark	Natural
✓	Negligence
✓	Vandalism
\checkmark	Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

- 1. Debala Mitra, 1958, *Bhubaneswar*, New Delhi.
- 2. T. E. Doraldson, 1986, *Hindu temple Art of Orissa*, Vol. II, Leiden.
- 3. Nilamani Senapati (ed), 1977, Orissa District Gazetteers, Puri, Cuttack.
- 4. R. P. Mohapatra, 1986, Archaeology in Orissa, Vol.- I, New Delhi.

14. Photographs: 28 nos

		(attach list as in page 6, in case of multiple photographs)
Photo Reference	:	
CAPTION	:	
15. Audio / Video		
		(related to rituals / performance / festivals etc.)
Reference	:	
DESCRIPTION	:	
16. Maps/Plans/Drawings		

17. Listers

NAME : 18. Reviewers	Jaya Shankar Naik	NAME :	
NAME : COMMENTS		NAME : COMMENTS :	