

## **INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS**

Janpath, New Delhi -110 001, <a href="www.ignca.gov.in">www.ignca.gov.in</a>
Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA/ BSR- 151

1. Name	SECTION I: IDENTIFICATION
Present Past Other Name (if any): 2. Location	<ul><li>Satyanarayana Temple, Bhubaneswar, DistKhurda</li><li></li><li></li></ul>
LONGITUDE 85° 50' 04" E Address	LATITUDE 20 <sup>0</sup> 14' 44" N ELEVATION 60 ft : Village (village code) Post: Old Town Tehsil: Bhubaneswar. State: Orissa  PIN: 751002
Approach	: Located on the left side of the road leading from Lingaraj to Bindusagar.
3. Property Type	
Buildings  Palace Fort Citadel Govt. building Railway station Defense building Industrial building Other public building Residential building	Religious structures Temple wall Mosque Gateway Minar Pillar Church Others (specify) Monastery Stupa Tomb, Mausoleum
Engineering structure  Bridge Tunnel Other engineering structure	Open space and related structures  Public square Park or garden Graveyard Baolis, Well Tank Cave  Note: Rekha vimana and pidha jagamohana of Kalingan order.

4. Property Use		
		ABANDONED / IN USE: In use
Present Past	:	Living temple, enshrined deity is Visnu. Worshipped.
5. Age (Source)		
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition	: : : : : : : : : : : : : : : : : : : :	Late Ganga Period 14 <sup>th</sup> century AD
6. Ownership / Level of Protection	on	
		SINGLE /MULTIPLE : Multiple
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	:	Protected Monument of Orissa State Archaeology.
Private Any other (Please specify) Name Address	: : : :	Bhabani Sankar Club Ashok Kumar Garabadu, the president of the Club  Orissa State Archaeology, Paryatan Bhawan, B.J.B. Nagar, Bhubaneswar, Orissa
Phone	:	0674 - 2432147
7. Association		
WITH EVENTS In History In Rituals In Building Construction Any other (specify)     WITH PERSONS Patron Architect / Engineer Any other (specify)	: : : : : : : : : : : : : : : : : : : :	Ramanavami, Janmastami, etc observed here Now it is looked after by the Orissa State Archaeology
8. Statement of Significance		

Architectural	✓	Architectural

Archaeological Historical Religious Religious

Any other (specify)

The architectural design like plain pilasters decoration and building materials, assign the temple to the late Ganga period.

## **SECTION II: DESCRIPTION**

9. Physical Description and Decorative Features			
<ul> <li>Context</li> <li>Urban / Rural Setting</li> <li>Surroundings</li> </ul>		* <b>Drawings</b> (Attach extra sheet if necessary) : No Urban setting	
ourroundings		Stand in Isolation Integral part of a Landscape / Street / Complex :	Complex
<ul> <li>Quantification</li> <li>Area Dimension ( L x B x H)</li> </ul>	:	11.50 mtrs x 6.40 mtrs x 11.00 m	ntrs (approximately) ( <b>m</b> / cm/ feet / inch)
Number of Blocks Number of Storys	:		(III / GIII/ ICCE / IIIGII)
<ul> <li>Spatial Organization         Orientation         Plan         Allocation of Spaces     </li> </ul>	: :	The temple is facing towards eas The <i>vimana</i> and <i>jagamohana</i> are 22.60 mtrs (L) x 19.70 mtrs (W).	
• Ornamentation Exteriors  Interiors Movable Collections	:	The temple is devoid of any scu At the base of the <i>gandi</i> , angasik Plain Ganesa, Sculpture pieces and bu	thara are noticed.  ust part of few images.
* Any Other (specify)  10. Construction Technology	·	The <i>vimana</i> and the <i>jagamohan</i> plan and <i>panchangabada</i> in elev	
Structural System Building Techniques Material of Construction  11. Condition Assessment	: :	Rekha vimana and pidha jagamo Ashlar dry masonry. Laterite.	phana
In General Good / Fair	:	Fair	
<ul><li>✓ Sign of Deterioration</li><li>✓ Serious Deterioration</li><li>✓ Danger of Disappearance</li></ul>			
In Brief (Attach extra sheet if necessary): The temple is buried up to the <i>patta (pabhaga)</i> moulding. Lichen growth over the exterior wall. Rain water seepage during the rainy season.			
12. Threats to the Property  Natural			

<b>✓</b>	Negligence
	Vandalism
<b>✓</b>	Urban Pressures

## 

## **SECTION III: REFERENCES**

	_				
13. Reference	Sources (publishe	l and unpublished textual details)			
14. Photograp	ohs				
<u> </u>		(attach list as in page 6, in case of multiple photograph	າຣ)		
Photo Refere CAPTION	nce	: :			
15. Audio / Vi	deo				
		(related to rituals / performance / festivals et	c.)		
Reference DESCRIPTION	N	: :			
16. Maps/Plans/Drawings					
17. Listers					
NAME:	D. B. Garnayak	NAME:			
18. Reviewers	18. Reviewers				
NAME: COMMENTS	Dr. S. Pradhan	NAME: COMMENTS:			