INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA / 04

1. Name	SECTION I : IDENTIFICATION	
Present Past Other Name (if any): 2. Location	: Siddhanath Temple, Bai : : Siddhesvara Temple	nchua, Dist Khurda
LONGITUDE 85 ⁰ 54' 11" E	LATITUDE 20 ⁰ 16'19" N	ELEVATION 44 ft
Address	: Village (village code): Post : Bainchua Tehsil: Bhubaneswar State : Orissa	Bainchua Via: Balakati District: Khurda PIN: 752100
Approach	 proach The temple, on the left bank of the river Bhargavi a on the north-eastern outskirt of the village Bainchua situated on the right side of Balakati-Hanspal Road. 	
3. Property Type		
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public buildings Residential building Bridge Tunnel Other engineering structure	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Cave	Other Structures Wall Gateway Pillar Others (specify): Note: It is a ruined Siva temple but the sculptural treasures kept in the temple premise, assign its original date to the Somavamsi rule i.e. the 10 th century A.D.

4. Property Use	
	ABANDONED / IN USE : In use
Present	: It is a ruined but living temple and the presiding deit a Sivalinga within a circular <i>yonipitha</i> made of bla chlorite. It is 0.55 mtrs bellow the door level.
Past	: Worshipped
5. Age (Source)	
PERIOD	: Somavamsi rule
YEARS	: 10 th century A.D.
Precise date of Construction	: Last quarter of the 10 th century A.D.
Completion	
Subsequent changes Destruction / Demolition	
	·
6. Ownership / Level of Protectic	SINGLE /MULTIPLE : Multiple
Public : Archaeological Survey of	·
India / State Archaeology Department / Any Other (Please specify)	
Private	:
Any other (Please specify)	: Village Temple Committee under the presidentship Dharanidhara Behera
Name	:
Address	: At/PO. – Bainchua, Dist Khurda, Orissa, Pin - 7521
Phone 7. Association	
WITH EVENTS	
In History	:
In Rituals	: Sivaratri, Kartika Purnima, Sankranit, etc performed here.
In Building Construction	· ···
Any other (specify) WITH PERSONS 	: Yajna is held here
• WITH PERSONS Patron	: Now under the care of village Temple Committee.
Architect / Engineer	
Any other (specify)	:
8. Statement of Significance	
Architectural	: Archaeological
Archaeological Historical	: Archaeological
Religious	:
Any other (specify)	: The temple is in ruined condition and plastered up to
	<i>bada</i> portion. On the basis of the sculptu embellishments kept in the temple premise, its origi date can be assigned to the Somavamsis period the last quarter of the 10 th century AD.

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features				
 Context Urban / Rural Setting Surroundings 	:	* Drawings (Attach extra sheet	if necessary) : No Rural setting	
		Stand in Isolation Integral part of a Landscape / Street / Complex :	Stand in Isolation	
• Quantification Area Dimension (L x B x H) Number of Blocks	:	3.56 mtrs x 3.36 mtrs x 1.58 mtrs One	(existing height) (m / cm/ feet / inch)	
Number of Storys	:	N.A.		
• Spatial Organization Orientation Plan Allocation of Spaces		The temple is facing towards eas The <i>vimana</i> is square on plan. 30.00 mtrs x 20.00 mtrs in length respectively.		
ARCHITECTURAL STYLE • Ornamentation Exteriors Interiors Movable Collections * Any Other (specify)	:	Devoid of decorations Plain Four-armed Parvati, four-armed Kartikeya, Mahisasuramardini Bhairava, <i>udyotasimha</i> (2 nos) architectural fragments etc.	Durga, two-armed	
10. Construction Technology				
Structural System Building Techniques Material of Construction	:	As the temple is existing only up is difficult to assess the order of t English bond technique Bricks are used for the structure.		
11. Condition Assessment				
In GeneralGood / FairSign of Deterioration✓✓Serious DeteriorationDanger of DisappearanceIn Brief (Attach extra sheet if nec	: ces:	sary):		

The sculptures are scattered in the temple premise and they should be kept under a shade.

12. Threats to the Property

Natural

1	Negligence
	Vandalism
	Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

- 1. B.K. Rath (ed.) 1996, *The Forgotten Monuments of Orissa*, Vol. 3, Delhi.
- 2. R. P. Mohapatra, 1986, Archaeology in Orissa, Vol. I, Delhi.

14. Photogra	ohs: 05 nos			
		(attach list as in page 6, in case of multiple photographs)		
Photo Refere CAPTION	nce :			
15. Audio / Vi	deo			
		(related to rituals / performance / festivals etc.)		
Reference DESCRIPTIO	N :			
16. Maps/Plans/Drawings				
17. Listers				
NAME :	Jaya Shankar Naik	NAME :		
18. Reviewers				
NAME : COMMENTS	Dr.S. Pradhan	NAME : COMMENTS :		