

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA / 30

	SECTION I : IDENTIFICATION	
1. Name		
Present Past Other Name (if any):	: Sri Gopalji Jew Temple, Dist Khurda : :	Rathijhima Patna,
2. Location		
LONGITUDE 85 ⁰ 52' 14" E	LATITUDE 20 ⁰ 12' 43" N	ELEVATION 60 ft
Address	: Village (village code): Post : Balakati Tehsil: Bhubaneswar State : Orissa	Rathijima Patna (Tirishighara Sahi) Via: Balakati District: Khurda PIN: 752100
Approach	situated on the right s	t bank of the river Bhargavi is side of the road leading from nd is about 3.5 kms from Uttara -Pipili Road.
3. Property Type		
Buildings Palace Fort Citadel Govt. building Railway station Defence building	Religious structures ✓ Temple Mosque Minar Church Monastery Stupa	Other Structures Wall Gateway Pillar Others (specify):
Industrial building Other public buildings Residential building	Tomb, Mausoleum	Note:
Engineering structure	<i>Open space and related structures</i> Public square	The temple has a <i>pidha vimana</i> and <i>jagamohana</i> of impoverished <i>Kalingan</i> order.
Tunnel Other engineering structure	Park or garden Graveyard Baolis, Well Tank Cave	

4. Property Use		
		ABANDONED / IN USE : In use
Present	:	It is a living temple and the presiding deities are stone image of Krisna, brass images of Radha, Lax
Past	:	Narasimha, and lord Jagannath, made of <i>neem</i> wood Worshipped.
5. Age (Source)	•	
PERIOD	:	Bhoi rule of Khurda
YEARS Precise date of Construction	÷	18 th century A.D. 18 th century A.D.
Completion		
Subsequent changes	:	Recently a R.C.C. mandapa is added in front of
	•	temple.
Destruction / Demolition	:	·
6. Ownership / Level of Protecti	on	
		SINGLE /MULTIPLE : Multiple
Public : Archaeological Survey of		
India / State Archaeology		
Department / Any Other (Please		
specify) Private		
Any other (Please specify)	:	Village Committee under the presidentship of Dibaka
	•	Sahoo.
Name	:	
Address	:	At - Rathijima Patna, PO Balakati, Dist Khurda, P
		752100, Orissa.
Phone	:	
7. Association		
WITH EVENTS	_	
In History In Rituals	-	 Janmastami. Radhastami. Chandana Yatra. D
	•	Purnima, Rasa Purnima, Astaprahari, etc are held he
In Building Construction	:	Local people ascribed the temple to Chaitanya,
-		great saint of vaisnavite movement.
Any other (specify)	:	Only engagement is performed here.
WITH PERSONS		
Patron	:	Presently under the village committee.
Architect / Engineer Any other (specify)	÷	
• • • • •	•	
8. Statement of Significance		
Architectural	✓	Architectural
Archaeological Historical	•	
Religious	✓	Religious
Any other (specify)		On architectural & sculptural grounds, the temple can
		assigned to the 18 th century A.D.

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features				
Context Urban / Rural Setting Surroundings	:	* Drawings (Attach extra sheet if necessary) : No Rural setting		
		Stand in IsolationStreetIntegral part of a Landscape/ Street / Complex :		
Quantification				
Area Dimension (L x B x H)	:	7.45 mtrs x 4.28 mtrs x 6.45 mtrs (approximate height) (m / cm/ feet / inch)		
Number of Blocks	:	Thee		
Number of Storys	:	N.A.		
Spatial Organization				
Orientation	:	The temple is facing towards east.		
Plan	:	The vimana and jagamohana are square on plan and		
Allocation of Spaces	:	the RCC <i>mandapa</i> in front is rectangular. 35.00 mtrs x 25.00 mtrs in length and breadth respectively.		
ARCHITECTURAL STYLE • Ornamentation				
Exteriors	:	Devoid of decorations, except the <i>dopichhasimhas</i> and <i>deulacharinis</i> over the <i>beki</i> and the <i>parsvadevata</i> niches surmounted by <i>pidhamundi</i> design.		
Interiors	:	Plain		
Movable Collections	:	Erotic figure & <i>udyotasimha</i> found in the temple premise.		
* Any Other (specify)	:	Both the components – <i>vimana</i> and <i>jagamohana</i> are <i>panchangabada</i> in elevation.		
10. Construction Technology				
Structural System	:	Both vimana and jagamohana are of pidha order of impoverished Kalingan order.		
Building Techniques	:	Ashlar masonry.		
Material of Construction	:	Laterite is used for structure, foundation and the compound wall. Now the entire temple is plastered lime and white washed.		
11. Condition Assessment				
In GeneralGood / FairSign of DeteriorationSerious DeteriorationDanger of Disappearance	:	Good		

In Brief (Attach extra sheet if necessary):

It is in a good state of preservation, except growth of vegetation in the temple premise.

12. Threats to the Property

Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

1. B.K. Rath (ed.), 1996, *The Forgotten Monuments of Orissa*, Vol. -3, Delhi.

14. Photographs: 06 nos

		(attach list as in page 6, in case of multiple photographs)
Photo Refere CAPTION	nce	
15. Audio / Vi	ideo	
		(related to rituals / performance / festivals etc.)
Reference DESCRIPTIO 16. Maps/Pla		
17. Listers		
NAME :	Jaya Shankar Naik	NAME :
18. Reviewer	S	
NAME : COMMENTS	Dr. S. Pradhan	NAME : COMMENTS :