

INDIRA GANDHI NATIONAL CENTRE sisFOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA/ BSR- 164

1. Name	SECTION I: IDENTIFICATION
Present Past Other Name (if any):	: Tirthesvara Siva Temple, Bhubaneswar, DistKhurda : :
LONGITUDE 85 ⁰ 50'10"E	LATITUDE 20 ⁰ 14'36"N ELEVATION 85 ft
Address	: Village (village code) Talabazar Post : Old Town Via: Bhubaneswar Tehsil: Bhubaneswar State : Orissa PIN: 751002
Approach	: It is located on the left side of the road leading from Bindusagar to Lingaraj temple.
3. Property Type	
Buildings Palace Fort Citadel Govt. building Railway station Defense building Industrial building Other public building Residential building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum Other Structures Wall Gateway Pillar Others (specify) Others (specify)
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Public square park or garden Graveyard Baolis, Well Tank Cave Note: It has a rekha vimana and pidha jagamohana of Kalingan order.

4. Property Use		
		ABANDONED / IN USE: In use
Present	:	Living temple, the presiding deity is a Sivalinga within a circular <i>yonipitha</i>
Past	:	Worshipped
5. Age (Source)		
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition	: : : : : : : : : : : : : : : : : : : :	Ganga rule 14 th century AD It was a renovated later on.
6. Ownership / Level of Protection	on	
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) Private	:	SINGLE /MULTIPLE: Multiple
Any other (Please specify) Name Address Phone	: : : : :	It is looked after by Talabazar Temple Committee Talabazar, Old Town, Bhubaneswara
7. Association		
WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron Architect / Engineer	: : : : : : : : : : : : : : : : : : : :	Chaturdasi, Dahanchori, Sivaratri etc. are observed. Originally, the Gangas but now the Talabazar Temple Committee
Architect / Engineer Any other (specify)	:	
8. Statement of Significance		
Architectural Archaeological Historical Religious Any other (specify)	✓ : : ✓	Architectural Religious On the basis of architectural features, the temple can be

Religious
On the basis of architectural features, the temple can be dated to the 14th century A.D i.e last part of the Ganga rule.

SECTION II: DESCRIPTION

9. Physical Description and Decora	ative Features
Context Urban / Rural Setting Surroundings	* Drawings (Attach extra sheet if necessary): No Urban setting
Carroundings	Stand in Isolation Stand in Isolation Integral part of a Landscape / Street / Complex :
• Quantification Area Dimension (L x B x H) :	8.06 mtrs x 4.30 mtrs x 7.21 mtrs
Number of Blocks : Number of Storys :	Two
• Spatial Organization Orientation : Plan : Allocation of Spaces :	Facing towards west The <i>vimana</i> is square on plan while the <i>jagamohana</i> is rectangular. 8.06 mtrs (L)x 4.30 mtrs (B)
ARCHITECTURAL STYLE • Ornamentation Exteriors : Interiors : Movable Collections : * Any Other (specify) :	Plain, the temple has given a cement plaster with ochre colour red wash. Plain Nil The <i>vimana</i> is <i>pancharatha</i> on plan & <i>panchangabada</i> in elevation but the <i>jagamohana</i> has <i>triangabada</i> .
10. Construction Technology	
Structural System : Building Techniques : Material of Construction :	The <i>vimana</i> is a <i>rekha</i> temple and the <i>jagamohana</i> is a <i>pidha</i> temple of <i>Kalingan</i> order. Ashlar dry masonry Sandstone is used for the temple and laterite for the foundation.
11. Condition Assessment	
In General Good / Fair :	Fair
✓ Sign of Deterioration Serious Deterioration Danger of Disappearance In Brief (Attach extra sheet if neces	ssary):
The temple is now buried up to the i	angha portion and the rain water seepage into the temple

The temple is now buried up to the *jangha* portion and the rain water seepage into the temple during rainy season.

12. Threats t	o the Property	
		Natural
	_	Negligence Vandalism
	<u>.</u>	✓ Urban Pressures
	_	
x	x	x x x x x x x x x x x x x x x x x x x
	SEC	CTION III: REFERENCES
13. Referenc	e Sources (published a	and unpublished textual details)
1. T. E. Dol	adson, 1986, <i>Hindu Te</i>	emple Art of Orissa, VolII, Leiden.
14 Photogra	nhe: 10 nos	
14. Photogra	ษแร. เบ แบร	(attach list as in page 6, in case of multiple photograph
Photo Refere	ence	
CAPTION		· :
4 - 4 11 /3/		
15. Audio / V	Ideo	(related to rituals / performance / festivals etc
Deference		
Reference DESCRIPTIO	N	
16. Maps/Pla	ns/Drawings	
17. Listers		
NAME:	D.B Garnayak	NAME:
18. Reviewer	'S	
NAME :	Dr. S. Pradhan	NAME:
COMMENTS		COMMENTS: